Watershed Protection Department
Pond Inspection Form

Pond Asset Number:	1204644	Pond, R, R00144, 7201 John Blocker			
Drainage ID:	352480				
Address:	7201 JOHN BLOCKER DR AUSTIN TX 78749				
Pond Owner:				**Pond Owner ID:**	0
Business Name:					
Location Description:					
Pond Type:	SEDIMENTATION/SAND_FILTRATION				
Location:	1210746	**Water Reg Area:**	BSZ	**Recharge Zone:**	SOUTH
Map Page:	642B	**Map Grid:**	C18	**Field Ops Zone:**	3
Case #:	C8-85-156.02.2(87)	**Property ID:**	314982	**Parcel #:**	
Resp Maint:	COA_WPD	**Inspection:**	COA_WPD	**Partial or Full:**	PARTIAL
DU Discount:		**Pond Status:**	ACTIVE	**Op. Permit #:**	
Document:	C8-85-156.02.2(87)	**# of Ponds at Site:**		**Berm Height:**	
Subdivision Name:	Legend Oaks Phase A Section 3A 3B				
Inspection Type:	COMPLIANCE	**Inspected By:**	WESTBROOKM	**Inspection Date:**	05/22/2014
Work Order Number:	14-1727				
Pond Comments:	Property Owned by HOA Lot 45 Blk D				

Two choices: 0 is compliant and 9 is a violation

Problem Area

Sediment Build-up:	7	Structural Integrity/Soil Erosion:	0
Standing Water:	0	Riser Pipe/Trash Rack:	0
Inlet Blocked:	0	Outlet Blocked:	0
Excessive Trash:	0	Excessive Vegetation Growth:	0
Access Difficulties:	0	Work or Letter Warranted:	Y

Inspection Comments:

3, CLEANING, R00144, Sediment removal

1. Remove sediment from sedimentation basin

Pond shall be restored to all design specifications as per approved plans or until in compliance with City code.

NO
TRESPASSING
05/22/2014 11:53

05/22/2014 11:55

05/22/2014 11:56

05/22/2014 11:56

05/22/2014 11:57

05/22/2014 11:58

11/20/2014 11:36

11/20/2014 11:36

11/20/2014 11:36

11/20/2014 11:37