Watershed Protection Department
Pond Inspection Form

Pond Asset Number:	1206779	Pond, R, R00136, 7910 Beckett			
Drainage ID:	352417				
Address:					
Pond Owner:				**Pond Owner ID:**	0
Business Name:					
Location Description:	@ Ganttcrest				
Pond Type:	SEDIMENTATION/SAND_FILTRATION				
Location:	1211586	**Water Reg Area:**	BSZ	**Recharge Zone:**	SERZ
Map Page:	642F	**Map Grid:**	C18	**Field Ops Zone:**	3
Case #:	C8-84-58.1	**Property ID:**		**Parcel #:**	
Resp Maint:	COA_WPD	**Inspection:**	COA_WPD	**Partial or Full:**	FULL
DU Discount:		**Pond Status:**	ACTIVE	**Op. Permit #:**	
Document:	C8-84-58.1	**# of Ponds at Site:**		**Berm Height:**	
Subdivision Name:	Village at Western Oaks Section 11				
Inspection Type:	COMPLIANCE	**Inspected By:**	WESTBROOKM	**Inspection Date:**	05/21/2014
Work Order Number:	14-1717				
Pond Comments:					

Two choices: 0 is compliant and 9 is a violation

Problem Area

Sediment Build-up:	7	Structural Integrity/Soil Erosion:	0
Standing Water:	0	Riser Pipe/Trash Rack:	9
Inlet Blocked:	0	Outlet Blocked:	0
Excessive Trash:	0	Excessive Vegetation Growth:	0
Access Difficulties:	0	Work or Letter Warranted:	Y

Inspection Comments:

3, NON-COMPLIANT, R00136, Riser pipe missing, replace cleanout cap, sediment buildup

1. Repair missing riser pipe and trash rack
2.Replace cleanout cap
3. Remove sediment buildup and regrade for drainage

Pond shall be restored to all design specifications as per approved plans or until in compliance with City code.

05/21/2014 10:07

05/21/2014 10:07

05/21/2014 10:09

05/21/2014 10:09

05/21/2014 10:11

05/21/2014 10:12

05/21/2014 10:13

05/21/2014 10:14

05/21/2014 10:15

05/21/2014 10:15

05/21/2014 10:16

11/19/2014 14:06

11/19/2014 14:06

11/19/2014 14:07

11/19/2014 14:09

11/19/2014 14:09

11/19/2014 14:09

11/19/2014 14:09

11/19/2014 14:10

11/19/2014 14:10

11/19/2014 14:11

11/19/2014 14:11

11/19/2014 14:11