Pdf. ✓ IC4S Copied TX526[illegible]

Water Quality Noncompliance Notification

X Unauthorized Discharge of Wastewater ____ Reportable Effluent Violation ____ Other

General Information

Entity Name: San Antonio Water System Telephone: 210-233-3274

X Permitte ____ Subscriber

TCEQ Region: 13 County: Bexar Permit Number 10137-008-Salado Creek

Noncompliance Summary

Description of Noncompliance (include location, discharge route, and estimated volume if an unauthorized discharge): The address of the spill was at 3800 Espada Falls (FERG 233B6) Approximately 84150 gallons spilled into Creek Bed - Spilled Into Rosillo Creek .

SR#: 1786674 ; INSPT#: 482213; WO#: ; Sewer Main 45341 47557

Cause of Noncompliance: Grease

Duration: Start 05/15/2017 11:40 (Date) (Time) End 05/15/2017 14:00 (Date) (Time)

Or expected to be Corrected ____ (Date)

Potential Dangers to Human Health and Safety or the Environment: No Significant Dangers There Are No Known Drinking Water Wells With ½ Mile Of The Spill.

Actions Taken

Monitoring Data: Data should be attached or submitted to TCEQ when available.

X	yes	____	no	Field Measurements
____	yes	X	no	Laboratory Samples
X	yes	____	no	Fish Kill, If yes, estimated number killed 45

Actions Taken to Mitigate Adverse Effects: Returned to System, Clean Up In Progress

Actions Taken to Correct the Problem and Prevent Recurrence: 8 Inch Sewer Main, Unstopped Main,

Verification Information

Information Reported By Christopher Luna / LC/TV III (Name) (Title)

Date Reported 5/15/2017 Signature: Juan C Ramirez Manager Service Center 5-18-17

TCEQ 0501 (November 5, 2002) If the noncompliance is an unauthorized discharge from a wastewater collection system, use the permit number of the treatment plant to which the collection system is tied.

TCEQ Region 13 Phone: 490-3096 TCEQ Region 13 Fax: 545-4329

Received

MAY 23 2017

GEN-W