ENERGY TRANSFER

12353 Eagle Pointe Drive
Mont Belvieu, Texas 77535
281-385-3573
281-385-3609 (Fax)
Cynthia.pate@energytransfer.com

July 22, 2019

Executive Director - MC 109
TCEQ
12100 Park 35 Circle
Austin, TX 78753

Subject: 40 CFR 60 Subpart OOOO: VOC Monitoring Semi-Annual Report
Lone Star NGL Fractionators LLC
CN604309419; RN106018260

Lone Star NGL Fractionators LLC is subject to the requirements of 40 CFR 60 Subpart OOOO per §60.5422 and is required to submit semi-annual fugitive monitoring reports.

On behalf of Lone Star the attached reports are submitted to satisfy the requirements of this subpart and represent the period between January 1, 2019 and June 30, 2019.

If you have any questions or require additional information please contact meat 281-382-3573 or cindy.pate@energytransfer.com.

Regards,

Cynthia L. Pate

Cynthia L. Pate REM, CEA, CESCO
Environmental Manager

CC: TCEQ – Region 12

Lone Star Mont Belvieu
NSPS OOOO Semi-Annual Report
January 1, 2019 through June 30, 2019

Assuring the
Highest Attainable
State of Compliance

Semi-Annual Report

From: 1/1/2019 to 6/30/2019, Regulation: NSPS OOOO
Lone Star Mont Belvieu

Unit: **Export**

	Valves:		Pumps:		Compressors:		Agitators		PRVs:	
# Components:		0		0		0		0		0
# Added:		0		0		0		0		0
# Perm OOS:		0		0		0		0		0
Total Monitored:		0		0		0		0		0
Month:	Leaking:	Not Repaired in Repair Period:	Leaking:	Not Repaired in Repair Period:	Leaking:	Not Repaired in Repair Period:	Leaking:	Not Repaired in Repair Period:	Leaking:	Not Repaired in Repair Period:
Jan 2019	0	0	0	0	0	0	0	0	0	0
Feb 2019	0	0	0	0	0	0	0	0	0	0
March 2019	0	0	0	0	0	0	0	0	0	0
April 2019	0	0	0	0	0	0	0	0	0	0
May 2019	0	0	0	0	0	0	0	0	0	0
June 2019	0	0	0	0	0	0	0	0	0	0

Semi-Annual Report

From: 1/1/2019 to 6/30/2019, Regulation: NSPS OOOO

Lone Star Mont Belvieu

Unit: FRAC1

# Components:	Valves:	5322	Pumps:	20	Compressors:	4	Agitators	0	PRVs:	66	Connectors	17382
# Added:		6		0		0		0		0		17
# Perm OOS:		17		0		0		0		0		28
Total Monitored:		4842		20		4		0		62		16107
Month:	Leaking:	Not Repaired in Repair Period:	Leaking:	Not Repaired in Repair Period:	Leaking:	Not Repaired in Repair Period:	Leaking:	Not Repaired in Repair Period:	Leaking:	Not Repaired in Repair Period:	Leaking:	Not Repaired in Repair Period:
Jan 2019	2	0	0	0	0	0	0	0	0	0	1	1
Feb 2019	24	5	0	0	0	0	0	0	0	0	3	0
March 2019	13	1	0	0	0	0	0	0	0	0	3	1
April 2019	6	2	0	0	0	0	0	0	0	0	1	0
May 2019	14	0	0	0	1	0	0	0	0	0	4	0
June 2019	12	0	0	0	0	0	0	0	0	0	8	1

Semi-Annual Report

From: 1/1/2019 to 6/30/2019, Regulation: NSPS OOOO

Lone Star Mont Belvieu

Unit: **FRAC2**

# Components:	Valves:	5557	Pumps:	17	Compressors:	4	Agitators	0	PRVs:	56	Connectors	17396
# Added:		2		0		0		0		0		6
# Perm OOS:		7		0		0		0		0		18
Total Monitored:		5357		16		4		0		51		16943
Month:	Leaking:	Not Repaired in Repair Period:	Leaking:	Not Repaired in Repair Period:	Leaking:	Not Repaired in Repair Period:	Leaking:	Not Repaired in Repair Period:	Leaking:	Not Repaired in Repair Period:	Leaking:	Not Repaired in Repair Period:
Jan 2019	0	0	0	0	0	0	0	0	0	0	1	0
Feb 2019	10	1	0	0	0	0	0	0	0	0	3	1
March 2019	7	1	0	0	0	0	0	0	0	0	2	0
April 2019	2	0	0	0	0	0	0	0	0	0	0	0
May 2019	19	0	0	0	0	0	0	0	0	0	10	1
June 2019	23	0	0	0	0	0	0	0	0	0	5	1

Semi-Annual Report

From: 1/1/2019 to 6/30/2019, Regulation: NSPS OOOO
Lone Star Mont Belvieu

Unit: **FRAC3**

# Components:	Valves:	6023	Pumps:	11	Compressors:	4	Agitators	0	PRVs:	70	Connectors	21789
# Added:		0		0		0		0		0		0
# Perm OOS:		3		0		0		0		0		3
Total Monitored:		5390		8		4		0		67		19351
Month:	Leaking:	Not Repaired in Repair Period:	Leaking:	Not Repaired in Repair Period:	Leaking:	Not Repaired in Repair Period:	Leaking:	Not Repaired in Repair Period:	Leaking:	Not Repaired in Repair Period:	Leaking:	Not Repaired in Repair Period:
Jan 2019	0	0	0	0	0	0	0	0	0	0	0	0
Feb 2019	6	0	0	0	0	0	0	0	0	0	2	0
March 2019	9	0	0	0	0	0	0	0	0	0	4	0
April 2019	0	0	0	0	0	0	0	0	0	0	0	0
May 2019	11	1	0	0	0	0	0	0	0	0	6	2
June 2019	13	1	0	0	0	0	0	0	0	0	6	1