ENERGY TRANSFER

12353 Eagle Pointe Drive
PO Box 250
Mont Belvieu, Texas 77580
281-573-3617
281-385-3609 (Fax)
Ashley.harrison@energytransfer.com

January 23, 2018

Executive Director - MC 109
TCEQ
12100 Park 35 Circle
Austin, TX 78753

Subject: 40 CFR 60 Subpart OOOO: VOC Monitoring Semi-Annual Report
Lone Star NGL Fractionators LLC
CN604309419; RN106018260

Lone Star NGL Fractionators LLC, is subject to the requirements of 40 CFR 60 Subpart OOOO per §60.5422 is required to submit semi-annual fugitive monitoring reports. On behalf of Lone Star the attached reports are submitted to satisfy the requirements of this subpart and represent the period between July 1, 2017 and December 31, 2017.

If you have any questions or require additional information I can be contacted at 281-576-3614 or anthony.poukish@energytransfer.com.

Regards,

Anthony Poukish
Sr. Environmental Specialist

Cc: TCEQ – Region 12
EPA – Region 6

Lone Star Mont Belvieu
NSPS OOOO Semi-Annual Report
July 1, 2017 through December 31, 2017

NSPS OOOO Semi-Annual Report
July - December 2017

Process Unit Identification
Lone Star Mont Belvieu
Area: Export

2H17

Total Monitore	0
Total Leaking	0
Leak Percent:	#DIV/0!

Delay of Repair

There were no valves added to the delay of repair list during this reporting period.
There were no relief valves added to the delay of repair list during this reporting period.
There were no pumps added to the delay of repair list during this reporting period.
There were no compressors added to the delay of repair list during this reporting period.
There were no_connectors added to the delay of repairs list during this reporting period.

Revisions

Previous Number of Agitators:	0
Number of Agitators added:	0
Number of Agitators retired:	0
Current number of Agitators:	0
Previous Number of Compressors:	0
Number of Compressors added:	0
Number of Compressors retired:	0
Current number of Compressors:	0
Previous Number of Pumps:	0
Number of Pumps added:	0
Number of Pumps retired:	0
Current number of Pumps:	0
Previous Number of Relief Valves:	0
Number of Relief Valves added:	0
Number of Relief Valves retired:	0
Current number of Relief Valves:	0
Previous Number of Valves:	0
Number of Valves added:	0
Number of Valves retired:	0
Current number of Valves:	0
Previous Number of Connectors:	3
Number of Connectors added:	0
Number of Connectors retired:	0
Current number of Connectors:	3

Semi-Annual Report

From: 7/1/2017 to 12/31/2017, Regulation: NSPS OOOO
Lone Star Mont Belvieu

Unit: **Export**

	Valves:	Pumps:	Compressors:	Agitators	PRVs:	Connectors
# Components:	0	0	0	0	0	3
# Added:	0	0	0	0	0	0
# Perm OOS:	0	0	0	0	0	0
Total Monitored:	0	0	0	0	0	3

Month:	Leaking:	Not Repaired in Repair Period:	Leaking:	Not Repaired in Repair Period:	Leaking:	Not Repaired in Repair Period:	Leaking:	Not Repaired in Repair Period:	Leaking:	Not Repaired in Repair Period:	Leaking:	Not Repaired in Repair Period:
July 2017	0	0	0	0	0	0	0	0	0	0	0	0
Aug 2017	0	0	0	0	0	0	0	0	0	0	0	0
Sept 2017	0	0	0	0	0	0	0	0	0	0	0	0
Oct 2017	0	0	0	0	0	0	0	0	0	0	0	0
Nov 2017	0	0	0	0	0	0	0	0	0	0	0	0
Dec 2017	0	0	0	0	0	0	0	0	0	0	0	0

Delay of Repairs:

EQUIP	TAG	LEAK DATE	REPAIR DATE	TYPE	REASON

No Delay of Repairs Performed.

Unit Removals:

No Unit Removals Performed.

Late Repairs:

No Late Repairs.

NSPS OOOO Semi-Annual Report
July - December 2017

Process Unit Identification
Lone Star Mont Belvieu
Area: FRAC1

2H17

Total Monitored:	20222
Total Leaking:	173
Leak Percent:	0.86%

Delay of Repair

There were 7 valves added to the delay of repair list during this reporting period.
There was 1 valve repaired during this reporting period.
There were no relief valves added to the delay of repair list during this reporting period.
There were no pumps added to the delay of repair list during this reporting period.
There were no compressors added to the delay of repair list during this reporting period.
There were 20 connectors added to the delay of repair list during this reporting period.
There was 7 connectors repaired during this reporting period.

Revisions

Previous Number of Agitators:	0
Number of Agitators added:	0
Number of Agitators retired:	0
Current number of Agitators:	0
Previous Number of Compressors:	4
Number of Compressors added:	0
Number of Compressors retired:	0
Current number of Compressors:	4
Previous Number of Pumps:	19
Number of Pumps added:	0
Number of Pumps retired:	0
Current number of Pumps:	19
Previous Number of Relief Valves:	47
Number of Relief Valves added:	0
Number of Relief Valves retired:	0
Current number of Relief Valves:	47
Previous Number of Valves:	5022
Number of Valves added:	59
Number of Valves retired:	0
Current number of Valves:	5081
Previous Number of Connectors:	16988
Number of Connectors added:	56
Number of Connectors retired:	0
Current number of Connectors:	17074

Semi-Annual Report

From: 7/1/2017 to 12/31/2017, Regulation: NSPS OOOO

Lone Star Mont Belvieu

Unit: FRAC1

# Components:	Valves:	5022	Pumps:	19	Compressors:	4	Agitators	0	PRVs:	47	Connectors	16988
# Added:		59		0		0		0		0		86
# Perm OOS:		0		0		0		0		0		0
Total Monitored:		4527		19		4		0		46		15626

Month:	Leaking:	Not Repaired in Repair Period:	Leaking:	Not Repaired in Repair Period.	Leaking:	Not Repaired in Repair Period:	Leaking:	Not Repaired in Repair Period.	Leaking:	Not Repaired in Repair Period:	Leaking:	Not Repaired in Repair Period:
July 2017	1	1	0	0	0	0	0	0	0	0	0	0
Aug 2017	10	0	0	0	0	0	0	0	0	0	22	2
Sept 2017	20	5	0	0	0	0	0	0	0	0	48	14
Oct 2017	0	0	0	0	0	0	0	0	0	0	1	0
Nov 2017	13	0	0	0	0	0	0	0	0	0	38	4
Dec 2017	11	1	0	0	0	0	0	0	0	0	9	0

Delay of Repairs:

Equip	Tag	Leak Date	Repair Date	Type	Reason
PV17.040	19219-000	7/26/2017	NOT REPAIRED	VALVE	WAITING FOR UNIT SHUTDOWN
HT16.018	11098-001	8/4/2017	10/4/2017	CONNECTOR	WAITING FOR UNIT SHUTDOWN
PV17.017	17604-002	8/9/2017	NOT REPAIRED	SCONN	WAITING FOR UNIT SHUTDOWN
PV17.039	19104-000	9/2/2017	NOT REPAIRED	VALVE	WAITING FOR UNIT SHUTDOWN
CM12.003A/B	22709-001	9/12/2017	11/6/107	SCONN	WAITING FOR UNIT SHUTDOWN
HT16.002	22871-001	9/13/2017	11/6/2017	CONNECTOR	WAITING FOR UNIT SHUTDOWN
HT16.002	22871-002	9/13/2017	NOT REPAIRED	CONNECTOR	WAITING FOR UNIT SHUTDOWN
PV17.004	22258-000	9/14/2017	NOT REPAIRED	CONNECTOR	WAITING FOR UNIT SHUTDOWN
DIBHEATPUM	22088-000	9/14/2017	NOT REPAIRED	CONNECTOR	WAITING FOR UNIT SHUTDOWN
PV17.004	22231-001	9/14/2017	NOT REPAIRED	SCONN	WAITING FOR UNIT SHUTDOWN
DIBHEATPUM	21804-000	9/14/2017	12/5/2017	CONNECTOR	WAITING FOR UNIT SHUTDOWN
PV17.003	22898-002	9/15/2017	NOT REPAIRED	CONNECTOR	WAITING FOR UNIT SHUTDOWN
PV17.003	22900-001	9/15/2017	NOT REPAIRED	CONNECTOR	WAITING FOR UNIT SHUTDOWN
PV17.003	22979-000	9/18/2017	NOT REPAIRED	SCONN	WAITING FOR UNIT SHUTDOWN
PV17.003	22979-002	9/18/2017	NOT REPAIRED	SCONN	WAITING FOR UNIT SHUTDOWN
PM18.041A	24076-001	9/18/2017	12/5/2017	SCONN	WAITING FOR UNIT SHUTDOWN
PM18.041A/B	24291-003	9/19/2017	12/5/2017	SCONN	WAITING FOR UNIT SHUTDOWN
PM18.041A/B	24296-001	9/19/2017	11/6/2017	CONNECTOR	WAITING FOR UNIT SHUTDOWN
HT16.018	11102-000	9/27/2017	NOT REPAIRED	VALVE	WAITING FOR UNIT SHUTDOWN
PV17.040	19234-000	9/27/2017	NOT REPAIRED	VALVE	WAITING FOR UNIT SHUTDOWN
PV17.039	19117-000	9/27/2017	NOT REPAIRED	VALVE	WAITING FOR UNIT SHUTDOWN
HR15.002	18658-000	9/27/2017	12/4/2017	VALVE	WAITING FOR UNIT SHUTDOWN
HT16.001	17374-001	11/1/2017	NOT REPAIRED	CONNECTOR	WAITING FOR UNIT SHUTDOWN
PV17.002	17534A-003	11/8/2017	NOT REPAIRED	SCONN	WAITING FOR UNIT SHUTDOWN
PV17.016	17090-001	11/9/2017	NOT REPAIRED	SCONN	WAITING FOR UNIT SHUTDOWN
PV17.002	17558-000	11/9/2017	NOT REPAIRED	CONNECTOR	WAITING FOR UNIT SHUTDOWN
HT16.001	17309-000	12/28/2017	NOT REPAIRED	VALVE	WAITING FOR UNIT SHUTDOWN

No Delay of Repairs Performed.

Unit Removals:

No Unit Removals Performed.

Late Repairs:

No Late Repairs.

NSPS OOOO Semi-Annual Report
July - December 2017

Process Unit Identification
Lone Star Mont Belvieu
Area: FRAC2

2H17

Total Monitored:	22067
Total Leaking:	128
Leak Percent:	0.58%

Delay of Repair

There were 1 valves added to the delay of repair list during this reporting period.
There was 1 valve repaired during this reporting period.
There were no relief valves added to the delay of repair list during this reporting period.
There were no pumps added to the delay of repair list during this reporting period.
There were no compressors added to the delay of repair list during this reporting period.
There were 15 connectors added to the delay of repair list during this reporting period.
There was 1 connector repaired during this reporting period.

Revisions

Previous Number of Agitators:	0
Number of Agitators added:	0
Number of Agitators retired:	0
Current number of Agitators:	0
Previous Number of Compressors:	4
Number of Compressors added:	0
Number of Compressors retired:	0
Current number of Compressors:	4
Previous Number of Pumps:	18
Number of Pumps added:	0
Number of Pumps retired:	0
Current number of Pumps:	18
Previous Number of Relief Valves:	84
Number of Relief Valves added:	0
Number of Relief Valves retired:	0
Current number of Relief Valves:	53
Previous Number of Valves:	5721
Number of Valves added:	31
Number of Valves retired:	0
Current number of Valves:	5752
Previous Number of Connectors:	18140
Number of Connectors added:	49
Number of Connectors retired:	0
Current number of Connectors:	18189

Semi-Annual Report

From: 7/1/2017 to 12/31/2017, Regulation: NSPS OOOO

Lone Star Mont Belvieu

Unit: FRAC2

# Components:	Valves:	5721	Pumps:	18	Compressors:	4	Agitators	0	PRVs:	84	Connectors	18140
# Added:		31		0		0		0		0		49
# Perm OOS:		0		0		0		0		0		0
Total Monitored:		5216		18		4		0		53		16776

Month:	Leaking:	Not Repaired In Repair Period:	Leaking:	Not Repaired in Repair Period:	Leaking:	Not Repaired in Repair Period:	Leaking:	Not Repaired In Repair Period:	Leaking:	Not Repaired In Repair Period:	Leaking:	Not Repaired In Repair Period:
July 2017	1	0	0	0	0	0	0	0	0	0	1	0
Aug 2017	6	1	0	0	0	0	0	0	0	0	22	4
Sept 2017	15	1	0	0	0	0	0	0	0	0	28	3
Oct 2017	1	0	0	0	0	0	0	0	0	0	0	0
Nov 2017	8	0	0	0	0	0	0	0	0	0	21	4
Dec 2017	14	0	0	0	0	0	0	0	0	0	11	5

Delay of Repairs:

EQUIP	TAG	LEAK DATE	REPAIR DATE	TYPE	REASON
CM12.002	01854-000	8/14/2017	NOT REPAIRED	CONNECTOR	WAITING FOR UNIT SHUTDOWN
HR15.001	03157-002	8/16/2017	NOT REPAIRED	CONNECTOR	WAITING FOR UNIT SHUTDOWN
HR15.001	03177-002	8/16/2017	NOT REPAIRED	CONNECTOR	WAITING FOR UNIT SHUTDOWN
PV17.017	01814-000	8/21/2017	NOT REPAIRED	VALVE	WAITING FOR UNIT SHUTDOWN
COOLINGTOWER	12745-001	9/7/2017	NOT REPAIRED	CONNECTOR	WAITING FOR UNIT SHUTDOWN
PM18.012B	15401-000	9/8/2017	10/11/2017	VALVE	WAITING FOR UNIT SHUTDOWN
PV17.003	15421-002	9/8/2017	NOT REPAIRED	SCONN	WAITING FOR UNIT SHUTDOWN
PV17.014	14887-000	9/11/2017	NOT REPAIRED	CONNECTOR	WAITING FOR UNIT SHUTDOWN
HT16.018	01094-000	11/16/2017	NOT REPAIRED	CONNECTOR	WAITING FOR UNIT SHUTDOWN
HT16.017	01197-000	11/20/107	12/6/2017	CONNECTOR	WAITING FOR UNIT SHUTDOWN
PV17.002	01683-000	11/20/2017	NOT REPAIRED	CONNECTOR	WAITING FOR UNIT SHUTDOWN
PV17.039	03620-000	11/21/2017	NOT REPAIRED	CONNECTOR	WAITING FOR UNIT SHUTDOWN
CM12.003A/B	14413-003	12/13/2017	NOT REPAIRED	SCONN	WAITING FOR UNIT SHUTDOWN
HT16.002	04590-000	12/14/2017	NOT REPAIRED	SCONN	WAITING FOR UNIT SHUTDOWN
HT16.002	04591-000	12/14/2017	NOT REPAIRED	SCONN	WAITING FOR UNIT SHUTDOWN
DIBSTRUCTUR	15236-002	12/14/2017	NOT REPAIRED	CONNECTOR	WAITING FOR UNIT SHUTDOWN
PV17.025	16066-001	12/18/2017	NOT REPAIRED	CONNECTOR	WAITING FOR UNIT SHUTDOWN

No Delay of Repairs Performed.

Unit Removals:

No Unit Removals Performed.

Late Repairs:

AREA	EQUIP	TAG	TYPE	LEAK DATE	PPM	REPAIR DATE	DOR?	REASON:
01	PV17.039	03615-000	CONNECTOR	8/18/2017	671	9/5/2017		Due to Hurricane Harvey

No Late Repairs.

NSPS OOOO Semi-Annual Report
July - December 2017

Process Unit Identification
Lone Star Mont Belvieu
Area: FRAC3

2H17

Total Monitore	24056
Total Leaking	250
Leak Percent:	1.04%

Delay of Repair

There were 5 valves added to the delay of repair list during this reporting period.
There was 1 valve repaired during this reporting period.
There were 1 relief valves added to the delay of repair list during this reporting period.
There were no pumps added to the delay of repair list during this reporting period.
There were no compressors added to the delay of repair list during this reporting period.
There were 26 connectors added to the delay of repair list during this reporting period.
There was 8 connectors repaired during this reporting period.

Revisions

Previous Number of Agitators:	0
Number of Agitators added:	0
Number of Agitators retired:	0
Current number of Agitators:	0
Previous Number of Compressors:	4
Number of Compressors added:	0
Number of Compressors retired:	0
Current number of Compressors:	4
Previous Number of Pumps:	9
Number of Pumps added:	0
Number of Pumps retired:	0
Current number of Pumps:	9
Previous Number of Relief Valves:	68
Number of Relief Valves added:	0
Number of Relief Valves retired:	0
Current number of Relief Valves:	68
Previous Number of Valves:	5977
Number of Valves added:	9
Number of Valves retired:	0
Current number of Valves:	5986
Previous Number of Connectors:	21758
Number of Connectors added:	12
Number of Connectors retired:	0
Current number of Connectors:	21770

Semi-Annual Report

From: 7/1/2017 to 12/31/2017, Regulation: NSPS OOOO
Lone Star Mont Belvieu

Unit: FRAC3

# Components:	Valves:	5977	Pumps:	9	Compressors:	4	Agitators	0	PRVs:	68	Connectors	21758
# Added:		9		0		0		0		0		12
# Perm OOS:		0		0		0		0		0		0
Total Monitored:		5120		9		4		0		65		18858

Month:	Leaking:	Not Repaired in Repair Period:	Leaking:	Not Repaired in Repair Period:	Leaking:	Not Repaired in Repair Period:	Leaking:	Not Repaired in Repair Period:	Leaking:	Not Repaired in Repair Period:	Leaking:	Not Repaired in Repair Period:
July 2017	17	1	0	0	0	0	0	0	0	0	42	10
Aug 2017	0	0	0	0	0	0	0	0	0	0	0	0
Sept 2017	26	2	0	0	0	0	0	0	1	1	49	3
Oct 2017	18	1	0	0	0	0	0	0	0	0	40	0
Nov 2017	5	0	0	0	0	0	0	0	0	0	0	0
Dec 2017	16	1	0	0	0	0	0	0	0	0	38	13

Delay of Repairs:

EQUIP	TAG	LEAK DATE	REPAIR DATE	TYPE	REASON
300-AW-1202	9332-001	7/11/2017	10/3/2017	SCONN	WAITING FOR UNIT SHUTDOWN
CM12.003A	7504-000	7/13/2017	NOT REPAIRED	CONNECTOR	WAITING FOR UNIT SHUTDOWN
CM12.003A	7518-000	7/13/2017	NOT REPAIRED	CONNECTOR	WAITING FOR UNIT SHUTDOWN
HT16.002	8752-064	7/14/2017	10/3/2017	SCONN	WAITING FOR UNIT SHUTDOWN
HT16.002	8753-045	7/14/2017	10/3/2017	SCONN	WAITING FOR UNIT SHUTDOWN
HT16.029	6351-000	7/18/2017	10/3/2017	VALVE	WAITING FOR UNIT SHUTDOWN
HT17.012	8248-001	7/19/2017	12/11/2017	SCONN	WAITING FOR UNIT SHUTDOWN
HT17.012	8248-002	7/19/2017	12/11/2017	SCONN	WAITING FOR UNIT SHUTDOWN
HT17.012	8249-001	7/19/2017	12/11/2017	SCONN	WAITING FOR UNIT SHUTDOWN
PV17.003	9001-002	7/20/2017	10/3/2017	CONNECTOR	WAITING FOR UNIT SHUTDOWN
300-PV17.002	2036-000	7/27/2017	11/1/2017	CONNECTOR	WAITING FOR UNIT SHUTDOWN
PV17.003	1748-000	9/22/2017	NOT REPAIRED	VALVE	WAITING FOR UNIT SHUTDOWN
PV17.003	1750-000	9/22/2017	NOT REPAIRED	VALVE	WAITING FOR UNIT SHUTDOWN
300-HT16.001	1522-001	9/27/2017	NOT REPAIRED	CONNECTOR	WAITING FOR UNIT SHUTDOWN
HT16.306A	2632-009	9/27/2017	NOT REPAIRED	SCONN	WAITING FOR UNIT SHUTDOWN
300-PV17.002	2048-000	9/28/2017	NOT REPAIRED	CONNECTOR	WAITING FOR UNIT SHUTDOWN
300-PV17.027	1442-000	10/13/2017	NOT REPAIRED	VALVE	WAITING FOR UNIT SHUTDOWN
300-HT16.017	1832-000	12/19/2017	NOT REPAIRED	CONNECTOR	WAITING FOR UNIT SHUTDOWN
300-FL20.002	4093-000	12/20/2017	NOT REPAIRED	CONNECTOR	WAITING FOR UNIT SHUTDOWN
300-HT16.017	1209-000	12/20/2017	NOT REPAIRED	CONNECTOR	WAITING FOR UNIT SHUTDOWN
300-PV17.002	2035-001	12/20/2017	NOT REPAIRED	SCONN	WAITING FOR UNIT SHUTDOWN
300-PV17.017	2121-001	12/21/2017	NOT REPAIRED	CONNECTOR	WAITING FOR UNIT SHUTDOWN
300-PV17.017	1577-004	12/21/2017	NOT REPAIRED	SCONN	WAITING FOR UNIT SHUTDOWN
300-PV17.029	0123-002	12/21/2017	NOT REPAIRED	SCONN	WAITING FOR UNIT SHUTDOWN
CM12.002	2555-000	12/26/2017	NOT REPAIRED	SCONN	WAITING FOR UNIT SHUTDOWN
CM12.002	2556-002	12/26/2017	NOT REPAIRED	SCONN	WAITING FOR UNIT SHUTDOWN
CM12.002	2557-000	12/26/2017	NOT REPAIRED	VALVE	WAITING FOR UNIT SHUTDOWN
CM12.002	2557-001	12/26/2017	NOT REPAIRED	SCONN	WAITING FOR UNIT SHUTDOWN
CM12.002	2557-002	12/26/2017	NOT REPAIRED	SCONN	WAITING FOR UNIT SHUTDOWN
HT16.004	4040-043	12/27/2017	NOT REPAIRED	SCONN	WAITING FOR UNIT SHUTDOWN
PV17.005	4662-000	12/27/2017	NOT REPAIRED	CONNECTOR	WAITING FOR UNIT SHUTDOWN
300-HT16.001	1522-000	9/27/2017	NOT REPAIRED	RVLV	WAITING FOR UNIT SHUTDOWN

No Delay of Repairs Performed.

Unit Removals:

No Unit Removals Performed.

Late Repairs:

No Late Repairs.

January 29,2018

Dear Customer:

The following is the proof-of-delivery for tracking number **771300047329**.

Delivery Information:

Status:	Delivered	**Delivered to:**	Mailroom
Signed for by:	C.STERLING	**Delivery location:**	12100 N INTERSTATE 35 AUSTIN, TX 78753
Service type:	FedEx Standard Overnight	**Delivery date:**	Jan 24, 2018 09:05
Special Handling:	Deliver Weekday Direct Signature Required		

Sterling

Shipping Information:

Tracking number:	771300047329	**Ship date:**	Jan 23, 2018
		Weight:	0.5 lbs/0.2 kg

Recipient:
Air Program
TCEQ
12100 Park 35 Circle
MC 109
AUSTIN, TX 78753 US

Shipper:
Cynthia Pate
Energy Transfer
12353 Eagle Pointe Drive
Mont Belvieu, TX 77580 US

Reference 350166
Purchase order number: Shipment Reason
Invoice number Enter AFE # if Applicable

Thank you for choosing FedEx.

January 29,2018

Dear Customer:

The following is the proof-of-delivery for tracking number **771300074403**.

Delivery Information:

Status:	Delivered	**Delivered to:**	Receptionist/Front Desk
Signed for by:	S.FORD	**Delivery location:**	5425 POLK ST H HOUSTON, TX 77023
Service type:	FedEx Standard Overnight	**Delivery date:**	Jan 24, 2018 09:45
Special Handling:	Deliver Weekday Direct Signature Required		



Shipping Information:

Tracking number:	771300074403	**Ship date:**	Jan 23, 2018
		Weight:	0.5 lbs/0.2 kg

Recipient:
Air Section
TCEQ Region 12
5425 Polk Street, Suite H
HOUSTON, TX 77023 US

Shipper:
Cynthia Pate
Energy Transfer
12353 Eagle Pointe Drive
Mont Belvieu, TX 77580 US

Reference	350166
Purchase order number:	Shipment Reason
Invoice number	Enter AFE # if Applicable

Thank you for choosing FedEx.

January 29,2018

Dear Customer:

The following is the proof-of-delivery for tracking number **771300102543**.

Delivery Information:

Status:	Delivered	**Delivered to:**	Receptionist/Front Desk
Signed for by:	C.LEWIS	**Delivery location:**	1445 ROSS AV DALLAS, TX 75202
Service type:	FedEx Standard Overnight	**Delivery date:**	Jan 24, 2018 11:11
Special Handling:	Deliver Weekday Direct Signature Required		



Shipping Information:

Tracking number:	771300102543	**Ship date:**	Jan 23, 2018
		Weight:	0.5 lbs/0.2 kg

Recipient:
Air Section
US EPA Region 6
1445 Ross Avenue
6PD-R
DALLAS, TX 75202 US

Shipper:
Cynthia Pate
Energy Transfer
12353 Eagle Pointe Drive
Mont Belvieu, TX 77580 US

Reference 350166
Purchase order number: Shipment Reason
Invoice number Enter AFE # if Applicable

Thank you for choosing FedEx.

ORIGIN ID:HBYA (281) 385-3573
CYNTHIA PATE
ENERGY TRANSFER
12353 EAGLE POINTE DRIVE

MONT BELVIEU, TX 77580
UNITED STATES US

SHIP DATE: 23JAN18
ACTWGT: 0.10 LB
CAD: 106248940/INET3980

BILL SENDER

TO **AIR PROGRAM**
TCEQ
12100 PARK 35 CIRCLE
MC 109
AUSTIN TX 78753
(512) 239-1000
INV: ENTER AFE # IF APPLICABLE
PO: SHIPMENT REASON

REF: 350166

DEPT:

552J1/8D40/DCA5

J1818180100801uv

FedEx Express

WED - 24 JAN 3:00P
STANDARD OVERNIGHT
DSR
78753
AUS
TX-US

TRK# 0201 **7713 0004 7329**

A8 MMRA

After printing this label:
1. Use the 'Print' button on this page to print your label to your laser or inkjet printer.
2. Fold the printed page along the horizontal line.
3. Place label in shipping pouch and affix it to your shipment so that the barcode portion of the label can be read and scanned.

Warning: Use only the printed original label for shipping. Using a photocopy of this label for shipping purposes is fraudulent and could result in additional billing charges, along with the cancellation of your FedEx account number.

Use of this system constitutes your agreement to the service conditions in the current FedEx Service Guide, available on fedex.com. FedEx will not be responsible for any claim in excess of $100 per package, whether the result of loss, damage, delay, non-delivery, misdelivery, or misinformation, unless you declare a higher value, pay an additional charge, document your actual loss and file a timely claim. Limitations found in the current FedEx Service Guide apply. Your right to recover from FedEx for any loss, including intrinsic value of the package, loss of sales, income interest, profit, attorney's fees, costs, and other forms of damage whether direct, incidental, consequential, or special is limited to the greater of $100 or the authorized declared value. Recovery cannot exceed actual documented loss. Maximum for items of extraordinary value is $1,000, e.g. jewelry, precious metals, negotiable instruments and other items listed in our ServiceGuide. Written claims must be filed within strict time limits, see current FedEx Service Guide.