ENERGY TRANSFER

12353 Eagle Pointe Drive
Mont Belvieu, Texas 77535
281-576-3614
281-385-3609 (Fax)
anthony.poukish@energytransfer.com

January 29, 2018

Executive Director - MC 109
TCEQ
12100 Park 35 Circle
Austin, TX 78753

Subject: 40 CFR 60 Subpart OOOO: VOC Monitoring Semi-Annual Report
Lone Star NGL Fractionators LLC
CN604309419; RN106018260

Lone Star NGL Fractionators LLC is subject to the requirements of 40 CFR 60 Subpart OOOO per §60.5422 and is required to submit semi-annual fugitive monitoring reports.

On behalf of Lone Star the attached reports are submitted to satisfy the requirements of this subpart and represent the period between July 1, 2018 and December 31, 2018.

If you have any questions or require additional information please contact meat 281-576-3614 or anthony.poukish@energytransfer.com.

Regards,

Anthony Poukish
Sr. Specialist – Environmental

CC: TCEQ – Region 12
EPA – Region 6



Lone Star Mont Belvieu
NSPS OOOO Semi-Annual Report
July 1, 2018 through December 31, 2018

Assuring the
Highest Attainable
State of Compliance

Semi-Annual Report

From: 7/1/2018 to 12/31/2018, Regulation: NSPS OOOO

Lone Star Mont Belvieu

Unit: **Export**

# Components:	Valves:	0	Pumps:	0	Compressors:	0	Agitators	0	PRVs:	0	Connectors	0
# Added:		0		0		0		0		0		0
# Perm OOS:		0		0		0		0		0		0
Total Monitored:		0		0		0		0		0		0
Month:	Leaking:	Not Repaired in Repair Period:	Leaking:	Not Repaired in Repair Period:	Leaking:	Not Repaired in Repair Period:	Leaking:	Not Repaired in Repair Period:	Leaking:	Not Repaired in Repair Period:	Leaking:	Not Repaired in Repair Period:
July 2018	0	0	0	0	0	0	0	0	0	0	0	0
Aug 2018	0	0	0	0	0	0	0	0	0	0	0	0
Sept 2018	0	0	0	0	0	0	0	0	0	0	0	0
Oct 2018	0	0	0	0	0	0	0	0	0	0	0	0
Nov 2018	0	0	0	0	0	0	0	0	0	0	0	0
Dec 2018	0	0	0	0	0	0	0	0	0	0	0	0

Semi-Annual Report

From: 7/1/2018 to 12/31/2018, Regulation: NSPS OOOO

Lone Star Mont Belvieu

Unit: **FRAC1**

# Components:	Valves:	5457	Pumps:	20	Compressors:	4	Agitators	0	PRVs:	66	Connectors	17873
# Added:		14		0		0		0		0		3
# Perm OOS:		16		0		0		0		0		116
Total Monitored:		4740		20		4		0		62		15993
Month:	Leaking:	Not Repaired in Repair Period:	Leaking:	Not Repaired in Repair Period:	Leaking:	Not Repaired in Repair Period:	Leaking:	Not Repaired in Repair Period:	Leaking:	Not Repaired in Repair Period:	Leaking:	Not Repaired in Repair Period:
July 2018	4	0	0	0	0	0	0	0	0	0	0	0
Aug 2018	19	2	0	0	0	0	0	0	0	0	35	5
Sept 2018	17	3	0	0	0	0	0	0	0	0	25	4
Oct 2018	3	2	0	0	0	0	0	0	0	0	0	0
Nov 2018	6	1	0	0	0	0	0	0	0	0	22	4
Dec 2018	2	0	0	0	0	0	0	0	0	0	7	0

Semi-Annual Report

From: 7/1/2018 to 12/31/2018, Regulation: NSPS OOOO

Lone Star Mont Belvieu

Unit: **FRAC2**

# Components:	Valves:	5736	Pumps:	17	Compressors:	4	Agitators	0	PRVs:	84	Connectors	18070
# Added:		4		0		0		0		0		11
# Perm OOS:		14		0		0		0		0		148
Total Monitored:		5183		16		4		0		51		16667
Month:	Leaking:	Not Repaired in Repair Period:	Leaking:	Not Repaired in Repair Period:	Leaking:	Not Repaired in Repair Period:	Leaking:	Not Repaired in Repair Period:	Leaking:	Not Repaired in Repair Period:	Leaking:	Not Repaired in Repair Period:
July 2018	2	0	0	0	0	0	0	0	0	0	0	0
Aug 2018	18	4	0	0	0	0	0	0	0	0	64	15
Sept 2018	11	0	0	0	0	0	0	0	0	0	35	4
Oct 2018	2	1	0	0	0	0	0	0	0	0	0	0
Nov 2018	3	1	0	0	0	0	0	0	0	0	29	7
Dec 2018	5	1	0	0	0	0	0	0	0	0	17	2

Semi-Annual Report

From: 7/1/2018 to 12/31/2018, Regulation: NSPS OOOO

Lone Star Mont Belvieu

Unit: **FRAC3**

# Components:	Valves:	6026	Pumps:	11	Compressors:	4	Agitators	0	PRVs:	70	Connectors	21792
# Added:		1		0		0		0		0		1
# Perm OOS:		8		0		0		0		0		26
Total Monitored:		5128		10		4		0		67		18833
Month:	Leaking:	Not Repaired in Repair Period:	Leaking:	Not Repaired in Repair Period:	Leaking:	Not Repaired in Repair Period:	Leaking:	Not Repaired in Repair Period:	Leaking:	Not Repaired in Repair Period:	Leaking:	Not Repaired in Repair Period:
July 2018	5	1	0	0	0	0	0	0	0	0	0	0
Aug 2018	10	4	0	0	0	0	0	0	0	0	38	7
Sept 2018	1	0	0	0	0	0	0	0	0	0	13	0
Oct 2018	3	0	0	0	0	0	0	0	0	0	0	0
Nov 2018	8	1	0	0	0	0	0	0	0	0	23	5
Dec 2018	9	0	0	0	0	0	0	0	1	0	13	2