LEACHATE COLLECTION WELLS
OM&M MONITORING AND BAILING DATA SHEET
WASTE DISPOSAL, INC. SUPERFUND SITE

DATE: November 5, 2007

TECHNICIAN NAME: Refugio D. Gutierrez.

TECHNICIAN SIGNATURE

WELL ID	BOTTOM OF WELL AFTER CONSTRUCT-ED [TOTAL DEPTH] (ft)	MEASURED BOTTOM OF WELL [TOTAL DEPTH] (ft)	GAUGING TIME		DEPTH TO LIQUID (ft)						HEIGHT OF LIQUID COLUMN (ft)		VOLUME OF LIQUID REMOVED (gallons)	COMMENTS
					Start			Finish						
			Start	Finish	1st Rdg.	2nd Rdg.	3rd Rdg.	1st Rdg.	2nd Rdg.	3rd Rdg.	Start	Finish		
LC-1	22.25	22.25	1154	1205	18.60	18.60	18.60	22.00	22.00	22.00				
LC-2	21.90	21.90	1216	1230	11.85	11.85	11.85	21.05	21.05	21.05				
LC-3	22.20	22.20	1237	1245	20.90	20.90	20.90	21.33	21.33	21.33				
LC-4	21.90	21.90	1251	1304	11.20	11.20	11.20	21.25	21.25	21.25				

W:\InterimOpMain+Mon\LeachateCollectionWells\WorkPlan+FieldForms\February2007\Feb507LC-WellsM&B(YF1).doc

TRC
Customer-Focused Solutions

LEACHATE COLLECTION WELLS
OM&M INSPECTION SHEET
WASTE DISPOSAL, INC. SUPERFUND SITE

INSPECTOR'S NAME	INSPECTOR'S SIGNATURE	INSPECTION TIME	INSPECTION DATE
Refugio D. Gutierrez.	[signature]		November 5, 2007

ITEM OF POTENTIAL CONCERN	CONDITIONS OBSERVED				COMMENTS	CHECK (√) BELOW WHEN COMPLETED
	WELL ID LC-1	WELL ID LC-2	WELL ID LC-3	WELL ID LC-4		
Wellhead (well box, cover, gasket, concrete)	ok	ok	ok	ok		√√√√
Well Casing and Cap/Plug	ok	ok	ok	ok		√√√√
Liquid Present in Well Box	ok	ok	ok	ok.		√√√√
Other:						
Other:						
Other:						

W:\InterimOpMain+Mon\LeachateCollectionWells\WorkPlan+FieldForms\February2007\Feb507LC-WellsInspection(YF).doc

TRC
Customer-Focused Solutions

DAILY FIELD REPORT

JOB NAME: WASTE DISPOSAL, INC. (WDI)	PROJECT NUMBER: 125154/**001400**	DATE: 11/5/2007
LOCATION: Santa Fe Springs, California	WEATHER:	DAY: Monday
OM&M CONTRACTOR: TRC	FOREMAN:	
FIELD TECHNICIAN:	INSPECTION/TESTING OF: LEACHATE MONITORING/CONTROL SYSTEM	

SUMMARY OF OPERATIONS/WORK PERFORMED::

Drove to WDI. Arrived at WDI. Paper work. Knock out pot. Started Gauging and Hand Bailing Product. Finished. Cleaned well lids. Checked Fence for damage. Cleaned around WDI. Pumped out water from water drums. Drove to shop.

TRC
Customer-Focused Solutions

Note: Specific System Data and Observations are Included on "OM&M Inspection Sheets" and "OM&M Monitoring and Bailing Data Sheets"

DAILY FIELD REPORT
WASTE DISPOSAL, INC
SANTA FE SPRINGS, CALIFORNIA

TRC

FIGURE J.1