LEACHATE COLLECTION WELLS
INTERIM OM&M MONITORING AND BAILING DATA SHEET
WASTE DISPOSAL, INC. SUPERFUND SITE

DATE: MAY 10-07 ~~December 21, 2006~~

TECHNICIAN NAME: Baltazar

TECHNICIAN SIGNATURE:

WELL ID	BOTTOM OF WELL AFTER CONSTRUCTED [TOTAL DEPTH] (ft)	MEASURED BOTTOM OF WELL [TOTAL DEPTH] (ft)	GAUGING TIME		DEPTH TO LIQUID (ft)						HEIGHT OF LIQUID COLUMN (ft)		VOLUME OF LIQUID REMOVED (gallons)	COMMENTS
					Start			Finish						
			Start	Finish	1st Rdg.	2nd Rdg.	3rd Rdg.	1st Rdg.	2nd Rdg.	3rd Rdg.	Start	Finish		
LC-1	22.25	22.24	1057	1105	19.92	19.92	19.92	21.71	21.71	21.71				
LC-2	21.90	21.90	1113	1124	13.28	13.28	13.28	21.16	21.16	21.16				
LC-3	22.20													
LC-4	21.90	21.89	1132	1144	12.97	12.97	12.97	21.19	21.19	21.19				

W:\InterimOpMain+Mon\LeachateCollectionWells\WorkPlan+FieldForms\December2006\Dec2106LC-WellsM&B(YFI).doc

TRC
Customer Focused Solutions

LEACHATE COLLECTION WELLS
INTERIM OM&M INSPECTION SHEET
WASTE DISPOSAL, INC. SUPERFUND SITE

INSPECTOR'S NAME	INSPECTOR'S SIGNATURE	INSPECTION TIME	INSPECTION DATE
Baltazar	[illegible]	1043	May 10-07 ~~January 18, 2007~~

ITEM OF POTENTIAL CONCERN	CONDITIONS OBSERVED				COMMENTS	CHECK (•) BELOW WHEN COMPLETED
	WELL ID LC-1	WELL ID LC-2	WELL ID LC-3	WELL ID LC-4		
Wellhead (well box, cover, gasket, concrete)	OK	OK		OK		✓✓✓
Well Casing and Cap/Plug	OK	OK		OK		✓✓✓
Liquid Present in Well Box	NO	NO		NO		✓✓✓
Other:						
Other:						
Other:						

W:\InterimOpMaintMon\LeachateCollection\Wells\WorkPlan+FieldForms\January2007\Jan1807LC-WellsInspection(YF).doc

TRC
Customer-Focused Solutions

DAILY FIELD REPORT

JOB NAME: WDI	PROJECT NUMBER:	DATE: 5-10-07
LOCATION:	WEATHER: Hot	DAY: THURS.
CONTRACTOR:	FOREMAN:	
FIELD TECHNICIAN: Baltazar	INSPECTION/TESTING OF:	

SUMMARY OF OPERATIONS:

Drove around site to check for damage on fence than gauge LC-1, LC-2 and LC-4 Also hand bail LC-1, LC-2 and LC-4 into a 55gallon drum and clean casing and lids from all wells.

TRC Alton Geoscience