LEACHATE COLLECTION WELLS
INTERIM OM&M MONITORING AND BAILING DATA SHEET
WASTE DISPOSAL, INC. SUPERFUND SITE

DATE: 5/7/07

TECHNICIAN NAME: Baltazar

TECHNICIAN SIGNATURE: [illegible]

WELL ID	BOTTOM OF WELL AFTER CONSTRUCTED [TOTAL DEPTH] (ft)	MEASURED BOTTOM OF WELL [TOTAL DEPTH] (ft)	GAUGING TIME		DEPTH TO LIQUID (ft)						HEIGHT OF LIQUID COLUMN (ft)		VOLUME OF LIQUID REMOVED (gallons)	COMMENTS
					Start			Finish						
			Start	Finish	1st Rdg.	2nd Rdg.	3rd Rdg.	1st Rdg.	2nd Rdg.	3rd Rdg.	Start	Finish		
LC-1	22.25	22.24	1050	1105	19.77	19.77	19.77	21.70	21.70	21.70				
LC-2	21.90	21.90	1112	1123	12.97	12.97	12.97	21.15	21.15	21.15				
LC-3	22.20	22.19	1134	1140	21.28	21.28	21.28							Less than one foot of product
LC-4	21.90	21.90	1153	1208	12.07	12.07	12.07	21.21	21.21	21.21				

W:\Interim_OM+M\LeachateCollectionWells\WorkPlan+FieldForms\July2006\July3106LC-WellsM&B(YF).doc

TRC
Customer-Focused Solutions

LEACHATE COLLECTION WELLS
INTERIM OM&M INSPECTION SHEET
WASTE DISPOSAL, INC. SUPERFUND SITE

INSPECTOR'S NAME	INSPECTOR'S SIGNATURE	INSPECTION TIME	INSPECTION DATE
Baltazar		1025	8/7/09

ITEM OF POTENTIAL CONCERN	CONDITIONS OBSERVED				COMMENTS	CHECK (•) BELOW WHEN COMPLETED
	WELL ID LC-1	WELL ID LC-2	WELL ID LC-3	WELL ID LC-4		
Wellhead (well box, cover, gasket, concrete)	OK	OK	OK	OK		✓✓✓✓
Well Casing and Cap/Plug	OK	OK	OK	OK		✓✓✓✓
Liquid Present in Well Box	NO	NO	NO	NO		✓✓✓✓
Other:						
Other:						
Other:						

W:\Interim_OM+M\LeachateCollectionWells\WorkPlan+FieldForms\October2006\Oct2306LC-WellsInspection(YF).doc

TRC
Customer-Focused Solutions

DAILY FIELD REPORT

JOB NAME: WDF	PROJECT NUMBER: 2903316-01 1303A	DATE: 5/7/07
LOCATION:	WEATHER: HOT	DAY: Monday
CONTRACTOR:	FOREMAN:	
FIELD TECHNICIAN: Baltazar	INSPECTION/TESTING OF:	

SUMMARY OF OPERATIONS:

Drove to site checked fence for damage. gauge LC-1, LC-2, LC-3 and LC-4 and hand bail LC-1, LC-2, and LC-4 into a 55 gallon drum and Drain Knock out pot Also clean casing and Lids

TRC Alton Geoscience