

N

Figure 8.2-47
Natural Attenuation Parameters in Groundwater
Elevation -5 ft, MSL
Remedial Investigation Report
Stratford Army Engine Plant
Stratford, Connecticut

MACTEC Engineering and Consulting, Inc.

Prepared by RRR | Checked by DRP

Document: P:\Projects\AFCEE\4P Plus AE\SAEP\GIS\MapDocuments\SAEP_revised_mna.mxd PDF: P:\Projects\AFCEE\4P Plus AE\SAEP\GIS\Figures\RSR_slices\Fig8_2_47_mna5.pdf 05/17/2004 9:29 AM rrrustad