Dvirka and Bartilucci CONSULTING ENGINEERS A DIVISION OF WILLIAM F. COSULICH ASSOCIATES, P.C.		DATE: 3/18/2010 DAY: Thursday
		REPORT NO. 1
		PAGE NO. 1 of 3
		PROJECT NO. 2582
		LOGBOOK NO. 1, PAGES 1-7

DAILY FIELD ACTIVITY REPORT

PROJECT	**Gladsky Marine Site**
LOCATION	**Glen Cove, New York**
ATTACHMENTS	**Photo Log and Photos**

WEATHER	TIME	TEMP.	PRECIP.	WIND (MPH)	WIND (DIR)
Sunny	7:00	45◦F	None	--	--
Sunny	15:00	70 ◦F	None	--	--

SITE CONDITIONS: Dry and sunny.

PERSONNEL ON SITE:

NAME	AFFILIATION	ARRIVAL TIME	DEPART TIME
Antonio Pires	Dvirka and Bartilucci Consulting Engineers	06:45	16:00
Paul Martorano	Dvirka and Bartilucci Consulting Engineers	7:00	8:30
John Syzmanski	EnviroTrac Ltd.	7:00	13:30
Don Stedge	YEC	7:00	16:00
Jim Christopher	YEC	7:00	16:00
Joe [ ]	Glen Cove Water District	09:15	--
Paul Woytsiak	Nassau County	09:15	09:30
Mike Colangelo	Glen Cove Water District	09:30	--

EQUIPMENT ON SITE:

TYPE	MODEL	TYPE	MODEL
EnviroTrac Field Truck	Toyota Tundra (ENF6869)		
GC Water Truck			
GC Water Truck			
Nassau County Truck	Ford Truck (M19720)		

HEALTH & SAFETY:

PPE REQUIRED: ☒ LEVEL D ☐ LEVEL C ☐ LEVEL B ☐ LEVEL A **HASP?** No

SITE SAFETY OFFICER:

H & S NOTES: Site work performed in Level D PPE.

Dvirka and Bartilucci
CONSULTING ENGINEERS
A DIVISION OF WILLIAM F. COSULICH ASSOCIATES, P.C.

DATE: 3/18/2010	
PAGE NO. 2 of 3	
LOGBOOK NO. 1, PAGES 1-7	
PROJECT NO. 2582	

DAILY FIELD ACTIVITY REPORT

DESCRIPTION OF MATERIALS UTILIZED

DESCRIPTION	UNIT	QUANTITY
NONE		

Dvirka and Bartilucci CONSULTING ENGINEERS A DIVISION OF WILLIAM F. COSULICH ASSOCIATES, P.C.		DATE: 3/18/2010
		PAGE NO. 3 of 3
		LOGBOOK NO. 1, PAGES 1-7
		PROJECT NO. 2582

DAILY FIELD ACTIVITY REPORT

DESCRIPTION OF WORK PERFORMED AND OBSERVED

06:45 - On-site to meet with Paul Martorano to complete an initial site walk.

07:00 - YEC, EnviroTrac's subcontracted surveyor, arrived to complete the initial site survey. YEC setup reference points in order to complete the survey and measure the existing site elevations (see photos 1 and 2).

09:15 - Joe from Glen Cove Water District (GCWD) arrived, then shortly after Mr. Paul Woytysiak from Nassau County arrived. EnviroTrac and Glen Cove Water District discussed access to the adjacent pump house location and whether or not it was necessary to shut off an isolation valve within the pump house during excavation.

09:30 – Mr. Colangelo from the GCWD arrived to inspect the on-site water spout/valve (see photo 16). It could not be determined where the valve connected and whether or not it was live and not capped. GCWD would return Monday to locate a possible turn on valve.

10:00 - Pre-construction photos were taken at various locations throughout the site; in order to document the existing conditions of the site, prior to construction (see photos 3 through 50).

14:00 - The drums located on the north side of the building were observed. An unknown liquid was observed at the base of the drums (see photos 45-47). EnviroTrac was notified of the leak, and they indicated it would be handled as part of the drum waste characterization. The soil would be removed as part of the planned excavation activities in that area.

15:30 – YEC completed initial site survey. YEC indicated that the survey was complete, with the exception of certain portions of the site due to dangerous conditions and excessive debris.

Future Work for week ending March 19, 2010:
None.

PREPARED BY (OBSERVER)	**REVIEWED BY**
PRINT NAME: Antonio Pires	PRINT NAME: Paul Martorano
SIGNATURE:	SIGNATURE:
☒ **ADDITIONAL SHEETS USED**	
☒ emailed draft / final to CDA – date: 4/15/10	☐ hardcopy to CDA – date:

PHOTOGRAPHIC LOG
March 18, 2010
D&B JOB NO. 2582
GLADSKY MARINE SITE
GLEN COVE, NEW YORK

PHOTO #	DATE	TIME	DESCRIPTION
1	3/18/2010	7:13	YEC measuring a reference point. (SW corner across the street from the site on Garvies Point Road.
2	3/18/2010	8:23	YEC measuring elevations using a survey reference point across from man hole near to entrance of site.
3	3/18/2010	8:25	View of old building/house from the front.
4	3/18/2010	8:25	View of the location of the sanitary leaching pool.
5	3/18/2010	8:35	4 waste drums located against old building/house.
6	3/18/2010	8:43	Chain link fence located in the NE section of site.
7	3/18/2010	8:44	Wood debris located in the NE corner of the site.
8	3/18/2010	9:41	White picket fence located along Eastern side of site, along the creek.
9	3/18/2010	9:41	White picket fence, Tree and associated miscellaneous debris, running down the middle of the site (NW-NE).
10	3/18/2010	9:43	Wood debris, other misc. debris, and old dock bridge located along the Easter side of site along the creek.
11	3/18/2010	9:44	Old wood shed, and misc. debris with buckets of lubricants and other waste. (SE section of site).
12	3/18/2010	9:46	Miscellaneous and wood debris located on SE section of site.
15	3/18/2010	9:49	Miscellaneous and wood debris located on NE corner of site.
16	3/18/2010	13:45	Old water valve, located on NW part of site, near fence by Garvies Point Rd.
17	3/18/2010	13:46	Fence located on S part of site(not to be take down) and misc debris in the area.
18	3/18/2010	13:47	Fence located on S part of site(not to be take down) and misc debris in the area.
19	3/18/2010	13:48	Fence located on S part of site(not to be take down) and misc debris in the area.

PHOTOGRAPHIC LOG
March 18, 2010
D&B JOB NO. 2582
GLADSKY MARINE SITE
GLEN COVE, NEW YORK

PHOTO #	DATE	TIME	DESCRIPTION
20	3/18/2010	13:48	Fence located on S part of site(not to be take down) and misc debris in the area.
21	3/18/2010	13:49	Fence located on S part of site(not to be take down) and misc debris in the area.
23	3/18/2010	13:50	Dock entrance bridge along side small shack looking East.
24	3/18/2010	13:50	Dock entrance bridge along side small shack looking East.
25	3/18/2010	13:51	View of the dock, and all the debris on it. (Located on Glen Cove Creek)
26	3/18/2010	13:52	View of the dock, and all the debris on it. (Located on Glen Cove Creek)
27	3/18/2010	13:52	View of the dock, and all the debris on it. (Located on Glen Cove Creek)
28	3/18/2010	13:52	View of the dock, and all the debris on it. (Located on Glen Cove Creek)
29	3/18/2010	13:52	Looking west from dock on creek at shore of site , and all the debris along it.
30	3/18/2010	13:53	Looking west from dock on creek at shore of site , and all the debris along it.
31	3/18/2010	13:54	Looking west from dock on creek at shore of site , and all the debris along it.
32	3/18/2010	13:54	Sinking portion of the dock.
33	3/18/2010	13:55	debris on the dock.
34	3/18/2010	13:55	View of Dock entrance bridge looking West toward site from creek.
35	3/18/2010	13:56	View of Dock entrance bridge looking West toward site from creek.
36	3/18/2010	13:56	View of Dock entrance bridge looking West toward site from creek.
37	3/18/2010	13:57	Electrical box and cord located on dock entrance bridge.
38	3/18/2010	13:58	Portion of dock bridge up along Eastern Portion of site.
39	3/18/2010	14:00	Wood Building/House

PHOTOGRAPHIC LOG
March 18, 2010
D&B JOB NO. 2582
GLADSKY MARINE SITE
GLEN COVE, NEW YORK

PHOTO #	DATE	TIME	DESCRIPTION
40	3/18/2010	14:01	Adjacent site to the NE, possible field trailer locations and associated fencing and debris in area.
41	3/18/2010	14:01	Adjacent site to the NE, possible field trailer locations and associated fencing and debris in area.
42	3/18/2010	14:02	Adjacent site to the NE, possible field trailer locations and associated fencing and debris in area.
43	3/18/2010	14:02	Adjacent site to the NE, possible field trailer locations and associated fencing and debris in area.
44	3/18/2010	14:03	Adjacent site to the NE, possible field trailer locations and associated fencing and debris in area.
45	3/18/2010	14:05	Staining and leakage from 4 waste drums located by old building/house.
46	3/18/2010	14:05	Staining and leakage from 4 waste drums located by old building/house.
47	3/18/2010	14:05	Staining and leakage from 4 waste drums located by old building/house.
48	3/18/2010	14:06	Wood and misc. debris behind the building/shed.
49	3/18/2010	14:06	Wood Building/House
50	3/18/2010	14:07	View of the entire length of the site looking SE from the entrance.

*Please note that Date stamp on photo is a year off of actual date and Time stamp on photo is an hour behind of actual time. The times and dates on the photo log are correct.

1

2

3

4

5

6

7

8

9

10

11

12

15

16

17

18

19

20

21

23

24

25

26

27

28

29

30

31

32

33

34

35

36

37

38

39

40

41

42

43

44

45

46

47

48

49

50