7/29

- stratigraphy & structure

1952 image - Blown away soils

1971 post mining

1997 post Reclamation

2014 Recent conditions -

- Reclamation Area issues - further assessments

-

Time critical - migration - - Drainage pathway from road
~~coverate~~

- purposed areas in Removal Action are for located areas, to be further characterized for the Action

- CERCLA process
- lots of uncertainties of site conditions

- further study was Recommended

-

Ore body - background concerns - no Disturbed areas sampling "clean fill"?

~~correlation~~ correlation "R" factor was acceptable

"NORM" vs Anthropogenic —

exposure vs cover