Bible 2 Site Plan - 110511

Arrows show the direction of non-contact stormwater drainage. Barns are labeled as shown and the enclosed feed bins are located on the east end of the barns. A small nursery exists on the northeast corner of the site with a curved arrow pointing out the building from the large nursery. There is a freshwater pond shown at the south end of the barns that appears clear. No discharge was observed at the time of inspection on 05-11-11.