Attachment- A JCI Jones Photo Log 6/21/12 RMP/GDC Inspection

JCI0	Air Compressor
JCI1	Bleach Machine
JCI2	ER Gear
JCI3	50 % Sodium Hydroxide Tank
JCI4	Hypochlorite Solution Tanks 12.5%
JCI5	ER Shutoff
JCI6	Cylinder Room
JCI7	New/Reconditioned Valve Station
JCI8	Railcar Closure System
JCI9	ER Shutoff
JCI10	Detector railcar
JCI11	Railcar with loading rack
JCI12	Railcar with automatic shutoff



161-8



10 1-1

EMERGENCY RESPONSE GEAR
SAFETY LOCK-OUT CENTER
LOCK OUT TAG OUT SUPPLIES
CON POOL KIT
SCBA'S
KITS
2012/06/21 07:25AM

JCI-2



10 1-2



101-4



IC1-5

2012/06/21 07:36AM

JCI
MILFORD
2012/06/12 07:38AM



JC-1-8

10-1-9

2012/06/21 08:03AM


DOT 105 J 500 W
TANK QUALIFICATION
THICKNESS TEST
SERVICE EQUIPMENT
PRD: VALVE
LINING
CHLORINE
INHALATION
HAZARD
2012/06/21 08:07AM

.1(P.1-11



10-1-12