APPENDIX D

Site Photographs – Excavation



1. 7/20/06 – NWC boring NWC-X-39, prior to excavation, looking northwest.

2. 7/20/06 – Excavation of upper 2 feet, looking northeast. Note barrier wall on right.

3. Northwest corner of NWC excavation, looking northwest, showing deeper excavation to 5 feet.

4. Excavation, looking northeast from southwest corner. Note areas of deeper excavation to 5 feet. Note barrier wall on east side of excavation.

5. 7/21/06 – Excavation looking southeast from northwest corner. Note barrier wall on east side of excavation.

6. 7/21/06 – Excavation complete to 5 feet, looking northeast. Concrete pile in left foreground.

7. 7/21/06 – Stockpiled soil from NWC excavation (to be disposed of off site).

8. 7/21/06 – NWC after excavation and backfill.

9. 7/21/06 – Backfill and compaction of northwest corner using vibratory roller.