LEASE FACILITY INSPECTION REPORT

DNR/Office of Conservation

SRCN996
0

Serial Num 44904 **Date** November 12, 2013	**Operator** Texaco, Inc. **Id** 5878
Lease Name SHE 9300 STR RA SU;KURZWEG U1 # 005	**Address** 4800 Fournace Place
Section: 023 **Township:** 06S **Range:** 07E	Bellaire , TX 77401-2324
Parish POINTE COUPEE	**Phone**
Field Sherburne Id: 8107	**Contact** Vicki Duncan

A. INSPECTION REASON

Periodic **Complaint #:** **Order #:**

B. FACILITY TYPE

Single Lease **Commingled:** N **Permit no.** **Oil:** N **Gas:** N **Both:** N

C. WELL SITE

1. **IDENTIFICATION:** Passed
2. **CONDITION:** Deficiency

Violation(s): Debris At Ws

Violation(s):

Well Site Comments: Well was plugged and abandoned but, site clearance was not performed.

D. TANK BATTERY

1. **IDENTIFICATION:** Passed

Violation(s):

2. **CONTAINMEN** Passed **Type:** **Reference well:**

Violation(s):

3. **BLEEDERS** **Exist:** N/A Passed

Violation(s):

4. **PIPELINE SALES VALVES:** Passed **Transporter:**

Violation(s):

5. **B S & W VALVES:** Passed

Violation(s):

6. **MECHANICAL ARRANGEMENT:** Passed

Violation(s):

7. **STRUCTURAL INTEGRITY OF STORAGE TANKS** Passed

Violation(s):

LEASE FACILITY INSPECTION REPORT

DNR/Office of Conservation

SRCN996
0

8. VENTING OF STORAGE TANK Passed

Violation(s):

Tank Battery Comments:

E. FIRE HAZARD Passed

Violation(s):

Fire Comments:

F. DISCHARGE OF E&P Passed

Violation(s):

Discharge Status:

Discharge Comments:

G. DISPOSITION OF E&P

Site Id: **Permit No:**

H. EXISTENT PITS: No **I. NO. OF WELLS ON LEASE:**

REMARKS:

THE OPERATOR'S REPRESENTATIVE SHALL SIGN THIS REPORT TO ACKNOWLEDGE RECEIPT OF HIS COPY, YOUR SIGNATURE CANNOT BE CONSTRUED AS AN ADMISSION OF GUILT FOR ANY VIOLATIONS CONTAINED IN THIS REPORT.

No Witness November 12, 2013 **IN COMPLIANCE** **No** **Sealed:** N
Operator's Representative

KEITH MARKS November 12, 2013
Conservation Enforcement Agent

Sonris Id: 2679

Latitude (Deg/Min/Sec:) 30 31 57.3 Longitude (Deg/Min/Sec:) 91 43 19.8 GPS Position: NW

LEASE FACILITY INSPECTION REPORT

DNR/Office of Conservation

SRCN996
0

Subject: **debris**

Photo File Name: F1224633678/007.JPG

Subject: **debris**

Photo File Name: F1861192778/009.JPG

Subject: **debris**

Photo File Name: F1364086197/008.JPG