United States Environmental Protection Agency

Digital Image Log

1. Case Number: 02DM17	2. Inspector Name: Dean Maraldo		
3. Date(s) of Inspection: 9/12/17 - 9/13/17	4. Company/Facility Name: US Steel Minntac Tailings Basin		
5. Street Address of Digital Images: County Road 102	6. City: Mountain Iron	7. State: MN	8. Zip: 55768
9. Image Numbers: USSM 252-264	10. File Name (if any):		

Digital Image Number	Sample Number (if any)	Description of Digital Image	Date and Time Digital Image Taken
USSM 252	NA	CALIB. STANDARDS	9/12/17 0918
253	S01	Seep A N47.57985, W92.68961	9/12/17 0952
255 ~~254~~ 9/13/17 dm	S01	" " Sample Bottles	9/12/17 0959
256	S02	Dark River pond seep N47.56834, W92.68606	9/12/17 1022
257	S02	" Sample Bottles	9/12/17 1024
258	S03	Seep 3 (Hatch) N47.59813, W92.68136	9/12/17 1046
259	S03	" " Sample Bottles	9/12/17 1053
260	S04/DOS	SD001 (Seep 4 Hatch) ~~N47.5~~ N47.59878 W92.67989	9/12/17 1107
261	S04/DOS	" " Sample Bottles Dmaldo	9/12/17 1111
262	S06	Seep 7 (Hatch) N47.61200, W92.68116	9/12/17 1126
263	S06	" " Sample Bottles	9/12/17 1131
264	S07	Seep 13 (Hatch) N47.62307, W92.68063	9/12/17 1146

(2 of 4)

United States Environmental Protection Agency

Digital Image Log

1. Case Number: 02DM17	2. Inspector Name: Dean Maraldo		
3. Date(s) of Inspection: 9/12/17 - 9/13/17	4. Company/Facility Name: US Steel Minntac Tailings Basin		
5. Street Address of Digital Images: County Road 102	6. City: Mountain Iron	7. State: MN	8. Zip: 55768
9. Image Numbers: USSM 265 - 276	10. File Name (if any):		

Digital Image Number	Sample Number (if any)	Description of Digital Image	Date and Time Digital Image Taken
USSM 265	S07	Seep 13 (Hatch) Sample Bottles	9/12/17 1152
266	S08	Area 11 Pond (USS Backcleaner) N47.55625 W92.60082	9/12/17 1358
267	S08	" Sample Bottles	9/12/17 1404
268	S09	CB-12 sample bottles	9/12/17 1503
269	S09	" Seep Pool (OUTSIDE) N47.61222, W92.61440	9/12/17 1504
270	—	CB-12 SHEETPILE OUTSIDE, LOW SHEETPILE	9/12/17 1505
271	—	" " "	9/12/17 1505
272	S10	CB-12 In Basin 10' near south well N47.61234, W92.61449	9/12/17 1513
273	S10	" " " Sample Bottles	9/12/17 1521
274	—	CB-11 Sheetwall Note holes	9/12/17 1543
275	—	CB-5 OUTSIDE SHEET PILE N47.59992, W.92.60999	9/12/17 1605
276	—	CB-5 INSIDE SHEET PILE N47.59991, W 92.60999	9/12/17 1604

(3 of 4)

United States Environmental Protection Agency

Digital Image Log

1. Case Number: 02DM17	2. Inspector Name: Dean Maraldo		
3. Date(s) of Inspection: 9/12/17 - 9/13/17	4. Company/Facility Name: US Steel Minntac Tailings Basin		
5. Street Address of Digital Images: County Road 102	6. City: Mountain Iron	7. State: MN	8. Zip: 55768
9. Image Numbers: USSM 277 - 288	10. File Name (if any):		

Digital Image Number	Sample Number (if any)	Description of Digital Image	Date and Time Digital Image Taken
USSM 277	S11	CB-S North end of Sheetpile	9/12/17 1605
278	S11	CB-S OUTSIDE Sheetpile, due east of inlet	9/13/17 0945
279	S11	" Sample Bottles	9/13/17 0945
280	S12	CB-S Catch basin near inlet, 1' off wall	9/13/17 0947
281	S12	CB-S " Sample Bottles	9/13/17 0951
282	S13	CB-S Northend of Sheetpile	9/13/17 0952
283	S13	CB-S Sample Bottles	9/13/17 0957
284	S14	DARK RIVER POND Sample Location N47.55915 W92.67916	9/13/17 1021
285	S14	" Sample Bottles	9/13/17 1024
286	—	DARK RIVER POND	9/13/17 1026
287	—	Swale Downstream of Dark River Pond	9/13/17 1032
288	S15	Timber Creek Sample Location N47.56624 W92.67951	9/13/17 1107

United States Environmental Protection Agency

Digital Image Log

1. Case Number: 02DM17	2. Inspector Name: Dean Maraldo		
3. Date(s) of Inspection: 9/12/17 - 9/13/17	4. Company/Facility Name: US Steel Minntac Tailings Basin		
5. Street Address of Digital Images: County Road 102	6. City: Mountain Iron	7. State: MN	8. Zip: 55768
9. Image Numbers: USSM 289 - 291	10. File Name (if any):		

Digital Image Number	Sample Number (if any)	Description of Digital Image	Date and Time Digital Image Taken
289	S15	Timber Creek Sample Bottles	9/13/17 1111
290	S15	Timber Creek Sample Bottles w/ Field Jar + Pole	9/13/17 1116
291	R16	Field Blank Sample Bottles + Dt water	9/13/17 1254