Export To Excel

Project Number	Project Name	Type of Need	Reasons for Need	NRHE	C/F	Reg/Sec	Design Cap.	Diameter	Length	Number Needed	Cost Estimate	Date of Cost	Doc.
1000	Well Rehabilitation #3, #13, & $20	R2	A1	N	C	4A	1.44 MGD			1			6, 10
1001	Well Rehabilitation #14, #15, #16, #18, #22	R2	A1	N	C	4A	1.58 MGD			1			6, 10
1002	Well Rehabilitation #9	R2	A1	H	F	4A	0.86 MGD			1			6, 10
1003	Well Rehabilitation #12	R2	A1	H	F	4A	1.08 MGD			2			6, 10
1004	Well Rehabilitation #19, #21	R2	A1	H	F	4A	1.72 MGD			1			6, 10
1005	Well Rehabilitation #11	R2	A1	H	F	4A	1.8 MGD			1			6, 10
1006	Well Rehabilitation #17	R2	A1	H	F	4A	3.1 MGD			1			6, 10
1007	Aerator at Plant #1	T33	A6, A7	H	F	1H, 2A	7.9 MGD			1			6, 10
1008	Rehab Plant #1	T10	A6, A7	H	F	1H, 2A	5 MGD			1			6, 10
1009	Aerator at Plant #2	T33	A6, A7	H	F	1H, 2A	5 MGD			1			6, 10
1010	Rehab Plant #2	T10	A6, A7	H	F	1H, 2A	5 MGD			1			6, 10

1011	Groundwater Treatment for Well #11	T22	A6	H	F	1H , 2A	5 MGD			1			6 , 10
1012	Groundwater Treatment for Well #12	T22	A6	H	F	1H , 2A	5 MGD			1			6 , 10
1013	Groundwater Treatment for Well #16	T22	A6	H	F	1H , 2A	5 MGD			1			6 , 10
1014	Booster #1 Chlorinator	T1	A6	H	F	1H	1.72 MGD			1			6 , 10
1015	Booster #2 Chlorinator	T1	A6	H	F	1H	2.88 MGD			1			6 , 10
1016	In-Line Booster Station Chlorination	T1	A6	H	F	1H	4.32 MGD			1			6 , 10
1017	28th Avenue Pumping Station	P2	A1	H	F	4A	4.32 MGD			1			6 , 10
1018	Lincoln Rd Pumping Station	P2	A1	H	F	4A	0.72 MGD			1			6 , 10
1019	Booster #1	P2	A1	H	F	4A	1.72 MGD			1			6 , 10
1020	Booster #2	P2	A1	H	F	4A	2.88 MGD			1			6 , 10
1021	Ralston Road Pumping Station	P2	A1	H	F	4A	0.36 MGD			1			6 , 10
1022	Country Club Pumping Station	P2	A1	H	F	4A	0.36 MGD			1			6 , 10
1023	Rehab USM, Weatherby, Industrial Elevated Tanks	S1	A1	H	F	4A	1 MG			3			6 , 10

1024	Rehab Industrial Park, Lincoln Rd. Elevated Tanks	S1	A1	H	F	4A	0.5 MG			2			6,10
1025	Rehab Forrest General Tank	S1	A1	H	F	4A	0.75 MG			1			6,10
1026	Rehab Richburg Hill Elevated Tank	S1	A1	H	F	4A	0.15 MG			1			6,10
1027	Rehab Turner and Old Johnson Pressure Tanks	S3	A1	H	F	4A	0.005 MG			2			6,10
1028	Rehab Plant #1 backwash tank	S2	A1	H	F	4A	2.88 MG			1			6,10
1029	Rehab Richburg Hill Collector	S2	A1	H	F	4A	2.5 MG			1			6,10
1030	Rehab Plant 1 Clearwell	S2	A1	H	F	4A	5 MG			1			6,10
1031	Rehab Plant 2 Clearwell	S2	A1	H	F	4A	2.5 MG			1			6,10
1032	Install Iron Treatment to Existing Well	T10	A6,A7	H	C	1H,2A	2.16 MGD			1	$2,453,000.00	2/11/2009	5,6,10
2000	Distribution Improvements on Bouie and Mobile St	M1	A1	R	C	4A					$1,113,750.00	2/11/2009	5,6,10
2001	Distribution Improvements on Classic & Ed Turner R	M1	A1	R	C	4A					$529,150.00	2/11/2009	5,6,10
3000	Water Meter Replacement	S1	A1	R	F	4A		0.75		16500			6,10