Export To Excel

Project Number	Project Name	Type of Need	Reasons for Need	NRHE	C/F	Reg/Sec	Design Cap.	Diameter	Length	Number Needed	Cost Estimate	Date of Cost	Doc.
1000	Rehabilitation of Well #1 & 5	R1	A1	H	F		0.58 MGD			1			10
1001	Rehabilitation of Well #2	R1	A1	H	F		0.83 MGD			1			10
1002	Rehabilitation of Well #3 & #6	R1	A1	H	F		0.96 MGD			1			10
1003	Rehabilitation of Well #4	R1	A1	H	F		0.64 MGD			1			10
1004	Rehabilitation of Well #7	R1	A1	H	F		0.84 MGD			1			10
1005	Rehabilitation of Well #8	R1	A1	H	F		1 MGD			1			10
1006	Rehabilitation of Well #9 & #13	R1	A1	H	F		1.05 MGD			2			10
1007	Rehabilitation of Well #10	R1	A1	H	F		1.02 MGD			1			10
1008	Rehabilitation of Well #11	R1	A1	H	F		0.92 MGD			1			10
1009	Rehabilitation of Well #12	R1	A1	H	F		1.03 MGD			1			10
1010	Rehabilitation of Well #14	R1	A1	H	F		1.25 MGD			1			10
1011	Rehabilitation of Well #15	R1	A1	H	F		1.36 MGD			1			10

1012	Rehabilitation of Well #16	R1	A1	H	F		1.47 MGD			1			10
1013	Rehab Plant Aerators at Plant 1 & 2	T33	A6	H	F	1D,2B	3.6 MGD			2			6,10
1014	Rehab Plant Aerator at Plant 3	T33	A6	H	F	1D,2B	7.2 MGD			1			6,10
1015	Rehab of Corrosion Control Treatment Plants 1 & 2	T22	A6	H	F	1D,2B	3.6 MGD			2			6,10
1016	Rehab of Corrosion Control Treatment Plants 3	T22	A6	H	F	1D,2B	3.6 MGD			2			6,10
1017	Rehab Treatment Plant 1 Clearwell	S2	A6	H	F	1D,2B	0.5 MG			1			6,10
1018	Rehab Treatment Plant 2 Clearwell	S2	A6	H	F	1D,2B	1.5 MG			1			6,10
1019	Rehab Treatment Plant 3 Clearwell	S2	A6	H	F	1D,2B	0.25 MG			1			6,10
1020	Rehab Finished Ground Water Storage Tank	S2	A1	H	F	4A	0.5 MG			1			6,10
1021	Rehab Elevated Storage Tank - Airport & Mar-Ree	S1	A1	H	F	4A	0.2 MG			2			6,10
1022	Rehab Elevated Storage Tank 12th Street	S1	A1	H	F	4A	0.5 MG			1			6,10
1023	Rehab Elevated Storage Tank Northview	S1	A1	H	F	4A	1 MG			1			6,10
1024	Rehab Service Pumps at Plant #1	P1	A1	H	F	4A	1.08 MGD			2			6,10

1025	Rehab Service Pumps at Plant #1	P1	A1	H	F	4A	1.44 MGD			1			6, 10
1026	Rehab Service Pumps at Plant #2	P1	A1	H	F	4A	4.6 MGD			3			6, 10
1027	Rehab Service Pumps at Plant #2	P1	A1	H	F	4A	2.16 MGD			2			6, 10
1028	Rehab Service Pumps at Plant #3	P1	A1	H	F	4A	1.73 MGD			3			6, 10
2000	Carter Avenue Area Improvements	M1	A1	R	C	4A					$760,491.00	9/1/2011	2
2001	Broadmoor Drive Waterline Improvements	M1	A1	R	C	4A					$135,502.00	9/1/2011	2
2002	Flowers Drive Area Improvements	M1	A1	R	C	4A					$240,582.00	9/1/2011	2
2003	3rd Avenue Waterline Improvements	M1	A1	R	C	4A					$279,457.00	9/1/2011	2
2004	St. Elmo Street Area Improvements	M1	A1	R	C	4A					$341,269.00	9/1/2011	2
2005	15th and 16th Avenue Area Improvements	M1	A1	R	C	4A					$304,321.00	9/1/2011	2
2006	East 11th Street Area Improvements	M1	A1	R	C	4A					$398,566.00	9/1/2011	2
2007	17th and 18th Avenue Area Improvements	M1	A1	R	C	4A					$488,921.00	9/1/2011	2
2008	Jarvis Street Area Improvements	M1	A1	R	C	4A					$179,589.00	9/1/2011	2
2009	Roberts Street Area Improvements	M1	A1	R	C	4A					$309,545.00	9/1/2011	2

2010	Magnolia Street Area Improvements	M1	A1	R	C	4A					$249,308.00	9/1/2011	2
2011	South 6th Avenue Area Improvements	M1	A1	R	C	4A					$332,572.00	9/1/2011	2
2012	Lee Street Area Improvements	M1	A1	R	C	4A					$148,016.00	9/1/2011	2
2013	Industrial Boulevard Waterline Improvements	M1	A1	R	C	4A					$449,531.00	9/1/2011	2
3000	Water Meters Replacement	M8	A1	R	F	2B		0.75		987			10