Export To Excel

| Project Number | Project Name | Type of Need | Reasons for Need | NRHE | C/F | Reg/Sec | Design Cap. | Diameter | Length | Number Needed | Cost Estimate | Date of Cost | Doc. |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | | | | | | | | | |
| 1000 | REHAB WELL #1 | R1 | A1 | H | F | 4A | 1.44 MGD | | | 1 | | | 6, 10 |
| 1001 | REHAB WELL #3 | R1 | A1 | H | F | 4A | 0.72 MGD | | | 1 | | | 6, 10 |
| 1002 | REHAB WELL #4 & #5 | R1 | A1 | H | F | 4A | 1.22 MGD | | | 2 | | | 6, 10 |
| 1003 | REHAB PLANT #1 | T22 | A6 | H | F | 1D, 2B | 5.04 MGD | | | 1 | | | 6, 10 |
| 1004 | Rehab Plant Aerator | T33 | A6 | H | F | 1D, 2B | 5.04 MGD | | | 1 | | | 6, 10 |
| 1005 | REHAB GROUND TANK #1 | S2 | A1 | H | F | 4A | 0.2 MG | | | 1 | | | 6, 10 |
| 1006 | REHAB ELEV. TANK #1 | S1 | A1 | H | F | 4A | 0.5 MG | | | 1 | | | 6, 10 |
| 1007 | REHAB ELEV. TANK #2 | S1 | A1 | H | F | 4A | 0.2 MG | | | 1 | | | 6, 10 |
| 1008 | Service Pumps set 1 | P1 | A1 | H | F | 4A | 1.37 MGD | | | 2 | | | 6, 10 |
| 1009 | Service Pumps set 2 | P1 | A1 | H | F | 4A | 1.44 MGD | | | 2 | | | 6, 10 |
| 2000 | Mariana Water Distribution Project | M1 | A9 | E | C | 4A | | | | | $3,126,600.00 | 5/21/2009 | 2, 8 |
| 3000 | Replacement of Existing Water Meters | M8 | A1 | R | F | 4A | | 0.75 | | 357 | | | 6, 10 |