SITE INVESTIGATION REPORT
FOR
DRUMRIGHT SPILL SITE
DRUMRIGHT, CREEK COUNTY, OKLAHOMA

May 6, 1998

Prepared for:

Henry Thompson, Jr.
Project Officer
Program Management Branch
EPA Region 6

Contract Number: 68-W6-0013

ecology and environment, inc.
International Specialists in the Environment

1999 Bryan Street, Dallas, Texas 75201
Tel: (214) 220-0318, Fax: (214) 855-1422

recycled paper

TABLE OF CONTENTS:

		Page
1.0	Introduction	1
2.0	Background	2
2.1	Site Description	2
2.2	Site History	3
2.3	Previous Investigations	4
3.0	Geology	5
4.0	Hydrogeology	6
5.0	Actions Taken	6
5.1	Seep / Creek Inspection	6
5.2	Possible oil Field Influences	7
5.3	Aerial Photography	8
5.4	Ground Conductivity Survey	8
5.5	Soil Coring / Sampling	8
5.6	Site Mapping	9
5.7	Ownership Abstract	9
6.0	Final Observations	10
6.1	Tiger Seep	10
6.2	Tributary Seep	12
7.0	Remedial Alternatives	13
7.1	Excavation and Off-Site Disposal	13
7.2	In-Situ Containment and Extraction of Free Product	13
7.3	On-Site or Off-Site Biodegradation	14
7.4	Bioventing	15
	Attachments	17
	References	18