SEMS DocID 668361

CHAIN OF CUSTODY RECORD

SPECTRUM ANALYTICAL

Page 1 of 1

Special Handling:
- ☐ Standard TAT - 7 to 10 business days
- ☒ Rush TAT - Date Needed: 12/18/98
- All TATs subject to laboratory approval; min. 24 hour notification needed for rushes.
- Samples disposed of after 60 days unless otherwised instructed.

Report To: OSC TONY BANG
SITE FAX 207-929-6169
SITE PHONE 207-929-6167
Project Mgr.:

Invoice To: JOE COLEMAN
IT GROUP
SITE PHONE (207) 929-6162
P.O. No.: 98878 RQN.

Project No.: ROGERS FIBRE MILL
Site Name: 777387
Location: BAR MILL State: ME
Sampler(s): P. BANZA

1=4°C 2=HCl 3=H_2SO_4 4=HNO_3 5=NaOH 6=MeOH 7= ICE

DW=Drinking Water GW=Ground Water WW=Waste Water
SO=Soil SL=Sludge O=Oil X1= X2=

G=Grab C=Composite

Lab Id:	Sample Id:	Date:	Time:	Type	Matrix	Preservative	pH	# Of VOA Vials	# Of Amber Glass	# Of Clear Glass	# Of Plastic	VOC	SVOC	PCB	TOC	RCRA 9 Total Metals				Notes:
AB 25224	358	12/15/98	14:15	G	SO	7		1	2			X	X	X		X				NE Turbine
AB 28225	359	12/15/98	14:20	G	SO	7		1	2			X	X	X		X				SW Turbine
AB																				
AB																				
AB																				
AB																				
AB																				
AB																				NO RES
AB																				
AB																				

Containers: # Of VOA Vials, # Of Amber Glass, # Of Clear Glass, # Of Plastic

Analyses: VOC, SVOC, PCB, TOC, RCRA 9 Total Metals

Additional Instructions:

☒ Faxresults when available to (207) 929-6169

Relinquished By: Reynaldo Ryan 12/15/98 1:00 PM
FED EX AIRBILL #
80929 2337490

Received By: Joe Kozik

Date: 12-16-98 Time: 10AM


Field Map
363
362
359
360
361
358
Turbine Room
Water Filled Chamber
Building 1
364
365
366
Building 3
Approximate Area of Structure Collapse
Water Tower
Stack
Depot