NYD980508147

FILE COPY

PRELIMINARY ASSESSMENT REVIEW FORM

SITE NAME ~~Site Name~~: DOVER LANDFILL #1

AKA ~~Alaises~~ SITE NAME: DOVER LF

COMPLETED

Address: Rt. 22 Across from Grand Union

City: DOVER County: _____ State: NJ__ NY ✓

___ Puerto Rico
___ Virgin Islands

Priority Rating Given By Contractor: ✓ low ___ medium ___ hi

What do you think: ✓ agree ___disagree

If disagree, why?

Other Comments:
- Landfill is not fenced off.
- Potential exist for groundwater and soil contamination due to high permeability of cover material and the nature of the underlying strata
- Potential for drinking H_2O may exist due to the closeness of the public well from resident

Final Rating: ✓ low ___medium ___high ___ NONE

Your Name: Carolyn Kwan Date: 10/22/85

11/25/85 - Concur w/ Reviewer's comments.. low priority w/ SI on a time available basis

P. Kelly

310038