DECLASSIFIED
jh
Type text here
6/1/22
Initials/Date

CONFIDENTIAL

COMPLETED

FILE COPY

SITE INSPECTION REVIEW FORM

SITE NAME: Emerson Street LF

ALIASES:

SITE I.D.#: NYD 980532477

ITEM	COMPLETE ? YES	NO*
SITE LOCATION (INCLUDING MAP)	___	___
SITE BACKGROUND	___	___
ENVIRONMENTAL SETTING (GEOLOGY, HYDROLOGY, METEOROLOGY, ECOLOGY + LAND USE)	___	___
WASTE DESCRIPTION (PRESENCE + CONDITION OF WASTE + WASTE MANAGEMENT UNITS)	___	___
LABORATORY RESULTS (CORRELATED TO SAMPLE LOCATION MAP)	___	___
HRS PRE - SCORE (PRELIMINARY + PROJECTED)	___	___
POTENTIAL FOR DIRECT CONTACT	___	___
CONCLUSIONS + RECOMMENDATIONS	___	___
REFERENCES	___	___

HRS PRE-SCORE: PRELIMINARY SCORE = _____

PROJECTED SCORE = _____

314468

COMMENTS:

This is a 230 Acre inactive LF located within a commercial + residential area in Rochester, N.Y. Site operated from 1930-71 for disposal of muni trash. Alleged low-level radioactive waste was disposed of at site. Also, ~~including~~ industrial wastes were disposed of.

Estimate between 3-10 ~~K~~ people living within 4 miles

Site scored relatively Low on old HRS 6.09

Would Need State to Re-evaluate site ~~under~~ under HRS-II + ship back to EPA

NFRAP

REVIEWED BY: Ben Cometta DATE: 6/27/90

*IF ANY ITEM IS LACKING INFORMATION PLEASE DESCRIBE IN COMMENTS