WEEKLY STATUS REPORT

Prepared By: Patrick Rubenbauer

BCP Project No.:	C224099	EPA Consent Order No.:	CERCLA-02-2017-2021	Date:	12/13/2019
Project Name:	BRT Powerhouse 153 2nd Street AKA 322 3rd Avenue, Brooklyn, NY 11215				

Remediation Activities (Week of December 9, 2019):

- No remediation activities took place during this reporting period.

Redevelopment Activities (Week of December 9, 2019):

- Maspeth Welding (Site steel contractor) continued steel repair work in the turbine hall.
- Domani and Garden State Surveying, Engineering, and Planning (Site survey contractors) continued site surveying work as necessary.
- Structure Tech continued installation of utilities at the boiler house structure.
- Structure Tech installed waterproofing at the boiler house walls.
- Northeast Demolition (Site demolition contractor) continued selective demolition work inside turbine hall. Demolition debris was loaded into roll-off containers for disposal.
- US Spray (Site steel contractor) continued scraping steel inside turbine hall.

Planned Activities for next week:

- Continue steel repair work in the turbine hall.
- Continue selective demolition work in the turbine hall.
- Continue the boiler house superstructure construction scope including utility installation, wall formwork construction, and concrete pours.

Photo Log

Photo 1 – Looking northeast in the east driveway. Drums staged in the driveway for future disposal.	
Photo 2 – Looking east. Structure Tech continues construction of boiler house superstructure.	
Photo 3 – Looking southeast. Structure Tech installed waterproofing along the boiler house walls.	

- Fill Stockpile
- Demolition
- Geotechnical Test Pits
- Excavation
- Steel Work
- Installed SOE
- Foundation Work
- Seepage Basin