SH 10-20-89 ~~8966 07 07~~
8811-22-14

# Recon/SI Tracking Form

12/20/88 PFE
Date

SEMS DocID 2334610

Site Name Gulf Oil Darby Creek Tank Farm
TDD No. F3-8811-22
Dump Site No. PA-788
Section Supervisor [redacted]
Site Leader
Recon Field Work Date 12/7/88

Recon Findings: The site was formerly a rock quarry. It was filled in with waste materials from the refinery, including listed materials K049, K051, K052, corrosive wastes (D002), including hydrofluoric acid contaminated materials, and oily sludges possibly containing lead and chromium. Materials were deposited on site from 1949-1979. The site now operates as a tank farm for the storage of crude oil for Chevron oil.

SIO [redacted] Date Contacted 12/20/88

Telecon Notes:

I told [redacted] that the rough HRS score for the subject site is 7.57 for the prescore and 7.72 for the proscore. I also stated that there were no private or municipal wells within 3 miles of the site. [redacted] Said that since there were no targets and it had such a low score, that ~~so~~ there would be no further action at the site.

Site Inspection yes (no)
Sampling Plan Due Date N/A
Recon Report Due Date 2-10-89 TF
SI (Tentative Field Date) N/A

[redacted]
Site Leader 12/20/88
Date

[redacted]
Section Supervisor 12/20/88
Date

Original: TDD file
Copies: [redacted]