ENVIRONMENTAL PROTECTION AGENCY STATE OF ILLINOIS

RECEIVED NOV 01 1985 IEPA-DLPC

D 2

L P C F C 0 5 5 C
(1) (8) (9)

OBSERVATION REPORT - SITE INVENTORY NO. _ _ _ _ _ _ _ _
(11) (18)

Cook CO. - L.P.C. Region # N Date 9/10/85
(20) (25)

Chicago / IC Letter Sent (Yes or No) N
(Location) (Responsible Party) (26)

Samples Taken: Yes ( ) No (X) Time: From 15:00 Pm Weather Overcast
Ground Water( ) Surface( ) Other( ) To 15:10 Pm
Photos Taken: Yes ( ) No (X) Interviewed no Inspector E S L
(27) (29)

Previous Inspection None Previous Correspondence None Site Open: Yes( ) No( )

OPERATIONAL STATUS:		TYPE OF OPERATION:				AUTHORIZATION:	
Operating	( )	Landfill	( )	Storage	( )	E.P.A. Permit	( )
Temporarily Closed	( )	Random Dump	( )	Salvage	( )	Variance	( )
Closed Not Covered	( )	Other _____	( )	A.C.D.	( )	21(e)	( )
Closed and Covered	( )	Quantity Received Daily(1-6)		_____ (30)		Board Order	( )
						Illegal (5)	( )
						Apparent Non-Compliance (5)	( )

IMPROVED

DETERIORATED

31

I S or D _____ (62)

US EPA RECORDS CENTER REGION 5
447439

GENERAL REMARKS:

See attached Memo

INTERVIEW:

DIAGRAM:



IL 532-0309 LPC 04 Rev. 8/82

ILLINOIS ENVIRONMENTAL PROTECTION AGENCY

R VED
NOV 0 1 1985
IEPA-DLPC

MEMORANDUM

TO: Superfund file

DATE: 9-26-85

FROM: E. Lin

☒ Information only

SUBJECT: SIte inspection at IC Tracks & 119th st. Chicago, Cook County
Chicago / 119th st. & IC Tracks
Superfund / PA

☐ Response requested

A site inspection was conducted on 9/10/85. The visited site is located at the intersection of a dead end residential street (119th) and IL Central rail road tracks. At the time of inspection, No evidence of hazardous waste was observed.

No information is available in the Maywood office. IC was contacted on 9/19/85, no information was available related to the subject site either.

Based on the current condition of the site, the priority for inspection is commended as none.

IL 532-0571
EPA 90A 6/75