279.44.08 5/3/99
Clear/Sunny

1030 MEB onsite to collect Monthly Water levels.

| Well | W.L | Time | |
|---|---|---|---|
| MW210 | 23.02 | 1043 | |
| MW203 | 20.72' | 1045 | |
| MW P-211 | 4.56' | 1050 | |
| MW209 | 5.27' | 1052 | |
| MW212 | 19.96' | 1055 | |
| Small Pond | 3.02 | 1059 | |
| MW101A | 15.45 | 1100 | |
| LAKE | 1.52' | 1102 | |
| Large Pond | 1.34' | 1105 | |
| MW204 | 13.37' | 1107 | |
| MW202 | 23.55' | 1114 | |
| MW208 | 23.85 | 1116 | |
| MW102 | 7.77' | 1125 | New Lock |
| MW103 | 6.62' | 1126 | |
| MEB MW201 | 5.06' | 1130 | Replaced Lock |
| MW206 | 5.91' | 1132 | |
| MW207 | 6.12' | 1135 | |

1140 MEB offsite return to Payne Firm.



279.44.08
6/3/99

1035 MEB onsite to measure water levels

| Well | W.L. | Time | |
|---|---|---|---|
| MW204 | 14.49' | 1040 | No lock/Replace. |
| Small Pond | Dry | 1041 | |
| MW101A | 16.83' | 1044 | Lock cut/Replace |
| LAKE | 3.33' | 1050 | |
| Large Pond | 3.14' | 1054 | |
| P-211 | 5.77' | 1100 | |
| MW209 | 6.39 | 1103 | |
| MW212 | 21.05' | 1105 | |
| MW203 | 21.84' | 1111 | |
| MW210 | 24.14' | 1114 | |
| MW202 | 24.70' | 1116 | |
| MW208 | 25.09' | 1120 | |
| MW102 | 9.31' | 1124 | |
| MW103 | 8.15' | 1127 | |
| MW201 | 6.57' | 1131 | |
| MW206 | 7.39' | 1133 | |
| MW207 | 7.46' | 1137 | |

1145 MEB offsite.

[signature]

US EPA RECORDS CENTER REGION 5
489904

279.44.08 Clear/Hot 92°

7/6/99

0970 MEB onsite to collect water levels

| Well | W.L. | Time |
|---|---|---|
| MW102 | 9.60 | 932 |
| MW103 | 8.44' | 936 |
| MW201 | 6.85' | 938 |
| MW206 | 6.69' | 941 |
| MW207 | 7.87 | 944 |
| MW208 | 25.59' | 951 |
| MW202 | 25.21 | 0954 |
| MW ~~203~~ 210 | 24.61 | 0957 |
| MW203 | 22.29' | 1000 |
| MW204 | 14.93' | 1006 |
| Small Pond | Dry | 1007 |
| MW101A | 17.22' | 1010 |
| LAKE | 3.61' | 1013 |
| Large Pond | 3.26' | 1016 |
| P-211 | 6.32' | 1023 |
| MW209 | 6.73' | 1025 |
| MW212 | 21.40' | 1028 |

1035 MEB offsite

[illegible]



279.44.08 Clear/Hot 87°

8/4/99

0919 MEB onsite to collect water levels

| Well | W.L. | Time |
|---|---|---|
| MW210 | 25.20' | 0922 |
| MW203 | 22.86' | 0929 |
| MW204 | 15.52' | 0932 |
| Small Pond | Dry | 0934 |
| MW101A | 17.77' | 0936 |
| LAKE | 4.20' | 0940 |
| Large Pond | Dry | 0949 |
| P-211 | 6.92' | 0951 |
| MW209 | 7.27' | 0953 |
| MW212 | 21.97' | 0958 |
| MW202 | 25.81' | 1007 |
| MW208 | 26.19' | 1009 |
| MW102 | 10.11 | 1022 |
| MW103 | 8.96' | 1026 |
| MW201 | 7.44 | 1032 |
| MW206 | 8.30 | 1037 |
| MW207 | 8.45 | 1045 |

- Survey markers along property (Easement)
- MEB runs grass around wells on MCO property.

1050 MEB off site.

279.44.08

Overnight

9/7 MEB onsite to collect W.L.

| Well | W.L. | Time | |
|---|---|---|---|
| MW200 | 25.83 | 947 | Replaced Lock |
| MW203 | 23.50 | 950 | |
| MW212 | 22.54 | 954 | |
| P-211 | 7.68 | 958 | |
| MW209 | 7.84 | 1000 | |
| MW204 | 16.12 | 1005 | |
| Small Pond | Dry | 1007 | |
| MW101A | 18.37' | 1009 | |
| LAKE | 4.90 | 1011 | Water below [illegible] Estimated value |
| Large Pond | Dry | 1017 | |
| MW208 | 26.87 | 1020 | |
| MW202 | 26.47 | 1028 | Replaced lock |
| MW102 | 10.73 | 1036 | |
| MW201 | 8.10 | 1041 | |
| MW206 | 9.00 | 1043 | |
| MW207 | 9.18 | 1046 | |

11:00 MEB offsite

* MW103 19.58 Equipment did not write down reading.



279.44.08

10/7/99 1330 MEB onsite to collect W.L.

| Well | W.L. | Time | |
|---|---|---|---|
| MW210 | 26.16 | 1335 | |
| MW203 | 23.40 | 1337 | |
| MW212 | 22.79 | 1342 | |
| P-211 | 8.25' | 1346 | |
| MW209 | 9.13' | 1349 | |
| MW204 | 16.42' | 1352 | |
| Small Pond | Dry | 1353 | |
| MW101A | 18.62' | 1354 | |
| LAKE | Gauge removed | | Take back to PFE |
| LARGE Pond | Dry | 1408 | |
| MW202 | 26.79' | 1414 | |
| MW208 | 27.17' | 1416 | |
| MW102 | 10.95 | 1422 | |
| MW103 | 9.84 | 1425 | |
| MW201 | 8.33 | 1427 | |
| MW206 | 9.22' | 1430 | Replace Lock |
| MW207 | 9.37' | 1432 | |

1445 MEB offsite

279.44.08

11/23 November Water Levels were recorded during Network sampling event. See Ground water sampling forms during Nov 99 for water levels.



279.44.08 Clear/Cool

12/3/99

1106 MEB onsite to collect water levels

| Well | W.L. | Time | Comments |
|---|---|---|---|
| MW204 | 16.61 | 1112 | |
| MW101A | 18.72 | 1114 | |
| P-211 | 8.80 | 1117 | |
| MW209 | 8.31 | 1119 | |
| MW212 | 23.00 | 1123 | |
| MW203 | 23.99 | 1128 | |
| MW210 | 26.37 | 1132 | |
| MW202 | 26.97 | 1135 | |
| MW208 | 27.37 | 1137 | |
| MW102 | 11.02 | 1144 | |
| MW103 | 9.91 | 1146 | |
| MW201 | 8.41 | 1147 | |
| MW206 | 9.31 | 1150 | |
| MW207 | 9.50 | 1152 | |

* Lake & Pond Readings Discontinued

1200 MEB off site

2/2/00

279.44.08 Clear, 40°

1120 TJB on-site for w.l.s

| Well # | W.L. | Time | Comments |
|---|---|---|---|
| MW-208 | 26.11 | 1137 | |
| MW-200 | 25.61 | 1145 | |
| MW-203 | 23.23 | 1153 | |
| MW-204 | 15.84 | 1159 | |
| P-211 | 7.55 | 1215 | |
| MW-207 | 7.56 | 1220 | |
| MW-212 | 22.21 | 1228 | |
| MW-101A | 17.96 | 1239 | |
| MW-102 | 9.34 | 1253 | |
| MW-103 | 9.23 | 1300 | |
| MW-201 | 7.71 | 1305 | |
| MW-206 | 8.61 | 1313 | |
| MW-207 | 8.76 | 1320 | |
| MW-208 | 26.58 | 1349 | |

1353 TJB off site



4/11/00

279.44.08 ~~Ron Collier~~ Rain, 50°

1000 TJB on-site for w.l.s.

| Well # | W.L. | Time | Comments |
|---|---|---|---|
| MW-208 | 22.25 | 1006 | |
| MW-202 | 22.44 | 1010 | |
| MW-210 | 22.23 | 1017 | |
| MW-203 | 15.80 | 1023 | |
| MW-204 | 12.35 | 1029 | |
| MW-101A | 13.86 | 1034 | |
| MW-212 | 18.8 | 1109 | |
| P-211 | 4.2 | 1115 | |
| MW-209 | 4.06 | 1120 | |

TJB to off-site wells. new fence has been constructed along pathway, must access MW-MW-209, 202, and P-211 through Dayle's Auto parts @ 2335 E. River Road

| | | |
|---|---|---|
| MW-102 | 3.58 | 1144 |
| MW-103 | 3.86 | 1213 |
| MW-201 | 2.02 | 1208 |
| MW-206 | 2.62 | 1205 |
| MW-207 | 2.93 | 1200 |

clear 7/17/00
279.44.05

0930 MEB onsite to collect water levels.

| WELL | W.L. | Time |
|---|---|---|
| MW 102 | 9.33 | 1000 |
| MW 103 | 8.21 | 1005 |
| MW201 | 6.70 | 1008 |
| MW206 | 7.56 | 1011 |
| MW207 | 7.74 | 1014 |
| MW204 | 14.66 | 1025 |
| P-211 | 6.02 | 1027 |
| MW209 | 6.41 | 1030 |
| MW 212 | 21.09 | 1036 |
| MW 101A | 16.97 | 1042 |
| MW203 | 22.02 | 1045 |
| MW210 | 24.37 | 1047 |
| MW202 | 25.00 | 1050 |
| MW208 | 25.45 | 1053 |

1055 MEB offsite



clear 10/11/00
279.44.08

0920 MEB/KDK onsite to collect water levels

| WELL | W.L. | Time | |
|---|---|---|---|
| MW210 | 24.08' | 0925 | |
| MW203 | 21.74' | 0935 | |
| MW204 | 14.37' | 0945 | |
| P-211 | 6.16' | 0948 | |
| MW-209 | 6.09' | 0952 | Replaced Lock |
| MW-212 | 20.76' | 1000 | |
| MW202 | 24.62' | 1015 | |
| MW208 | 24.95' | 1017 | |
| MW 103 | 8.70' | 1025 | Replaced lock |
| MW102 | 7.57' | 1035 | Replaced lock |
| MW201 | 6.40' | 1040 | |
| MW206 | 6.86' | 1043 | |
| MW207 | 7.09' | 1050 | |

MEB cuts grass around MCD property wells.

1100 MEB/KDK offsite return to IFI

MW 101A - 16.56'

2/6/01 279.44.08

SNOW, OVERCAST ~33°F

0915 CSK ONSITE TO RECORD WATER LEVELS

| TIME | WELL | W.L. |
|---|---|---|
| 0920 | MW-210 | 23.95 |
| 0924 | MW-203 | 21.61 |
| 0936 | MW 204 | 14.17 |
| 0940 | MW-101A | 16.30 |
| 0945 | MW-209 | 6.00 |
| 0944 | PZ ~~MW-209~~ CSK 6/6/01 | 5.37 |
| 0957 | MW-212 | 20.68 |
| 1010 | MW-208 | 24.84 |
| 1015 | MW-202 | 24.46 |
| 1030 | MW-207 | 6.89 |
| 1033 | MW-206 | 6.75 |
| 1035 | MW 201 | 5.91 |
| 1038 | MW 103 | 7.47 |
| 1041 | MW 102 | 8.61 |

⊗ 101A

⊗ 204

MIDDLE OF GRASSY AREA. CLOSEST TO GATE. 1" POTENTIAL

⊗ 212

TOP OF WELL

⊗ 209

1045 ALL WELLS SECURED / CSK OFFSITE



10/25/01 279.44.08

45°C, partly cloudy, cool, rain last night.

0830 SDL on site to collect water levels.

| TIME | WELL | W.L. | |
|---|---|---|---|
| 0843 | MW-210 | 22.86 | |
| 0851 | MW-204 | 12.77 | |
| 0904 | MW-101A | 14.35 | |
| 0919 | MW-203 | 20.30 | |
| 0927 | MW-209 | 4.27 | |
| 0932 | P-211 | 4.78 | cut & replaced lock |
| 0949 | MW-212 | 18.99 | " " " |
| 0959 | MW-208 | 23.19 | |
| 1004 | MW-202 | 23.01 | |

1017 MW-207, 206, 201, 103 & 102 along bike path underwater due to rising river water.

1022 SDL ~~off~~ site

Stenotyping 10/25/01

279.44.05 SPB 3/5/02

1335 - MFB onsite to collect

Water level

| WELL | WL. | |
|---|---|---|
| MW102 | 7.20' | New Lock |
| MW103 | 6.04' | New Lock |
| MW201 | 4.51' | |
| MW206 | 5.27' | |
| MW207 | 5.43 | |
| MW212 | 18.76' | |
| MW 202 | 22.49' | |
| MW208 | 23.00' | |
| MW210 | 21.95' | |
| MW203 | 19.91 | |
| MW204 | 12.24' | |
| P-211 | 4.31 | |
| MW-209 | 4.12 | |
| MW101A | 14.49' | |

14.45 MFB + SPB offsite



4/9/02 GRILLOT 279.44.05

RAIN 56°F

0950 LSK / SPB ONSITE. BEGIN RECORDING W.L.'S

| TIME | WELL | W.L | COMMENT |
|---|---|---|---|
| 0955 | MW-208 | 21.98 | |
| 0957 | MW-202 | 21.69 | |
| 1000 | MW-210 | 21.12 | |
| 1006 | MW-203 | 18.83 | |
| 1009 | MW-101A | 13.47 | |
| 1013 | MW-204 | 11.42 | |
| 1027 | MW-212 | 18.03 | ON RIDGE |
| 1020 | P-211 | 3.52 | |
| 1024 | MW-209 | 3.32 | LAKE |
| 1045 | MW-207 | 4.36 | |
| 1050 | MW-206 | 4.09 | NEW LOCK |
| 1053 | MW-201 | 3.30 | WATER IN METAL CASING |
| 1056 | MW-103 | 4.77 | |
| 1059 | MW-102 | 5.91 | |
| 1100 | W.L'S | COMPLETE. | OFFSITE |

5/2/02 GRILLOT 279.44.08

0935 SDL on site to collect water levels.

| Well | W.L. | Comments |
|---|---|---|
| MW-208 | 21.25 | |
| MW-202 | 20.89 | |
| MW-210 | 20.34 | |
| MW-203 | 18.04 | |
| MW-204 | 10.65 | |
| MW-101A | 12.77 | |
| MW-212 | 17.32 | |
| MW-209 | 2.77 | |
| P-211 | 2.64 | |
| MW-207 | 3.48 | |
| MW-206 | 3.28 | |
| MW-201 | 2.53 | water in casing - to top |
| MW-103 | 4.05 | |
| MW-102 | 5.22 | |

1045 All water levels completed. All wells secured. SDL off site.



6/14/02 GRILLOT 279.44.08

65°F, partly cloudy.

0840 SDL & BKG on site to perform ground water sampling of designated wells. - MW-101A, 102, 103, 201, 206, 207, 209, 212, 203, 210, 202 & 208. Refer to 'Ground Water Sampling Forms' per this date & project number.

| Well | W.L. | T.D. |
|---|---|---|
| P-211 | > 3.20 | 25.85 |

MW-204 open upon arrival (well casing & well) well cap missing, needs replaced. Covered well & re-locked after sampling.

1030 All sampling complete, all wells secured. SDL & BKG off site.

[signature] 6/14/02

10/2/02 Grillot 279.44.08

1025 JPB onsite to conduct water level events.

| Well | W.L | Comments |
|---|---|---|
| MW 208 | 24.23 | |
| MW 202 | 23.73 | |
| MW 210 | 23.07 | |
| MW 203 | 20.77 | |
| MW 204 | 13.37 | Replaced Cap |
| MW 101A | 15.79 | |
| MW 212 | ~~5.60~~ | 19.96 |
| MW 209 | ~~19.96~~ | 5.31 |
| P211 | 5.50 | |
| MW 102 | 8.51 | |
| MW 103 | 7.34 | |
| MW 201 | 5.83 | |
| MW 206 | 6.59 | |
| MW 207 | 6.77 | |

11:30 All wells Secured and JPB offsite.

10/2/02



3/4/03 Grillot 279.44.08

1118 JPB onsite to conduct Quarterly Water Levels.

| Well | W.L. | Time | Comments |
|---|---|---|---|
| MW 208 | 21.85 | 1125 | N.L. Cap |
| MW 202 | 21.71 | 1121 | |
| MW 210 | 21.46 | 1115 | |
| MW 203 | 19.12 | 1155 | |
| MW 204 | 11.70 | 1158 | |
| MW 101A | 13.74 | 1202 | |
| MW 212 | 18.21 | 1211 | |
| MW 209 | 3.57 | 1208 | |
| P211 | 3.70 | 1206 | |
| MW 102 | 5.60 | 1230 | |
| MW 103 | 4.28 | 1234 | |
| MW 201 | 2.54 | 1237 | |
| MW 206 | 3.03 | 1242 | |
| MW 207 | 3.13 | 1245 | |

1130 Call to Charles of Busy Bee Pallets to unlock front gate to gain access to monitoring wells.

1255 JPB offsite, All Activities Complete

3/4/03

5/12/03 Grillot 279.44.08

Very Windy ≅ 55°F

1245 JPB onsite to perform Quarterly G.W. Levels.

| Well | W.L | Comment |
|---|---|---|
| MW208 | 21.67 | |
| MW202 | 21.60 | |
| MW210 | 21.33 | |
| MW203 | 18.99 | |
| MW204 | 11.57 | |
| MW101A | 13.65 | |
| MW212 | 18.04 | |
| MW209 | 3.35 | |
| P211 | 3.37 | |
| MW102 | 4.96 | |
| MW103 | 3.51 | |
| MW201 | I.A. | Water |
| MW206 | I.A | Water |
| MW207 | 2.26 | |

1344 JPB offsite, All Activities Complete.

5/12/03