IF THE PAGE FILMED IS N
AS LEGIBLE AS THIS LABE
IT IS DUE TO THE QUALIT
OF THE ORIGINAL.

RCRA INSPECTION

I. SITE IDENTIFICATION

NMD 08 3212332

A. Site Name: Sparton SW, Inc

B. Street (or other identifier): 1621 Coors NW

C. City: Albuquerque

D. State: NM

E. Zip Code:

F. County Name: Bernalillo

G. Site Operator Information

1. Name: Same as Above

2. Telephone Number: 505-892-5300

3. Street

4. City

5. State

6. Zip Code

H. Site Description: Manufacture of electronic components and equipment

I. Latitude (deg.-min.-sec.)

Longitude (deg.-min.-sec.)

J. Type of Ownership

__1. Federal __2. State __3. County __4. Municipal X 5. Private

K. X 1. Generator __2. Transporter __3. Treatment X 4. Storage __5. Disposal

INSPECTION INFORMATION

A. Principal Inspector Information

1. Name: Boyd Hamilton

2. Title: Inspector

3. Organization: NMEID

4. Telephone No. (area code & No.): 505-984-0020

B. Inspection Participants

Mike Michaud - U.S. EPA Region 6

Terry Boone - Sparton S.W.

90045557