Photograph from Preliminary Assessment
dated 01/15/85

90070113

Photographer / Witness

RH Davis Engineering-Science

Date / Time / Direction

12-19-84 / 850am / south

Comments: View of 3 rusted Storage tanks from Hwy 105 Bldg in bkgd may house lumber treat area

Photographer / Witness

Date / Time / Direction

Comments:

Photographer / Witness

Date / Time / Direction

Comments: