MISSOURI PACIFIC RAILROAD
DITCH
DITCH
TRENCH
SUSPECTED SEEPAGE
SUSPECTED WASTE BURIAL AREA
TRENCH
SUSPECTED LANDFILL
WASTE POND
OLD BUILDING FOUNDATION
ACID STORAGE TANKS
LIQUID ACCUMULATION
TANK
STAINS
LOADING RACKS
STACKED MATERIALS
SPILL STAINS
SEEPAGE STAINS IN FILL MATERIAL
STACKED MATERIALS
PESTICIDES FORMULATION PLANT
TANKS
SPILL STAINS
DITCH
DRY PRODUCTS STORAGE SILOS
STAINS
BROADWAY
DIXIE
CHICAGO ROCK ISLAND AND PACIFIC RAILROAD
NORTH LITTLE ROCK
FLOW
DRAINAGE
BERM
Arkansas River
EPA Environmental Monitoring Systems Laboratory-Las Vegas
9292540
OLIN CORPORATION
NORTH LITTLE ROCK, ARKANSAS
FLOWN: DECEMBER 23, 1949
AMD 83041
APPROX. SCALE 1 inch = 300 feet
N