SWS ENVIRONMENTAL SERVICES

Project Reporting Log

Date:	3-13-15	SWS Environmental Services Rep	M. Turner
Client:	CBI	Rep	OK
SWS Environmental Services Job #:	HU3-409-1126	Client PO:	
Job Location:	4904 Griggs Rd. Houston Tx		
GPS Coordinates:	Longitude:	Latitude:	
Phone Number:		Fax Number:	

The following is a summary of the actions taken by SWS Environmental Services concerning the above incident:

0700	Crew Arrived onsite for Morning Safety Meeting and ops Meeting With Associated Paper Work
0730	Crew began to Setup 3" Pump @ South Pond For Pumping Of Water, VAC Truck Mob to South Containment For oily water Removal, & Gather Supplies for Door Blockage.
0900	VAcuum Truck ~~pro~~ full proceed to offload into ~~Box~~ Frac #(FT1001) upon Completion Crew Staged Truck For solids removal into VAC Box
1000	Crew Began gathering Flammable Grease Drums into Solids removal Area, Crews ~~are~~ is gathering grounding Cables, CAM lock flange for VAC Box, & Petro Hose to Began Removal of Flammable Grease.
1200	Lunch
1230	Crew helped Transport Tanker into VAC Boxes continued Pumping water & Gathering Of Empty's
1330	Crew cleaned around North Pond for Drainage of water.
1440	Began Removing Flammable Grease from Drums
1640	Breakdown Site Securement
1700	Depart Site

9858520