OT Roll Offs

2/17/2015

Number	Profile	Status	Org. Status		Analyzed	Approved
OT 25563		Sand Trench Residue				15 % Full
OT 25337		Empty				
OT 25474		Empty				
OT 25480		Fine material, soil sand from North Pond Asphalt	NH	Sand Composite 6	Sampling 2/19/2015	
OT 25160		Sand from Warehouse	NH	Sand Composite 6	Sampling 2/19/2015	
OT 25452		Sand from Warehouse	NH	Sand Composite 6	Sampling 2/19/2015	
OT 25319	**US Ecology**	Debris (ADS Hose, Wood,Pails, Plastic, PPE)	Haz?			
OT 25134	**US Ecology**	Debris (Pails, PPE, Wood)	Haz?			

Vacuum Boxes

Donated

2/17/2015

Number		Status		Composite	Analyzed	Approved
VB 25318	**Veolia**	Sludge S T 2	D018	Sludge Comp 5	Received Results	37 "
VB 25306	**Veolia**	Sludge S T 2 (D018), S T 5 (NH)	D018	Sludge Comp 5	Received Results	36.5"
VB 25278	**Veolia**	Sludge N T 9, N T 10, N T 11	D018	Sludge Comp 5	Received Results	36.5"
VB 25226	**Veolia**	Sludge S T 3, S T 5, S T 7	D018	Sludge Comp 2	Received Results	36"
VB 25302		Sludge N T 3, N T 5, N T 6, S T 8 N OT 8	Resample	Sludge Comp 3 *****	Received Results	36"
VB 2564	**Republic**	Sludge from WWT Area	NH	Sludge Comp 3	Received Results	36"
VB 2501	**Republic**	Sludge N T 3, N T 5, N T 6, S T 8	NH	Sludge Comp 3	Received Results	36"
VB 25348	**Republic**	Sludge S T 5	NH	Resample Sludge ST 5 Composite	Received Results,Resampling 2/19/2015	36"
VB A 0825097	**Republic**	Sludge ST 5	NH	Resample Sludge ST 5 Composite	Received Results,Resampling 2/19/2015	36"
VB A 785		Sludge ST 5	NH	Sludge ST 5 Composite	Sampling 2/19/2015	36"
VB 25206		Sludge ST 5	NH	Sludge ST 5 Composite	Sampling 2/19/2015	36"
VB 25274		Sludge ST 5	NH	Sludge ST 5 Composite	Sampling 2/19/2015	36"
VB 25341		Sludge ST 8	NH	Sludge ST 8 Composite	Sampling 2/19/2015	36"
VB 25251		Sludge ST 8	NH	Sludge ST 8 Composite	Sampling 2/19/2015	36"
VB 25322		Sludge ST 8	NH	Sludge ST 8 Composite	Sampling 2/19/2015	36"
VB 25287	**Veolia**	N OT 7, N OT 8	D018			36"
VB 25333	**Veolia**	N OT 8	D018			36"
VB 25281	**Veolia**	N OT 8	D018			36"
VB 25146		Empty				
VB 25343	**Veolia**	N OT 8	D018			14"
VB 25203		T1, T 11, T 3	NH			17"
VB 25315		T-7, T-8, T11, T 10, T 9, T 4	NH			36"

Full depth integrated Samples S1 and S6

Number		Status			Analyzed	Approved
VBDW 25196	**Veolia**	N OT 8	D018		No	28"

Frac Tanks

Number		Status			Analyzed	Approved
FT 1004		Full Approved Lonestar Qualifying w/CB&I			Yes	
FT 1002		Empty-Cleaned			NA	
FT 1001		Full Approved Lonestar Profile LSE 1128		Empty 2 19 2015	NA	Profile LSE 1128

9858899

FT 5180		Empty-Some residual sludge			NA	
FT 215012		Full-Analysis Pending			Preliminary	
FT 30335		5,060 Gallons				
FT 33527		Empty-Cleaned			NA	
FT 30338		Empty-Cleaned			NA	