TCEQ Handhel[illegible]nitoring Field Data Sheet

DATE: 3/25/19
NAME: Chester Walters

Location (include city)	Time (Approx.)	Instrument	Parameters	Survey Results	Other Notes/Observations
Cedar Bayou Baptist Church (Baytown)	1550	TVa	~~[illegible]~~ VOC	1.1ppm VOC	Wind out of Southwest
		Multi-Rae pro	VOC, lel, CO, O^2, H_2S	0.0 ppb VOC	No odors
Unidad Park	1606	TVa	VOC	0.6 ppm	Wind out of Southwest
		MultiRae Pro	VOC, lel, CO, O^2, H^2S	0.0 ppb	No odors
Intersection of Spencer + 16th Streets (La Porte)	1628	TVa	VOC	0.2 ppm	N/A
		multi rae	VOC etal	0.0 ~~ppb~~ ppb	No odors

9963888

TCEQ Handheld Monitoring Field Data Sheet

DATE: 3/25/19
NAME(s): Chester Hassain

Location (include city)	Time (Approx.)	Instrument	Parameters	Survey Results	Other Notes/Observations
EXAMPLE: Intersection of Thomas and Preston (Deer Park)	9:00 PM	TVA	VOC	2.4 – 3.5 ppm (similar to background levels)	Light odors detected continuously – Sulfur and light burning likely from a nearby recycling facility.
		MultiRAE	LEL, VOC, H2S, CO, O2	None detected, oxygen normal	
EXAMPLE: East Blvd and E 13th intersection (Deer Park)	9:30 PM	MultiRAE	LEL, VOC, H2S, CO, O2	None detected, oxygen normal	Exhaust odor, intermittent, likely due to vehicle traffic
Memorial North Baptist Church	1530	TVA	VOC 2.6 ppm	2.6 ppm VOC	wind out of South west.
		multirae	VOC, lel, H2S, CO, O2	0.0 ppb VOC	No odors

TCEQ Handheld Monitoring Field Data Sheet

DATE: 3/25/19
NAME: Chester Walters

Location (include city)	Time (Approx.)	Instrument	Parameters	Survey Results	Other Notes/Observations
Crawdads resturant and gas station (Love)	1734	TVA	VOC	0.1 ppm	N/A
		Multi-Rae pro	VOC, lel, CO, O2, H2S, gamma	0.0 ppb VOC Negative all other Parameters	No odors
Living hope Church (Baytown	1756	TVA	VOC	N/A TVA Began malfunctioning, false readings → we suspect TVa is malfunctioning	No odors
		Multirae	VOC, lel, CO, O2 H2S, gamma	0.0 ppb VOC Negative all other Parameters	Skunk like odor Detected in the area, found skunk.
Itc of Bob smith + Mickenney RD. (Baytown)	1827	TVa	Malfunctioning →		No odors
		Multirae	VOC, lel, CO, O2, H2S, gamma	0.0 ppb VOC Negative all other Parameters	

TCEQ Handheld Monitoring Field Data Sheet

DATE: 3/25/19
NAME: Chester / Hagain

Location (include city)	Time (Approx.)	Instrument	Parameters	Survey Results	Other Notes/Observations
2219 Tx-146 Business	1850	Tva Malfunction			N/A
		MultiRae	VOC, lel, CO, O2 H2S, gamma	0.0 PPb VOC Negative readings all other parameters	No odors
Evergreen Disc golf Course Charlton	1905	Tva Malfunction			N/A
		MultiRae	VOC, lel, CO, O2, H2S, gamma	0.0 PPb VOC Negative readings on all other parameters	No odors
Cedar Bayou Junior highschool	1932	Tva Malfunction			N/A
		MultiRae	VOC, lel, CO, O2, H2S, gamma	0.0 PPb VOC Negative readings on all other parameters	No odors

TCEQ Handheld Monitoring Field Data Sheet

DATE: 3/25/19
NAME: Chester / Hasain

Location (include city)	Time (Approx.)	Instrument	Parameters	Survey Results	Other Notes/Observations
Ross S. Sterling highschool (Baytown)	1956				No Odors
		Multirae	VOC, O2, CO, H2S gamma	0.0 ppb VOC all other Parameters Negative	N/a
Baytown Premier San Jacinto Mall (Baytown)	2017				No odors N/a
		Multirae	VOC, O2, CO, H2S, gamma	0.0 ppb VOC Negative all other Parameters	No odors
Stallworth Stadium (Baytown)	2039				No odors N/a
		Multirae	VOC, O2, CO, H2S, gamma	0.0 ppb VOC ~~Negative~~ Negative all other Parameters	

TCEQ Handheld Monitoring Field Data Sheet

DATE: 3/25/19
NAME: Chester Walters

Location (include city)	Time (Approx.)	Instrument	Parameters	Survey Results	Other Notes/Observations
Baytown Historical Museum	27:12	TVA Malfunction			No odors
		Multirae	Voc, lel, CO, O2 H2S, gamma	0.0 ppb VOC all other parameters Negative	
Intersection of Missouri & Wyoming St. (Baytown)	2151	TVA Malfunction			No odors
		multirae	Voc, lel, CO, O2 H2S, gamma	0.0 ppb VOC all other parameters Normal	