PIC 89790
FRAME 129
RAZED TANKS
STAIN
RAZED BUILDINGS
TAILINGS POND
BREACH IN CONTAINMENT
RAZED BUILDINGS
TAILINGS
EROSION
TAILINGS
DRAINAGE DITCH
COBALT VILLAGE
Tollar Branch
BARREN LAND
SEEPAGE AND EROSION
RAZED BUILDING
STANDING LIQUID
TAILINGS
DRAINAGE DITCH
IMPOUNDMENT
BERM/DIKE
MOUNDED MATERIAL
EXCAVATION, PIT
DRAINAGE
FLOW
EPA Environmental Monitoring Systems Laboratory-Las Vegas
30096577
Superfund
MADISON MINE
FREDRICKTOWN, MISSOURI
PIC 89790
DATE FLOWN: MAY 14, 1971
SOURCE: ASCS FRAME NO. 129
APPROX. SCALE 1 inch = 340 feet
N