PIC 89790
FRAME 141
Saline Creek
HIGH STREET
MARLOWE STREET
FREDRICKTOWN
MARVIN AVENUE
FILL
DEMOLISHED MINING BUILDINGS
COBALT VILLAGE
DRAINAGE DITCH
Tollar Branch
SEEPAGE AND EROSION
BARREN LAND
DRAINAGE DITCH
BREACH
BERM/DIKE
MOUNDED MATERIAL
EXCAVATION, PIT
DRAINAGE
FLOW
EPA Environmental Monitoring Systems Laboratory Las Vegas
30096578
Superfund
MADISON MINE
FREDRICKTOWN, MISSOURI
PIC 89790
DATE FLOWN: APRIL 17, 1974
SOURCE: EROS FRAME NO. 141
APPROX. SCALE 1 inch = 505 feet
N