
DISTURBED GROUND
REVEGETATION
SOLID WASTE
BACKHOE, DOZER AND TRACTOR DIGGING PIT
DISTURBED GROUND
SCRAPER
PIT
DEMOLISHED BUILDINGS
PREVIOUS LOCATION OF POND
EPA Environmental Monitoring Systems Laboratory-Las Vegas
30097404
Superfund
MADISON MINE
FREDRICKTOWN, MISSOURI
PIC 89790
DATE FLOWN: MAY 2, 1989
SOURCE: EMSL FRAME NO. 2
APPROX. SCALE 1 inch = 190 feet
(1 OF 3)
N