From:	Fowlow, Jeffrey
To:	Sibley, Michael
Subject:	FW: Odessa Biodiesel plant-Pictures 3/10/15
Date:	Thursday, March 12, 2015 10:59:00 PM
Attachments:	image001.png image002.png image003.png image004.png image005.png image006.png image007.png image008.png image009.png image010.png image011.png image012.png

---

From: French, Gerald (ECY) [mailto:GEFR461@ECY.WA.GOV]
Sent: Tuesday, March 10, 2015 2:51 PM
To: Fowlow, Jeffrey; Liverman, Earl
Subject: Odessa Biodiesel plant-Pictures 3/10/15

Here a few pictures of pictures taken on 3/10/15.

Incompatible lab chemicals in cabinet

Leaking tote of sulfuric acid onto kitty litter

Leak of liquid from a tank

Drum inside of building

Drums inside of building

Fire extinguisher

Lime sacks

White crystals outside and west of builidng from pipe and valve marked as sodium methoxide inbound

Leaks of unknown liquid on floor.

White crystals on floor near totes holding citric acid and another tote holding caustic soda

Pump unit severely corroded

White crystal formed on outside of leaking tank

Jerry French
Department of Ecology, Eastern Regional Office
Hazardous Waste & Toxics Reduction Program
4601 North Monroe Street
Spokane, WA 99205-1295
(509) 329-3489
gefr461@ecy.wa.gov