BACKFLOW PREVENTION ASSEMBLY TEST REPORT

ADVANCED SPECIALTY SERVICES
P.O. Box 3237
Silverdale, WA 98383-3237
(360) 981-6536

NAME OF PREMISE Penn Plaza Commercial ☑ Residential ☐

SERVICE ADDRESS 1560 Thompson CITY Brem ZIP 98337

CONTACT PERSON _____ PHONE ( ) _____ FAX ( ) _____

LOCATION OF ASSEMBLY 1560 Thompson SW Corner near meter Hot Box

DOWNSTREAM PROCESS Domestic DCVA ☐ RPBA ☑ PVBA ☐ OTHER _____

NEW INSTALL ☑ EXISTING ☐ REPLACEMENT ☐ OLD SER. # N/A PROPER INSTALLATION? YES ☑ NO ☐

MAKE OF ASSEMBLY Wilkins MODEL 975XL SERIAL NO. 1294553 SIZE 1

IS THE ASSEMBLY CORRECT FOR THE DEGREE OF HAZARD? Yes

IS THE ASSEMBLY A WA STATE APPROVED ASSEMBLY? Yes

	DCVA / RPBA CHECK VALVE NO.1	DCVA / RPBA CHECK VALVE NO.2	RPBA	PVBA/SVBA AIR INLET
INITIAL TEST PASSED ☑ FAILED ☐	CLOSED ☑ LEAKED ☐ 9.8 PSID	CLOSED ☑ LEAKED ☐ _____ PSID	OPENED AT 9.4 PSID #1 CHECK 9.8 PSID AIR GAP OK? ✓	OPENED AT _____ PSID DID NOT OPEN ☐
NEW PARTS AND REPAIRS	CLEAN REPLACE PART ☐ ☐ _____ ☐ ☐ _____ ☐ ☐ _____ ☐ ☐ _____	CLEAN REPLACE PART ☐ ☐ _____ ☐ ☐ _____ ☐ ☐ _____ ☐ ☐ _____	CLEAN REPLACE PART ☐ ☐ _____ ☐ ☐ _____ ☐ ☐ _____ ☐ ☐ _____	CHECK VALVE HELD AT _____ PSID LEAKED ☐ _____ CLEANED ☐ REPAIRED ☐
TEST AFTER REPAIRS PASSED ☐ FAILED ☐	LEAKED ☐ _____ PSID	LEAKED ☐ _____ PSID	OPENED AT _____ PSID #1 CHECK _____ PSID	AIR INLET _____ PSID CHK VALVE _____ PSID

AIR GAP INSPECTION: Required minimum air gap separation provided? Yes ☐ No ☐ Detector Meter Reading _____

REMARKS: This assembly was Relocated From B-13 LINE PRESSURE 60 PSI
unit 1 CONFINED SPACE? _____

TESTERS SIGNATURE: Ken Wilson CERT. NO. B 2082 DATE 1-8-16

TESTERS NAME PRINTED: KEN WILSON TESTERS PHONE # (360) 981-6536

REPAIRED BY: _____ DATE _____

FINAL TEST BY: _____ CERT. NO. _____ DATE _____

CALIBRATION DATE 11-18-14 GAUGE # 08080513 MODEL 835 SERVICE RESTORED? YES ☐ NO ☑