Lab/Cor, Inc.

A Professional Service Corporation in the Northwest

Report # 041172R3

Client: Ecology and Environment, Inc.

Project Name: Site# 0440.01CP, 0440.01CP-0001- FINAL RESULTS

ANALYSIS DETAIL

Lab/Cor Sample No.	B4760 S31 A1	**Volume (L)**	1186.08
Client Sample No.	RHB-H2-1FD-100304	**No. of Grid Openings**	23
Description		**Filter Area (mm2)**	385
Analysis Date	11/3/2004	**Area Analyzed (mm2)**	0.333
Analyst	JH	**Analytical Sens. (struc/cc)**	0.000974
		Dectection Limit. (struc/cc)	0.00291

Structure Type	Filter Density (s/mm2)	Concen-tration (struc/cc)	95% Confidence Interval (struc/cc)	Struc. Count
Primary Asbestos Structures	3.0	0.000974	0.00 - 0.00462	1
Total Asbestos Structures	3.0	0.000974	0.00 - 0.00462	1
Asbestos Structures > 5um	3.0	0.000974	0.00 - 0.00462	1
Asbestos Fibers and Bundles > 5um	3.0	0.000974	0.00 - 0.00462	1
PCM Equivalent Fibers-US	3.0	0.000974	0.00 - 0.00462	1
PCM Equivalent Structures-US	3.0	0.000974	0.00 - 0.00462	1
PROTOCOL ASB STRUCS 5-10	0.0	<0.00291	0.00 - 0.00291	0
PROTOCOL ASB STRUCS >10	0.0	<0.00291	0.00 - 0.00291	0
PROTOCOL ASB STRUCS TOTAL	0.0	<0.00291	0.00 - 0.00291	0
PROTOCOL CHRYS STRUCS 5-10	0.0	<0.00291	0.00 - 0.00291	0
PROTOCOL CHRYS STRUCS >10	0.0	<0.00291	0.00 - 0.00291	0
PROTOCOL CHRYS STRUCS TOTAL	0.0	<0.00291	0.00 - 0.00291	0
PROTOCOL AMPH STRUCS 5-10	0.0	<0.00291	0.00 - 0.00291	0
PROTOCOL AMPH STRUCS >10	0.0	<0.00291	0.00 - 0.00291	0
PROTOCOL AMPH STRUCS TOTAL	0.0	<0.00291	0.00 - 0.00291	0
AHERA-like Total Structures 3:1	3.0	0.000974	0.00 - 0.00462	1
AHERA-like Asb Strucs >5 and 3:1	3.0	0.000974	0.00 - 0.00462	1
AHERA-like Asb Strucs 5 - 10 and 3:1	3.0	0.000974	0.00 - 0.00462	1
AHERA-like Asb Strucs >10 and 3:1	0.0	<0.00291	0.00 - 0.00291	0
Total Other Amphibole Strucs 3:1	0.0	<0.00291	0.00 - 0.00291	0
Other Amphibole Strucs >5 and 3:1	0.0	<0.00291	0.00 - 0.00291	0
Other Amphibole Strucs 5 - 10 and 3:1	0.0	<0.00291	0.00 - 0.00291	0
Other Amphibole Strucs >10 and 3:1	0.0	<0.00291	0.00 - 0.00291	0

Lab/Cor, Inc.

A Professional Service Corporation in the Northwest

Report # 041172R3

Client: Ecology and Environment, Inc.

Project Name: Site# 0440.01CP, 0440.01CP-0001- FINAL RESULTS

ANALYSIS DETAIL

Lab/Cor Sample No. B4760 S32 A1
Client Sample No. RHB-H2-2FD-100304
Description
Analysis Date 11/3/2004
Analyst JH

Volume (L) 1220
No. of Grid Openings 22
Filter Area (mm2) 385
Area Analyzed (mm2) 0.319
Analytical Sens. (struc/cc) 0.000990
Dectection Limit. (struc/cc) 0.00296

Structure Type	Filter Density (s/mm2)	Concen-tration (struc/cc)	95% Confidence Interval (struc/cc)	Struc. Count
Primary Asbestos Structures	18.8	0.00594	0.00218 - 0.0129	6
Total Asbestos Structures	18.8	0.00594	0.00218 - 0.0129	6
Asbestos Structures > 5um	9.4	0.00297	0.00 - 0.00767	3
Asbestos Fibers and Bundles > 5um	9.4	0.00297	0.00 - 0.00767	3
PCM Equivalent Fibers-US	9.4	0.00297	0.00 - 0.00767	3
PCM Equivalent Structures-US	9.4	0.00297	0.00 - 0.00767	3
PROTOCOL ASB STRUCS 5-10	3.1	0.000990	0.00 - 0.00469	1
PROTOCOL ASB STRUCS >10	0.0	<0.00296	0.00 - 0.00296	0
PROTOCOL ASB STRUCS TOTAL	3.1	0.000990	0.00 - 0.00469	1
PROTOCOL CHRYS STRUCS 5-10	0.0	<0.00296	0.00 - 0.00296	0
PROTOCOL CHRYS STRUCS >10	0.0	<0.00296	0.00 - 0.00296	0
PROTOCOL CHRYS STRUCS TOTAL	0.0	<0.00296	0.00 - 0.00296	0
PROTOCOL AMPH STRUCS 5-10	3.1	0.000990	0.00 - 0.00469	1
PROTOCOL AMPH STRUCS >10	0.0	<0.00296	0.00 - 0.00296	0
PROTOCOL AMPH STRUCS TOTAL	3.1	0.000990	0.00 - 0.00469	1
AHERA-like Total Structures 3:1	18.8	0.00594	0.00218 - 0.0129	6
AHERA-like Asb Strucs >5 and 3:1	9.4	0.00297	0.00 - 0.00767	3
AHERA-like Asb Strucs 5 - 10 and 3:1	6.3	0.00198	0.00 - 0.00624	2
AHERA-like Asb Strucs >10 and 3:1	3.1	0.000990	0.00 - 0.00469	1
Total Other Amphibole Strucs 3:1	0.0	<0.00296	0.00 - 0.00296	0
Other Amphibole Strucs >5 and 3:1	0.0	<0.00296	0.00 - 0.00296	0
Other Amphibole Strucs 5 - 10 and 3:1	0.0	<0.00296	0.00 - 0.00296	0
Other Amphibole Strucs >10 and 3:1	0.0	<0.00296	0.00 - 0.00296	0

Lab/Cor, Inc.

A Professional Service Corporation in the Northwest

Report # 041176R1

Client: Ecology and Environment, Inc.

Project Name: Site# 0440.01CP, 0440.01CP-0001- FINAL RESULTS

ANALYSIS DETAIL

Lab/Cor Sample No.	B4763 S1 A1	Volume (L)	1220
Client Sample No.	RHB-H2-2FD-100304	No. of Grid Openings	22
Description	Replicate Analysis of 041172-32 - Same Grid Openings	Filter Area (mm2)	385
Analysis Date	12/2/2004	Area Analyzed (mm2)	0.319
Analyst	JH	Analytical Sens. (struc/cc)	0.000990
		Dectection Limit. (struc/cc)	0.00296

Structure Type	Filter Density (s/mm2)	Concen-tration (struc/cc)	95% Confidence Interval (struc/cc)	Struc. Count
Primary Asbestos Structures	18.8	0.00594	0.00218 - 0.0129	6

Lab/Cor Sample No.	B4763 S3 A1	Volume (L)	1220
Client Sample No.	RHB-H2-2FD-100304	No. of Grid Openings	22
Description	Duplicate Analysis of 041172-32 -Different Grid Opening	Filter Area (mm2)	385
Analysis Date	12/6/2004	Area Analyzed (mm2)	0.319
Analyst	DW	Analytical Sens. (struc/cc)	0.000990
		Dectection Limit. (struc/cc)	0.00296

Structure Type	Filter Density (s/mm2)	Concen-tration (struc/cc)	95% Confidence Interval (struc/cc)	Struc. Count
Primary Asbestos Structures	12.5	0.00396	0.00108 - 0.0101	4

Lab/Cor, Inc.

A Professional Service Corporation in the Northwest

Report # 041172R3

Client: Ecology and Environment, Inc.

Project Name: Site# 0440.01CP, 0440.01CP-0001- FINAL RESULTS

ANALYSIS DETAIL

Lab/Cor Sample No. B4760 S33 A1
Client Sample No. RHB-H2-3FD-100304
Description
Analysis Date 11/3/2004
Analyst KM

Volume (L) 1140.7
No. of Grid Openings 23
Filter Area (mm2) 385
Area Analyzed (mm2) 0.333
Analytical Sens. (struc/cc) 0.00101
Dectection Limit. (struc/cc) 0.00303

Structure Type	Filter Density (s/mm2)	Concen-tration (struc/cc)	95% Confidence Interval (struc/cc)	Struc. Count
Primary Asbestos Structures	6.0	0.00203	0.00 - 0.00638	2
Total Asbestos Structures	6.0	0.00203	0.00 - 0.00638	2
Asbestos Structures > 5um	3.0	0.00101	0.00 - 0.00480	1
Asbestos Fibers and Bundles > 5um	3.0	0.00101	0.00 - 0.00480	1
PCM Equivalent Fibers-US	3.0	0.00101	0.00 - 0.00480	1
PCM Equivalent Structures-US	0.0	<0.00303	0.00 - 0.00303	0
PROTOCOL ASB STRUCS 5-10	0.0	<0.00303	0.00 - 0.00303	0
PROTOCOL ASB STRUCS >10	0.0	<0.00303	0.00 - 0.00303	0
PROTOCOL ASB STRUCS TOTAL	0.0	<0.00303	0.00 - 0.00303	0
PROTOCOL CHRYS STRUCS 5-10	0.0	<0.00303	0.00 - 0.00303	0
PROTOCOL CHRYS STRUCS >10	0.0	<0.00303	0.00 - 0.00303	0
PROTOCOL CHRYS STRUCS TOTAL	0.0	<0.00303	0.00 - 0.00303	0
PROTOCOL AMPH STRUCS 5-10	0.0	<0.00303	0.00 - 0.00303	0
PROTOCOL AMPH STRUCS >10	0.0	<0.00303	0.00 - 0.00303	0
PROTOCOL AMPH STRUCS TOTAL	0.0	<0.00303	0.00 - 0.00303	0
AHERA-like Total Structures 3:1	6.0	0.00203	0.00 - 0.00638	2
AHERA-like Asb Strucs >5 and 3:1	3.0	0.00101	0.00 - 0.00480	1
AHERA-like Asb Strucs 5 - 10 and 3:1	3.0	0.00101	0.00 - 0.00480	1
AHERA-like Asb Strucs >10 and 3:1	0.0	<0.00303	0.00 - 0.00303	0
Total Other Amphibole Strucs 3:1	0.0	<0.00303	0.00 - 0.00303	0
Other Amphibole Strucs >5 and 3:1	0.0	<0.00303	0.00 - 0.00303	0
Other Amphibole Strucs 5 - 10 and 3:1	0.0	<0.00303	0.00 - 0.00303	0
Other Amphibole Strucs >10 and 3:1	0.0	<0.00303	0.00 - 0.00303	0

Lab/Cor, Inc.

A Professional Service Corporation in the Northwest

Report # 041176R1

Client: Ecology and Environment, Inc.

Project Name: Site# 0440.01CP, 0440.01CP-0001- FINAL RESULTS

ANALYSIS DETAIL

Lab/Cor Sample No.	B4763 S4 A1	**Volume (L)**	1140.7
Client Sample No.	RHB-H2-3FD-100304	**No. of Grid Openings**	23
Description	Replicate Analysis of 041172-33 - Same Grid Openings	**Filter Area (mm2)**	385
Analysis Date	11/17/2004	**Area Analyzed (mm2)**	0.333
Analyst	KM	**Analytical Sens. (struc/cc)**	0.00101
		Dectection Limit. (struc/cc)	0.00303

Structure Type	Filter Density (s/mm2)	Concen-tration (struc/cc)	95% Confidence Interval (struc/cc)	Struc. Count
Primary Asbestos Structures	9.0	0.00304	0.00 - 0.00785	3

Lab/Cor, Inc.

A Professional Service Corporation in the Northwest

Report # 041176R1

Client: Ecology and Environment, Inc.

Project Name: Site# 0440.01CP, 0440.01CP-0001- FINAL RESULTS

ANALYSIS DETAIL

Lab/Cor Sample No.	B4763 S5 A1	**Volume (L)**	1140.7
Client Sample No.	RHB-H2-3FD-100304	**No. of Grid Openings**	23
Description	Duplicate Analysis of 041172-33 - Reprep	**Filter Area (mm2)**	385
Analysis Date	12/6/2004	**Area Analyzed (mm2)**	0.333
Analyst	JH	**Analytical Sens. (struc/cc)**	0.00101
		Dectection Limit. (struc/cc)	0.00303

Structure Type	Filter Density (s/mm2)	Concen-tration (struc/cc)	95% Confidence Interval (struc/cc)	Struc. Count
Primary Asbestos Structures	3.0	0.00101	0.00 - 0.00480	1

Lab/Cor, Inc.

A Professional Service Corporation in the Northwest

Report # 041172R6

Client: Ecology and Environment, Inc.

Project Name: Site# 0440.01CP, 0440.01CP-0001-FINAL RESULTS

ANALYSIS DETAIL

Lab/Cor Sample No. B4760 S59 A1
Client Sample No. RHB-H2-4FD-100304
Description
Analysis Date 12/9/2004
Analyst DW

Volume (L) 1207.2
No. of Grid Openings 23
Filter Area (mm2) 385
Area Analyzed (mm2) 0.333
Analytical Sens. (struc/cc) 0.000957
Dectection Limit. (struc/cc) 0.00286

Structure Type	Filter Density (s/mm2)	Concen-tration (struc/cc)	95% Confidence Interval (struc/cc)	Struc. Count
Primary Asbestos Structures	18.0	0.00574	0.00211 - 0.0125	6
Total Asbestos Structures	21.0	0.00670	0.00269 - 0.0138	7
Asbestos Structures > 5um	6.0	0.00191	0.00 - 0.00603	2
Asbestos Fibers and Bundles > 5um	0.0	<0.00286	0.00 - 0.00286	0
PCM Equivalent Fibers-US	0.0	<0.00286	0.00 - 0.00286	0
PCM Equivalent Structures-US	0.0	<0.00286	0.00 - 0.00286	0
PROTOCOL ASB STRUCS 5-10	0.0	<0.00286	0.00 - 0.00286	0
PROTOCOL ASB STRUCS >10	0.0	<0.00286	0.00 - 0.00286	0
PROTOCOL ASB STRUCS TOTAL	0.0	<0.00286	0.00 - 0.00286	0
PROTOCOL CHRYS STRUCS 5-10	0.0	<0.00286	0.00 - 0.00286	0
PROTOCOL CHRYS STRUCS >10	0.0	<0.00286	0.00 - 0.00286	0
PROTOCOL CHRYS STRUCS TOTAL	0.0	<0.00286	0.00 - 0.00286	0
PROTOCOL AMPH STRUCS 5-10	0.0	<0.00286	0.00 - 0.00286	0
PROTOCOL AMPH STRUCS >10	0.0	<0.00286	0.00 - 0.00286	0
PROTOCOL AMPH STRUCS TOTAL	0.0	<0.00286	0.00 - 0.00286	0
AHERA-like Total Structures 3:1	15.0	0.00478	0.00155 - 0.0112	5
AHERA-like Asb Strucs >5 and 3:1	6.0	0.00191	0.00 - 0.00603	2
AHERA-like Asb Strucs 5 - 10 and 3:1	3.0	0.000957	0.00 - 0.00454	1
AHERA-like Asb Strucs >10 and 3:1	3.0	0.000957	0.00 - 0.00454	1
Total Other Amphibole Strucs 3:1	0.0	<0.00286	0.00 - 0.00286	0
Other Amphibole Strucs >5 and 3:1	0.0	<0.00286	0.00 - 0.00286	0
Other Amphibole Strucs 5 - 10 and 3:1	0.0	<0.00286	0.00 - 0.00286	0
Other Amphibole Strucs >10 and 3:1	0.0	<0.00286	0.00 - 0.00286	0

Lab/Cor, Inc.

A Professional Service Corporation in the Northwest

Report # 041172R6

Client: Ecology and Environment, Inc.

Project Name: Site# 0440.01CP, 0440.01CP-0001-FINAL RESULTS

ANALYSIS DETAIL

Lab/Cor Sample No.	B4760 S60 A1	Volume (L)	1083.32
Client Sample No.	RHB-H2-5FD-100304	No. of Grid Openings	25
Description		Filter Area (mm2)	385
Analysis Date	12/9/2004	Area Analyzed (mm2)	0.362
Analyst	DW	Analytical Sens. (struc/cc)	0.000981
		Dectection Limit. (struc/cc)	0.00293

Structure Type	Filter Density (s/mm2)	Concen-tration (struc/cc)	95% Confidence Interval (struc/cc)	Struc. Count
Primary Asbestos Structures	2.8	0.000981	0.00 - 0.00465	1
Total Asbestos Structures	2.8	0.000981	0.00 - 0.00465	1
Asbestos Structures > 5um	0.0	<0.00293	0.00 - 0.00293	0
Asbestos Fibers and Bundles > 5um	0.0	<0.00293	0.00 - 0.00293	0
PCM Equivalent Fibers-US	0.0	<0.00293	0.00 - 0.00293	0
PCM Equivalent Structures-US	0.0	<0.00293	0.00 - 0.00293	0
PROTOCOL ASB STRUCS 5-10	0.0	<0.00293	0.00 - 0.00293	0
PROTOCOL ASB STRUCS >10	0.0	<0.00293	0.00 - 0.00293	0
PROTOCOL ASB STRUCS TOTAL	0.0	<0.00293	0.00 - 0.00293	0
PROTOCOL CHRYS STRUCS 5-10	0.0	<0.00293	0.00 - 0.00293	0
PROTOCOL CHRYS STRUCS >10	0.0	<0.00293	0.00 - 0.00293	0
PROTOCOL CHRYS STRUCS TOTAL	0.0	<0.00293	0.00 - 0.00293	0
PROTOCOL AMPH STRUCS 5-10	0.0	<0.00293	0.00 - 0.00293	0
PROTOCOL AMPH STRUCS >10	0.0	<0.00293	0.00 - 0.00293	0
PROTOCOL AMPH STRUCS TOTAL	0.0	<0.00293	0.00 - 0.00293	0
AHERA-like Total Structures 3:1	2.8	0.000981	0.00 - 0.00465	1
AHERA-like Asb Strucs >5 and 3:1	0.0	<0.00293	0.00 - 0.00293	0
AHERA-like Asb Strucs 5 - 10 and 3:1	0.0	<0.00293	0.00 - 0.00293	0
AHERA-like Asb Strucs >10 and 3:1	0.0	<0.00293	0.00 - 0.00293	0
Total Other Amphibole Strucs 3:1	0.0	<0.00293	0.00 - 0.00293	0
Other Amphibole Strucs >5 and 3:1	0.0	<0.00293	0.00 - 0.00293	0
Other Amphibole Strucs 5 - 10 and 3:1	0.0	<0.00293	0.00 - 0.00293	0
Other Amphibole Strucs >10 and 3:1	0.0	<0.00293	0.00 - 0.00293	0

Lab/Cor, Inc.

A Professional Service Corporation in the Northwest

Report # 041172R3

Client: Ecology and Environment, Inc.

Project Name: Site# 0440.01CP, 0440.01CP-0001- FINAL RESULTS

ANALYSIS DETAIL

Lab/Cor Sample No.	B4760 S34 A1	Volume (L)	309.12
Client Sample No.	RHB-L2-1CH-100304	No. of Grid Openings	86
Description		Filter Area (mm2)	385
Analysis Date	11/3/2004	Area Analyzed (mm2)	1.25
Analyst	TM	Analytical Sens. (struc/cc)	0.000999
		Dectection Limit. (struc/cc)	0.00299

Structure Type	Filter Density (s/mm2)	Concen-tration (struc/cc)	95% Confidence Interval (struc/cc)	Struc. Count
Primary Asbestos Structures	7.2	0.00900	0.00411 - 0.0171	9
Total Asbestos Structures	7.2	0.00900	0.00411 - 0.0171	9
Asbestos Structures > 5um	4.8	0.00600	0.00220 - 0.0131	6
Asbestos Fibers and Bundles > 5um	2.4	0.00300	0.00 - 0.00775	3
PCM Equivalent Fibers-US	2.4	0.00300	0.00 - 0.00775	3
PCM Equivalent Structures-US	2.4	0.00300	0.00 - 0.00775	3
PROTOCOL ASB STRUCS 5-10	0.8	0.000999	0.00 - 0.00474	1
PROTOCOL ASB STRUCS >10	0.0	<0.00299	0.00 - 0.00299	0
PROTOCOL ASB STRUCS TOTAL	0.8	0.000999	0.00 - 0.00474	1
PROTOCOL CHRYS STRUCS 5-10	0.8	0.000999	0.00 - 0.00474	1
PROTOCOL CHRYS STRUCS >10	0.0	<0.00299	0.00 - 0.00299	0
PROTOCOL CHRYS STRUCS TOTAL	0.8	0.000999	0.00 - 0.00474	1
PROTOCOL AMPH STRUCS 5-10	0.0	<0.00299	0.00 - 0.00299	0
PROTOCOL AMPH STRUCS >10	0.0	<0.00299	0.00 - 0.00299	0
PROTOCOL AMPH STRUCS TOTAL	0.0	<0.00299	0.00 - 0.00299	0
AHERA-like Total Structures 3:1	7.2	0.00900	0.00411 - 0.0171	9
AHERA-like Asb Strucs >5 and 3:1	4.8	0.00600	0.00220 - 0.0131	6
AHERA-like Asb Strucs 5 - 10 and 3:1	4.0	0.00500	0.00162 - 0.0117	5
AHERA-like Asb Strucs >10 and 3:1	0.8	0.000999	0.00 - 0.00474	1
Total Other Amphibole Strucs 3:1	0.0	<0.00299	0.00 - 0.00299	0
Other Amphibole Strucs >5 and 3:1	0.0	<0.00299	0.00 - 0.00299	0
Other Amphibole Strucs 5 - 10 and 3:1	0.0	<0.00299	0.00 - 0.00299	0
Other Amphibole Strucs >10 and 3:1	0.0	<0.00299	0.00 - 0.00299	0

Lab/Cor, Inc.

A Professional Service Corporation in the Northwest

Report # 041172R6

Client: Ecology and Environment, Inc.

Project Name: Site# 0440.01CP, 0440.01CP-0001-FINAL RESULTS

ANALYSIS DETAIL

Lab/Cor Sample No. B4760 S61 A1
Client Sample No. RHB-L2-14CH-100304
Description
Analysis Date 12/9/2004
Analyst DW

Volume (L) 301.32
No. of Grid Openings 89
Filter Area (mm2) 385
Area Analyzed (mm2) 1.29
Analytical Sens. (struc/cc) 0.000991
Dectection Limit. (struc/cc) 0.00296

Structure Type	Filter Density (s/mm2)	Concen-tration (struc/cc)	95% Confidence Interval (struc/cc)	Struc. Count
Primary Asbestos Structures	3.9	0.00495	0.00161 - 0.0116	5
Total Asbestos Structures	3.9	0.00495	0.00161 - 0.0116	5
Asbestos Structures > 5um	1.6	0.00198	0.00 - 0.00624	2
Asbestos Fibers and Bundles > 5um	1.6	0.00198	0.00 - 0.00624	2
PCM Equivalent Fibers-US	1.6	0.00198	0.00 - 0.00624	2
PCM Equivalent Structures-US	0.8	0.000991	0.00 - 0.00470	1
PROTOCOL ASB STRUCS 5-10	0.0	<0.00296	0.00 - 0.00296	0
PROTOCOL ASB STRUCS >10	0.0	<0.00296	0.00 - 0.00296	0
PROTOCOL ASB STRUCS TOTAL	0.0	<0.00296	0.00 - 0.00296	0
PROTOCOL CHRYS STRUCS 5-10	0.0	<0.00296	0.00 - 0.00296	0
PROTOCOL CHRYS STRUCS >10	0.0	<0.00296	0.00 - 0.00296	0
PROTOCOL CHRYS STRUCS TOTAL	0.0	<0.00296	0.00 - 0.00296	0
PROTOCOL AMPH STRUCS 5-10	0.0	<0.00296	0.00 - 0.00296	0
PROTOCOL AMPH STRUCS >10	0.0	<0.00296	0.00 - 0.00296	0
PROTOCOL AMPH STRUCS TOTAL	0.0	<0.00296	0.00 - 0.00296	0
AHERA-like Total Structures 3:1	3.9	0.00495	0.00161 - 0.0116	5
AHERA-like Asb Strucs >5 and 3:1	1.6	0.00198	0.00 - 0.00624	2
AHERA-like Asb Strucs 5 - 10 and 3:1	1.6	0.00198	0.00 - 0.00624	2
AHERA-like Asb Strucs >10 and 3:1	0.0	<0.00296	0.00 - 0.00296	0
Total Other Amphibole Strucs 3:1	0.0	<0.00296	0.00 - 0.00296	0
Other Amphibole Strucs >5 and 3:1	0.0	<0.00296	0.00 - 0.00296	0
Other Amphibole Strucs 5 - 10 and 3:1	0.0	<0.00296	0.00 - 0.00296	0
Other Amphibole Strucs >10 and 3:1	0.0	<0.00296	0.00 - 0.00296	0

Lab/Cor, Inc.

A Professional Service Corporation in the Northwest

Report # 041172R3

Client: Ecology and Environment, Inc.

Project Name: Site# 0440.01CP, 0440.01CP-0001- FINAL RESULTS

ANALYSIS DETAIL

Lab/Cor Sample No. B4760 S35 A1
Client Sample No. RHB-L2-2CH-100304
Description
Analysis Date 11/3/2004
Analyst DW

Volume (L) 293.4
No. of Grid Openings 91
Filter Area (mm2) 385
Area Analyzed (mm2) 1.32
Analytical Sens. (struc/cc) 0.000995
Dectection Limit. (struc/cc) 0.00298

Structure Type	Filter Density (s/mm2)	Concen-tration (struc/cc)	95% Confidence Interval (struc/cc)	Struc. Count
Primary Asbestos Structures	2.3	0.00299	0.00 - 0.00771	3
Total Asbestos Structures	2.3	0.00299	0.00 - 0.00771	3
Asbestos Structures > 5um	1.5	0.00199	0.00 - 0.00627	2
Asbestos Fibers and Bundles > 5um	1.5	0.00199	0.00 - 0.00627	2
PCM Equivalent Fibers-US	1.5	0.00199	0.00 - 0.00627	2
PCM Equivalent Structures-US	0.8	0.000995	0.00 - 0.00472	1
PROTOCOL ASB STRUCS 5-10	0.0	<0.00298	0.00 - 0.00298	0
PROTOCOL ASB STRUCS >10	0.0	<0.00298	0.00 - 0.00298	0
PROTOCOL ASB STRUCS TOTAL	0.0	<0.00298	0.00 - 0.00298	0
PROTOCOL CHRYS STRUCS 5-10	0.0	<0.00298	0.00 - 0.00298	0
PROTOCOL CHRYS STRUCS >10	0.0	<0.00298	0.00 - 0.00298	0
PROTOCOL CHRYS STRUCS TOTAL	0.0	<0.00298	0.00 - 0.00298	0
PROTOCOL AMPH STRUCS 5-10	0.0	<0.00298	0.00 - 0.00298	0
PROTOCOL AMPH STRUCS >10	0.0	<0.00298	0.00 - 0.00298	0
PROTOCOL AMPH STRUCS TOTAL	0.0	<0.00298	0.00 - 0.00298	0
AHERA-like Total Structures 3:1	2.3	0.00299	0.00 - 0.00771	3
AHERA-like Asb Strucs >5 and 3:1	1.5	0.00199	0.00 - 0.00627	2
AHERA-like Asb Strucs 5 - 10 and 3:1	0.8	0.000995	0.00 - 0.00472	1
AHERA-like Asb Strucs >10 and 3:1	0.8	0.000995	0.00 - 0.00472	1
Total Other Amphibole Strucs 3:1	0.0	<0.00298	0.00 - 0.00298	0
Other Amphibole Strucs >5 and 3:1	0.0	<0.00298	0.00 - 0.00298	0
Other Amphibole Strucs 5 - 10 and 3:1	0.0	<0.00298	0.00 - 0.00298	0
Other Amphibole Strucs >10 and 3:1	0.0	<0.00298	0.00 - 0.00298	0

Lab/Cor, Inc.

A Professional Service Corporation in the Northwest

Report # 041172R3

Client: Ecology and Environment, Inc.

Project Name: Site# 0440.01CP, 0440.01CP-0001- FINAL RESULTS

ANALYSIS DETAIL

Lab/Cor Sample No. B4760 S36 A1
Client Sample No. RHB-L2-3CH-100304
Description
Analysis Date 11/4/2004
Analyst JH

Volume (L) 306.48
No. of Grid Openings 87
Filter Area (mm2) 385
Area Analyzed (mm2) 1.26
Analytical Sens. (struc/cc) 0.000996
Dectection Limit. (struc/cc) 0.00298

Structure Type	Filter Density (s/mm2)	Concen-tration (struc/cc)	95% Confidence Interval (struc/cc)	Struc. Count
Primary Asbestos Structures	0.8	0.000996	0.00 - 0.00472	1
Total Asbestos Structures	0.8	0.000996	0.00 - 0.00472	1
Asbestos Structures > 5um	0.8	0.000996	0.00 - 0.00472	1
Asbestos Fibers and Bundles > 5um	0.8	0.000996	0.00 - 0.00472	1
PCM Equivalent Fibers-US	0.8	0.000996	0.00 - 0.00472	1
PCM Equivalent Structures-US	0.8	0.000996	0.00 - 0.00472	1
PROTOCOL ASB STRUCS 5-10	0.0	<0.00298	0.00 - 0.00298	0
PROTOCOL ASB STRUCS >10	0.0	<0.00298	0.00 - 0.00298	0
PROTOCOL ASB STRUCS TOTAL	0.0	<0.00298	0.00 - 0.00298	0
PROTOCOL CHRYS STRUCS 5-10	0.0	<0.00298	0.00 - 0.00298	0
PROTOCOL CHRYS STRUCS >10	0.0	<0.00298	0.00 - 0.00298	0
PROTOCOL CHRYS STRUCS TOTAL	0.0	<0.00298	0.00 - 0.00298	0
PROTOCOL AMPH STRUCS 5-10	0.0	<0.00298	0.00 - 0.00298	0
PROTOCOL AMPH STRUCS >10	0.0	<0.00298	0.00 - 0.00298	0
PROTOCOL AMPH STRUCS TOTAL	0.0	<0.00298	0.00 - 0.00298	0
AHERA-like Total Structures 3:1	0.8	0.000996	0.00 - 0.00472	1
AHERA-like Asb Strucs >5 and 3:1	0.8	0.000996	0.00 - 0.00472	1
AHERA-like Asb Strucs 5 - 10 and 3:1	0.8	0.000996	0.00 - 0.00472	1
AHERA-like Asb Strucs >10 and 3:1	0.0	<0.00298	0.00 - 0.00298	0
Total Other Amphibole Strucs 3:1	0.0	<0.00298	0.00 - 0.00298	0
Other Amphibole Strucs >5 and 3:1	0.0	<0.00298	0.00 - 0.00298	0
Other Amphibole Strucs 5 - 10 and 3:1	0.0	<0.00298	0.00 - 0.00298	0
Other Amphibole Strucs >10 and 3:1	0.0	<0.00298	0.00 - 0.00298	0

Lab/Cor, Inc.

A Professional Service Corporation in the Northwest

Report # 041172R3

Client: Ecology and Environment, Inc.

Project Name: Site# 0440.01CP, 0440.01CP-0001- FINAL RESULTS

ANALYSIS DETAIL

Lab/Cor Sample No.	B4760 S37 A1	Volume (L)	312.48
Client Sample No.	RHB-L2-4CH-100304	No. of Grid Openings	86
Description		Filter Area (mm2)	385
Analysis Date	11/4/2004	Area Analyzed (mm2)	1.25
Analyst	KM	Analytical Sens. (struc/cc)	0.000989
		Dectection Limit. (struc/cc)	0.00296

Structure Type	Filter Density (s/mm2)	Concen-tration (struc/cc)	95% Confidence Interval (struc/cc)	Struc. Count
Primary Asbestos Structures	3.2	0.00395	0.00108 - 0.0101	4
Total Asbestos Structures	3.2	0.00395	0.00108 - 0.0101	4
Asbestos Structures > 5um	2.4	0.00297	0.00 - 0.00766	3
Asbestos Fibers and Bundles > 5um	0.8	0.000989	0.00 - 0.00469	1
PCM Equivalent Fibers-US	0.8	0.000989	0.00 - 0.00469	1
PCM Equivalent Structures-US	0.8	0.000989	0.00 - 0.00469	1
PROTOCOL ASB STRUCS 5-10	0.0	<0.00296	0.00 - 0.00296	0
PROTOCOL ASB STRUCS >10	0.0	<0.00296	0.00 - 0.00296	0
PROTOCOL ASB STRUCS TOTAL	0.0	<0.00296	0.00 - 0.00296	0
PROTOCOL CHRYS STRUCS 5-10	0.0	<0.00296	0.00 - 0.00296	0
PROTOCOL CHRYS STRUCS >10	0.0	<0.00296	0.00 - 0.00296	0
PROTOCOL CHRYS STRUCS TOTAL	0.0	<0.00296	0.00 - 0.00296	0
PROTOCOL AMPH STRUCS 5-10	0.0	<0.00296	0.00 - 0.00296	0
PROTOCOL AMPH STRUCS >10	0.0	<0.00296	0.00 - 0.00296	0
PROTOCOL AMPH STRUCS TOTAL	0.0	<0.00296	0.00 - 0.00296	0
AHERA-like Total Structures 3:1	3.2	0.00395	0.00108 - 0.0101	4
AHERA-like Asb Strucs >5 and 3:1	2.4	0.00297	0.00 - 0.00766	3
AHERA-like Asb Strucs 5 - 10 and 3:1	2.4	0.00297	0.00 - 0.00766	3
AHERA-like Asb Strucs >10 and 3:1	0.0	<0.00296	0.00 - 0.00296	0
Total Other Amphibole Strucs 3:1	0.0	<0.00296	0.00 - 0.00296	0
Other Amphibole Strucs >5 and 3:1	0.0	<0.00296	0.00 - 0.00296	0
Other Amphibole Strucs 5 - 10 and 3:1	0.0	<0.00296	0.00 - 0.00296	0
Other Amphibole Strucs >10 and 3:1	0.0	<0.00296	0.00 - 0.00296	0

Lab/Cor, Inc.

A Professional Service Corporation in the Northwest

Report # 041172R3

Client: Ecology and Environment, Inc.

Project Name: Site# 0440.01CP, 0440.01CP-0001- FINAL RESULTS

ANALYSIS DETAIL

Lab/Cor Sample No. B4760 S38 A1
Client Sample No. RHB-L2-5CH-100304
Description
Analysis Date 11/4/2004
Analyst KM

Volume (L) 295.56
No. of Grid Openings 90
Filter Area (mm2) 385
Area Analyzed (mm2) 1.30
Analytical Sens. (struc/cc) 0.000999
Dectection Limit. (struc/cc) 0.00299

Structure Type	Filter Density (s/mm2)	Concen-tration (struc/cc)	95% Confidence Interval (struc/cc)	Struc. Count
Primary Asbestos Structures	3.1	0.00400	0.00109 - 0.0102	4
Total Asbestos Structures	3.1	0.00400	0.00109 - 0.0102	4
Asbestos Structures > 5um	1.5	0.00200	0.00 - 0.00629	2
Asbestos Fibers and Bundles > 5um	0.8	0.000999	0.00 - 0.00473	1
PCM Equivalent Fibers-US	0.8	0.000999	0.00 - 0.00473	1
PCM Equivalent Structures-US	0.8	0.000999	0.00 - 0.00473	1
PROTOCOL ASB STRUCS 5-10	0.0	<0.00299	0.00 - 0.00299	0
PROTOCOL ASB STRUCS >10	0.0	<0.00299	0.00 - 0.00299	0
PROTOCOL ASB STRUCS TOTAL	0.0	<0.00299	0.00 - 0.00299	0
PROTOCOL CHRYS STRUCS 5-10	0.0	<0.00299	0.00 - 0.00299	0
PROTOCOL CHRYS STRUCS >10	0.0	<0.00299	0.00 - 0.00299	0
PROTOCOL CHRYS STRUCS TOTAL	0.0	<0.00299	0.00 - 0.00299	0
PROTOCOL AMPH STRUCS 5-10	0.0	<0.00299	0.00 - 0.00299	0
PROTOCOL AMPH STRUCS >10	0.0	<0.00299	0.00 - 0.00299	0
PROTOCOL AMPH STRUCS TOTAL	0.0	<0.00299	0.00 - 0.00299	0
AHERA-like Total Structures 3:1	3.1	0.00400	0.00109 - 0.0102	4
AHERA-like Asb Strucs >5 and 3:1	1.5	0.00200	0.00 - 0.00629	2
AHERA-like Asb Strucs 5 - 10 and 3:1	1.5	0.00200	0.00 - 0.00629	2
AHERA-like Asb Strucs >10 and 3:1	0.0	<0.00299	0.00 - 0.00299	0
Total Other Amphibole Strucs 3:1	0.0	<0.00299	0.00 - 0.00299	0
Other Amphibole Strucs >5 and 3:1	0.0	<0.00299	0.00 - 0.00299	0
Other Amphibole Strucs 5 - 10 and 3:1	0.0	<0.00299	0.00 - 0.00299	0
Other Amphibole Strucs >10 and 3:1	0.0	<0.00299	0.00 - 0.00299	0

Lab/Cor, Inc.

A Professional Service Corporation in the Northwest

Report # 041172R6

Client: Ecology and Environment, Inc.

Project Name: Site# 0440.01CP, 0440.01CP-0001-FINAL RESULTS

ANALYSIS DETAIL

Lab/Cor Sample No. B4760 S62 A1
Client Sample No. RHB-L2-1NA-100304
Description
Analysis Date 12/10/2004
Analyst KM

Volume (L) 318.6
No. of Grid Openings 83
Filter Area (mm2) 385
Area Analyzed (mm2) 1.20
Analytical Sens. (struc/cc) 0.00100
Dectection Limit. (struc/cc) 0.00300

Structure Type	Filter Density (s/mm2)	Concen-tration (struc/cc)	95% Confidence Interval (struc/cc)	Struc. Count
Primary Asbestos Structures	4.2	0.00502	0.00163 - 0.0117	5
Total Asbestos Structures	4.2	0.00502	0.00163 - 0.0117	5
Asbestos Structures > 5um	0.8	0.00100	0.00 - 0.00476	1
Asbestos Fibers and Bundles > 5um	0.8	0.00100	0.00 - 0.00476	1
PCM Equivalent Fibers-US	0.8	0.00100	0.00 - 0.00476	1
PCM Equivalent Structures-US	0.8	0.00100	0.00 - 0.00476	1
PROTOCOL ASB STRUCS 5-10	0.0	<0.00300	0.00 - 0.00300	0
PROTOCOL ASB STRUCS >10	0.0	<0.00300	0.00 - 0.00300	0
PROTOCOL ASB STRUCS TOTAL	0.0	<0.00300	0.00 - 0.00300	0
PROTOCOL CHRYS STRUCS 5-10	0.0	<0.00300	0.00 - 0.00300	0
PROTOCOL CHRYS STRUCS >10	0.0	<0.00300	0.00 - 0.00300	0
PROTOCOL CHRYS STRUCS TOTAL	0.0	<0.00300	0.00 - 0.00300	0
PROTOCOL AMPH STRUCS 5-10	0.0	<0.00300	0.00 - 0.00300	0
PROTOCOL AMPH STRUCS >10	0.0	<0.00300	0.00 - 0.00300	0
PROTOCOL AMPH STRUCS TOTAL	0.0	<0.00300	0.00 - 0.00300	0
AHERA-like Total Structures 3:1	4.2	0.00502	0.00163 - 0.0117	5
AHERA-like Asb Strucs >5 and 3:1	0.8	0.00100	0.00 - 0.00476	1
AHERA-like Asb Strucs 5 - 10 and 3:1	0.0	<0.00300	0.00 - 0.00300	0
AHERA-like Asb Strucs >10 and 3:1	0.8	0.00100	0.00 - 0.00476	1
Total Other Amphibole Strucs 3:1	0.0	<0.00300	0.00 - 0.00300	0
Other Amphibole Strucs >5 and 3:1	0.0	<0.00300	0.00 - 0.00300	0
Other Amphibole Strucs 5 - 10 and 3:1	0.0	<0.00300	0.00 - 0.00300	0
Other Amphibole Strucs >10 and 3:1	0.0	<0.00300	0.00 - 0.00300	0

Lab/Cor, Inc.

A Professional Service Corporation in the Northwest

Report # 041172R6

Client: Ecology and Environment, Inc.

Project Name: Site# 0440.01CP, 0440.01CP-0001-FINAL RESULTS

ANALYSIS DETAIL

Lab/Cor Sample No. B4760 S63 A1
Client Sample No. RHB-L2-1ZB-100304
Description
Analysis Date 12/10/2004
Analyst DW

Volume (L) 326.4
No. of Grid Openings 88
Filter Area (mm2) 385
Area Analyzed (mm2) 1.28
Analytical Sens. (struc/cc) 0.000925
Dectection Limit. (struc/cc) 0.00277

Structure Type	Filter Density (s/mm2)	Concen-tration (struc/cc)	95% Confidence Interval (struc/cc)	Struc. Count
Primary Asbestos Structures	0.0	<0.00277	0.00 - 0.00277	0
Total Asbestos Structures	0.0	<0.00277	0.00 - 0.00277	0
Asbestos Structures > 5um	0.0	<0.00277	0.00 - 0.00277	0
Asbestos Fibers and Bundles > 5um	0.0	<0.00277	0.00 - 0.00277	0
PCM Equivalent Fibers-US	0.0	<0.00277	0.00 - 0.00277	0
PCM Equivalent Structures-US	0.0	<0.00277	0.00 - 0.00277	0
PROTOCOL ASB STRUCS 5-10	0.0	<0.00277	0.00 - 0.00277	0
PROTOCOL ASB STRUCS >10	0.0	<0.00277	0.00 - 0.00277	0
PROTOCOL ASB STRUCS TOTAL	0.0	<0.00277	0.00 - 0.00277	0
PROTOCOL CHRYS STRUCS 5-10	0.0	<0.00277	0.00 - 0.00277	0
PROTOCOL CHRYS STRUCS >10	0.0	<0.00277	0.00 - 0.00277	0
PROTOCOL CHRYS STRUCS TOTAL	0.0	<0.00277	0.00 - 0.00277	0
PROTOCOL AMPH STRUCS 5-10	0.0	<0.00277	0.00 - 0.00277	0
PROTOCOL AMPH STRUCS >10	0.0	<0.00277	0.00 - 0.00277	0
PROTOCOL AMPH STRUCS TOTAL	0.0	<0.00277	0.00 - 0.00277	0
AHERA-like Total Structures 3:1	0.0	<0.00277	0.00 - 0.00277	0
AHERA-like Asb Strucs >5 and 3:1	0.0	<0.00277	0.00 - 0.00277	0
AHERA-like Asb Strucs 5 - 10 and 3:1	0.0	<0.00277	0.00 - 0.00277	0
AHERA-like Asb Strucs >10 and 3:1	0.0	<0.00277	0.00 - 0.00277	0
Total Other Amphibole Strucs 3:1	0.0	<0.00277	0.00 - 0.00277	0
Other Amphibole Strucs >5 and 3:1	0.0	<0.00277	0.00 - 0.00277	0
Other Amphibole Strucs 5 - 10 and 3:1	0.0	<0.00277	0.00 - 0.00277	0
Other Amphibole Strucs >10 and 3:1	0.0	<0.00277	0.00 - 0.00277	0

Lab/Cor, Inc.

A Professional Service Corporation in the Northwest

Report # 041172R6

Client: Ecology and Environment, Inc.

Project Name: Site# 0440.01CP, 0440.01CP-0001-FINAL RESULTS

ANALYSIS DETAIL

Lab/Cor Sample No.	B4760 S64 A1	Volume (L)	0
Client Sample No.	RHB-L2-FB-100304	No. of Grid Openings	10
Description	FILTER BLANK	Filter Area (mm2)	385
Analysis Date	12/15/2004	Area Analyzed (mm2)	0.145
Analyst	KM	Analytical Sens. (struc/cc)	NA
		Dectection Limit. (struc/cc)	NA

Structure Type	Filter Density (s/mm2)	Concen-tration (struc/cc)	95% Confidence Interval (struc/cc)	Struc. Count
Primary Asbestos Structures	0.0	NA	NA	0
Total Asbestos Structures	0.0	NA	NA	0
Asbestos Structures > 5um	0.0	NA	NA	0
Asbestos Fibers and Bundles > 5um	0.0	NA	NA	0
PCM Equivalent Fibers-US	0.0	NA	NA	0
PCM Equivalent Structures-US	0.0	NA	NA	0
PROTOCOL ASB STRUCS 5-10	0.0	NA	NA	0
PROTOCOL ASB STRUCS >10	0.0	NA	NA	0
PROTOCOL ASB STRUCS TOTAL	0.0	NA	NA	0
PROTOCOL CHRYS STRUCS 5-10	0.0	NA	NA	0
PROTOCOL CHRYS STRUCS >10	0.0	NA	NA	0
PROTOCOL CHRYS STRUCS TOTAL	0.0	NA	NA	0
PROTOCOL AMPH STRUCS 5-10	0.0	NA	NA	0
PROTOCOL AMPH STRUCS >10	0.0	NA	NA	0
PROTOCOL AMPH STRUCS TOTAL	0.0	NA	NA	0
AHERA-like Total Structures 3:1	0.0	NA	NA	0
AHERA-like Asb Strucs >5 and 3:1	0.0	NA	NA	0
AHERA-like Asb Strucs 5 - 10 and 3:1	0.0	NA	NA	0
AHERA-like Asb Strucs >10 and 3:1	0.0	NA	NA	0
Total Other Amphibole Strucs 3:1	0.0	NA	NA	0
Other Amphibole Strucs >5 and 3:1	0.0	NA	NA	0
Other Amphibole Strucs 5 - 10 and 3:1	0.0	NA	NA	0
Other Amphibole Strucs >10 and 3:1	0.0	NA	NA	0

Lab/Cor, Inc.

A Professional Service Corporation in the Northwest

Report # 041172R3

Client: Ecology and Environment, Inc.

Project Name: Site# 0440.01CP, 0440.01CP-0001- FINAL RESULTS

ANALYSIS DETAIL

Lab/Cor Sample No. B4760 S12 A1
Client Sample No. CC2A-L6-1CA-100304
Description
Analysis Date 10/8/2004
Analyst TM

Volume (L) 269.72
No. of Grid Openings 99
Filter Area (mm2) 385
Area Analyzed (mm2) 1.43
Analytical Sens. (struc/cc) 0.000995
Dectection Limit. (struc/cc) 0.00298

Structure Type	Filter Density (s/mm2)	Concen-tration (struc/cc)	95% Confidence Interval (struc/cc)	Struc. Count
Primary Asbestos Structures	7.7	0.0109	0.00546 - 0.0196	11
Total Asbestos Structures	14.6	0.0209	0.0129 - 0.0319	21
Asbestos Structures > 5um	2.1	0.00299	0.00 - 0.00771	3
Asbestos Fibers and Bundles > 5um	0.0	<0.00298	0.00 - 0.00298	0
PCM Equivalent Fibers-US	0.7	0.000995	0.00 - 0.00472	1
PCM Equivalent Structures-US	0.7	0.000995	0.00 - 0.00472	1
PROTOCOL ASB STRUCS 5-10	0.0	<0.00298	0.00 - 0.00298	0
PROTOCOL ASB STRUCS >10	0.0	<0.00298	0.00 - 0.00298	0
PROTOCOL ASB STRUCS TOTAL	0.0	<0.00298	0.00 - 0.00298	0
PROTOCOL CHRYS STRUCS 5-10	0.0	<0.00298	0.00 - 0.00298	0
PROTOCOL CHRYS STRUCS >10	0.0	<0.00298	0.00 - 0.00298	0
PROTOCOL CHRYS STRUCS TOTAL	0.0	<0.00298	0.00 - 0.00298	0
PROTOCOL AMPH STRUCS 5-10	0.0	<0.00298	0.00 - 0.00298	0
PROTOCOL AMPH STRUCS >10	0.0	<0.00298	0.00 - 0.00298	0
PROTOCOL AMPH STRUCS TOTAL	0.0	<0.00298	0.00 - 0.00298	0
AHERA-like Total Structures 3:1	7.7	0.0109	0.00546 - 0.0196	11
AHERA-like Asb Strucs >5 and 3:1	2.1	0.00299	0.00 - 0.00771	3
AHERA-like Asb Strucs 5 - 10 and 3:1	2.1	0.00299	0.00 - 0.00771	3
AHERA-like Asb Strucs >10 and 3:1	0.0	<0.00298	0.00 - 0.00298	0
Total Other Amphibole Strucs 3:1	0.0	<0.00298	0.00 - 0.00298	0
Other Amphibole Strucs >5 and 3:1	0.0	<0.00298	0.00 - 0.00298	0
Other Amphibole Strucs 5 - 10 and 3:1	0.0	<0.00298	0.00 - 0.00298	0
Other Amphibole Strucs >10 and 3:1	0.0	<0.00298	0.00 - 0.00298	0

Lab/Cor, Inc.

A Professional Service Corporation in the Northwest

Report # 041172R3

Client: Ecology and Environment, Inc.

Project Name: Site# 0440.01CP, 0440.01CP-0001- FINAL RESULTS

ANALYSIS DETAIL

Lab/Cor Sample No. B4760 S14 A1
Client Sample No. CC2-L6-1CC-100304
Description
Analysis Date 10/9/2004
Analyst JH

Volume (L) 533.62
No. of Grid Openings 51
Filter Area (mm2) 385
Area Analyzed (mm2) 0.739
Analytical Sens. (struc/cc) 0.000976
Dectection Limit. (struc/cc) 0.00292

Structure Type	Filter Density (s/mm2)	Concen-tration (struc/cc)	95% Confidence Interval (struc/cc)	Struc. Count
Primary Asbestos Structures	2.7	0.00195	0.00 - 0.00615	2
Total Asbestos Structures	2.7	0.00195	0.00 - 0.00615	2
Asbestos Structures > 5um	1.4	0.000976	0.00 - 0.00463	1
Asbestos Fibers and Bundles > 5um	1.4	0.000976	0.00 - 0.00463	1
PCM Equivalent Fibers-US	0.0	<0.00292	0.00 - 0.00292	0
PCM Equivalent Structures-US	0.0	<0.00292	0.00 - 0.00292	0
PROTOCOL ASB STRUCS 5-10	0.0	<0.00292	0.00 - 0.00292	0
PROTOCOL ASB STRUCS >10	0.0	<0.00292	0.00 - 0.00292	0
PROTOCOL ASB STRUCS TOTAL	0.0	<0.00292	0.00 - 0.00292	0
PROTOCOL CHRYS STRUCS 5-10	0.0	<0.00292	0.00 - 0.00292	0
PROTOCOL CHRYS STRUCS >10	0.0	<0.00292	0.00 - 0.00292	0
PROTOCOL CHRYS STRUCS TOTAL	0.0	<0.00292	0.00 - 0.00292	0
PROTOCOL AMPH STRUCS 5-10	0.0	<0.00292	0.00 - 0.00292	0
PROTOCOL AMPH STRUCS >10	0.0	<0.00292	0.00 - 0.00292	0
PROTOCOL AMPH STRUCS TOTAL	0.0	<0.00292	0.00 - 0.00292	0
AHERA-like Total Structures 3:1	2.7	0.00195	0.00 - 0.00615	2
AHERA-like Asb Strucs >5 and 3:1	1.4	0.000976	0.00 - 0.00463	1
AHERA-like Asb Strucs 5 - 10 and 3:1	0.0	<0.00292	0.00 - 0.00292	0
AHERA-like Asb Strucs >10 and 3:1	1.4	0.000976	0.00 - 0.00463	1
Total Other Amphibole Strucs 3:1	0.0	<0.00292	0.00 - 0.00292	0
Other Amphibole Strucs >5 and 3:1	0.0	<0.00292	0.00 - 0.00292	0
Other Amphibole Strucs 5 - 10 and 3:1	0.0	<0.00292	0.00 - 0.00292	0
Other Amphibole Strucs >10 and 3:1	0.0	<0.00292	0.00 - 0.00292	0

Lab/Cor, Inc.

A Professional Service Corporation in the Northwest

Report # 041172R3

Client: Ecology and Environment, Inc.

Project Name: Site# 0440.01CP, 0440.01CP-0001- FINAL RESULTS

ANALYSIS DETAIL

Lab/Cor Sample No.	B4760 S13 A1	Volume (L)	530.45
Client Sample No.	CC2-L6-11CC-100304	No. of Grid Openings	51
Description		Filter Area (mm2)	385
Analysis Date	10/8/2004	Area Analyzed (mm2)	0.739
Analyst	DW	Analytical Sens. (struc/cc)	0.000982
		Dectection Limit. (struc/cc)	0.00294

Structure Type	Filter Density (s/mm2)	Concen-tration (struc/cc)	95% Confidence Interval (struc/cc)	Struc. Count
Primary Asbestos Structures	4.1	0.00295	0.00 - 0.00761	3
Total Asbestos Structures	2.7	0.00196	0.00 - 0.00619	2
Asbestos Structures > 5um	1.4	0.000982	0.00 - 0.00466	1
Asbestos Fibers and Bundles > 5um	1.4	0.000982	0.00 - 0.00466	1
PCM Equivalent Fibers-US	1.4	0.000982	0.00 - 0.00466	1
PCM Equivalent Structures-US	1.4	0.000982	0.00 - 0.00466	1
PROTOCOL ASB STRUCS 5-10	0.0	<0.00294	0.00 - 0.00294	0
PROTOCOL ASB STRUCS >10	0.0	<0.00294	0.00 - 0.00294	0
PROTOCOL ASB STRUCS TOTAL	0.0	<0.00294	0.00 - 0.00294	0
PROTOCOL CHRYS STRUCS 5-10	0.0	<0.00294	0.00 - 0.00294	0
PROTOCOL CHRYS STRUCS >10	0.0	<0.00294	0.00 - 0.00294	0
PROTOCOL CHRYS STRUCS TOTAL	0.0	<0.00294	0.00 - 0.00294	0
PROTOCOL AMPH STRUCS 5-10	0.0	<0.00294	0.00 - 0.00294	0
PROTOCOL AMPH STRUCS >10	0.0	<0.00294	0.00 - 0.00294	0
PROTOCOL AMPH STRUCS TOTAL	0.0	<0.00294	0.00 - 0.00294	0
AHERA-like Total Structures 3:1	4.1	0.00295	0.00 - 0.00761	3
AHERA-like Asb Strucs >5 and 3:1	2.7	0.00196	0.00 - 0.00619	2
AHERA-like Asb Strucs 5 - 10 and 3:1	1.4	0.000982	0.00 - 0.00466	1
AHERA-like Asb Strucs >10 and 3:1	1.4	0.000982	0.00 - 0.00466	1
Total Other Amphibole Strucs 3:1	0.0	<0.00294	0.00 - 0.00294	0
Other Amphibole Strucs >5 and 3:1	0.0	<0.00294	0.00 - 0.00294	0
Other Amphibole Strucs 5 - 10 and 3:1	0.0	<0.00294	0.00 - 0.00294	0
Other Amphibole Strucs >10 and 3:1	0.0	<0.00294	0.00 - 0.00294	0

Lab/Cor, Inc.

A Professional Service Corporation in the Northwest

Report # 041172R3

Client: Ecology and Environment, Inc.

Project Name: Site# 0440.01CP, 0440.01CP-0001- FINAL RESULTS

ANALYSIS DETAIL

Lab/Cor Sample No.	B4760 S15 A1	Volume (L)	523
Client Sample No.	CC2-L6-2CC-100304	No. of Grid Openings	51
Description		Filter Area (mm2)	385
Analysis Date	10/9/2004	Area Analyzed (mm2)	0.739
Analyst	KM	Analytical Sens. (struc/cc)	0.000996
		Dectection Limit. (struc/cc)	0.00298

Structure Type	Filter Density (s/mm2)	Concen-tration (struc/cc)	95% Confidence Interval (struc/cc)	Struc. Count
Primary Asbestos Structures	0.0	<0.00298	0.00 - 0.00298	0
Total Asbestos Structures	0.0	<0.00298	0.00 - 0.00298	0
Asbestos Structures > 5um	0.0	<0.00298	0.00 - 0.00298	0
Asbestos Fibers and Bundles > 5um	0.0	<0.00298	0.00 - 0.00298	0
PCM Equivalent Fibers-US	0.0	<0.00298	0.00 - 0.00298	0
PCM Equivalent Structures-US	0.0	<0.00298	0.00 - 0.00298	0
PROTOCOL ASB STRUCS 5-10	0.0	<0.00298	0.00 - 0.00298	0
PROTOCOL ASB STRUCS >10	0.0	<0.00298	0.00 - 0.00298	0
PROTOCOL ASB STRUCS TOTAL	0.0	<0.00298	0.00 - 0.00298	0
PROTOCOL CHRYS STRUCS 5-10	0.0	<0.00298	0.00 - 0.00298	0
PROTOCOL CHRYS STRUCS >10	0.0	<0.00298	0.00 - 0.00298	0
PROTOCOL CHRYS STRUCS TOTAL	0.0	<0.00298	0.00 - 0.00298	0
PROTOCOL AMPH STRUCS 5-10	0.0	<0.00298	0.00 - 0.00298	0
PROTOCOL AMPH STRUCS >10	0.0	<0.00298	0.00 - 0.00298	0
PROTOCOL AMPH STRUCS TOTAL	0.0	<0.00298	0.00 - 0.00298	0
AHERA-like Total Structures 3:1	0.0	<0.00298	0.00 - 0.00298	0
AHERA-like Asb Strucs >5 and 3:1	0.0	<0.00298	0.00 - 0.00298	0
AHERA-like Asb Strucs 5 - 10 and 3:1	0.0	<0.00298	0.00 - 0.00298	0
AHERA-like Asb Strucs >10 and 3:1	0.0	<0.00298	0.00 - 0.00298	0
Total Other Amphibole Strucs 3:1	0.0	<0.00298	0.00 - 0.00298	0
Other Amphibole Strucs >5 and 3:1	0.0	<0.00298	0.00 - 0.00298	0
Other Amphibole Strucs 5 - 10 and 3:1	0.0	<0.00298	0.00 - 0.00298	0
Other Amphibole Strucs >10 and 3:1	0.0	<0.00298	0.00 - 0.00298	0

Lab/Cor, Inc.

A Professional Service Corporation in the Northwest

Report # 041172R3

Client: Ecology and Environment, Inc.

Project Name: Site# 0440.01CP, 0440.01CP-0001- FINAL RESULTS

ANALYSIS DETAIL

Lab/Cor Sample No. B4760 S16 A1
Client Sample No. CC2-L6-3CC-100304
Description
Analysis Date 10/9/2004
Analyst KM

Volume (L) 520.12
No. of Grid Openings 52
Filter Area (mm2) 385
Area Analyzed (mm2) 0.753
Analytical Sens. (struc/cc) 0.000982
Dectection Limit. (struc/cc) 0.00294

Structure Type	Filter Density (s/mm2)	Concen-tration (struc/cc)	95% Confidence interval (struc/cc)	Struc. Count
Primary Asbestos Structures	14.6	0.0108	0.00539 - 0.0193	11
Total Asbestos Structures	14.6	0.0108	0.00539 - 0.0193	11
Asbestos Structures > 5um	8.0	0.00589	0.00216 - 0.0128	6
Asbestos Fibers and Bundles > 5um	6.6	0.00491	0.00160 - 0.0115	5
PCM Equivalent Fibers-US	6.6	0.00491	0.00160 - 0.0115	5
PCM Equivalent Structures-US	5.3	0.00393	0.00107 - 0.0101	4
PROTOCOL ASB STRUCS 5-10	0.0	<0.00294	0.00 - 0.00294	0
PROTOCOL ASB STRUCS >10	0.0	<0.00294	0.00 - 0.00294	0
PROTOCOL ASB STRUCS TOTAL	0.0	<0.00294	0.00 - 0.00294	0
PROTOCOL CHRYS STRUCS 5-10	0.0	<0.00294	0.00 - 0.00294	0
PROTOCOL CHRYS STRUCS >10	0.0	<0.00294	0.00 - 0.00294	0
PROTOCOL CHRYS STRUCS TOTAL	0.0	<0.00294	0.00 - 0.00294	0
PROTOCOL AMPH STRUCS 5-10	0.0	<0.00294	0.00 - 0.00294	0
PROTOCOL AMPH STRUCS >10	0.0	<0.00294	0.00 - 0.00294	0
PROTOCOL AMPH STRUCS TOTAL	0.0	<0.00294	0.00 - 0.00294	0
AHERA-like Total Structures 3:1	14.6	0.0108	0.00539 - 0.0193	11
AHERA-like Asb Strucs >5 and 3:1	8.0	0.00589	0.00216 - 0.0128	6
AHERA-like Asb Strucs 5 - 10 and 3:1	4.0	0.00295	0.00 - 0.00761	3
AHERA-like Asb Strucs >10 and 3:1	4.0	0.00295	0.00 - 0.00761	3
Total Other Amphibole Strucs 3:1	0.0	<0.00294	0.00 - 0.00294	0
Other Amphibole Strucs >5 and 3:1	0.0	<0.00294	0.00 - 0.00294	0
Other Amphibole Strucs 5 - 10 and 3:1	0.0	<0.00294	0.00 - 0.00294	0
Other Amphibole Strucs >10 and 3:1	0.0	<0.00294	0.00 - 0.00294	0

Lab/Cor, Inc.

A Professional Service Corporation in the Northwest

Report # 041172R3

Client: Ecology and Environment, Inc.

Project Name: Site# 0440.01CP, 0440.01CP-0001- FINAL RESULTS

ANALYSIS DETAIL

Lab/Cor Sample No.	B4760 S17 A1	Volume (L)	542.69
Client Sample No.	CC2-L6-4CC-100304	No. of Grid Openings	49
Description		Filter Area (mm2)	385
Analysis Date	10/9/2004	Area Analyzed (mm2)	0.710
Analyst	KM	Analytical Sens. (struc/cc)	0.000999
		Dectection Limit. (struc/cc)	0.00299

Structure Type	Filter Density (s/mm2)	Concen-tration (struc/cc)	95% Confidence Interval (struc/cc)	Struc. Count
Primary Asbestos Structures	21.1	0.0150	0.00839 - 0.0247	15
Total Asbestos Structures	21.1	0.0150	0.00839 - 0.0247	15
Asbestos Structures > 5um	5.6	0.00400	0.00109 - 0.0102	4
Asbestos Fibers and Bundles > 5um	4.2	0.00300	0.00 - 0.00774	3
PCM Equivalent Fibers-US	5.6	0.00400	0.00109 - 0.0102	4
PCM Equivalent Structures-US	4.2	0.00300	0.00 - 0.00774	3
PROTOCOL ASB STRUCS 5-10	1.4	0.000999	0.00 - 0.00474	1
PROTOCOL ASB STRUCS >10	0.0	<0.00299	0.00 - 0.00299	0
PROTOCOL ASB STRUCS TOTAL	1.4	0.000999	0.00 - 0.00474	1
PROTOCOL CHRYS STRUCS 5-10	0.0	<0.00299	0.00 - 0.00299	0
PROTOCOL CHRYS STRUCS >10	0.0	<0.00299	0.00 - 0.00299	0
PROTOCOL CHRYS STRUCS TOTAL	0.0	<0.00299	0.00 - 0.00299	0
PROTOCOL AMPH STRUCS 5-10	1.4	0.000999	0.00 - 0.00474	1
PROTOCOL AMPH STRUCS >10	0.0	<0.00299	0.00 - 0.00299	0
PROTOCOL AMPH STRUCS TOTAL	1.4	0.000999	0.00 - 0.00474	1
AHERA-like Total Structures 3:1	21.1	0.0150	0.00839 - 0.0247	15
AHERA-like Asb Strucs >5 and 3:1	5.6	0.00400	0.00109 - 0.0102	4
AHERA-like Asb Strucs 5 - 10 and 3:1	4.2	0.00300	0.00 - 0.00774	3
AHERA-like Asb Strucs >10 and 3:1	1.4	0.000999	0.00 - 0.00474	1
Total Other Amphibole Strucs 3:1	0.0	<0.00299	0.00 - 0.00299	0
Other Amphibole Strucs >5 and 3:1	0.0	<0.00299	0.00 - 0.00299	0
Other Amphibole Strucs 5 - 10 and 3:1	0.0	<0.00299	0.00 - 0.00299	0
Other Amphibole Strucs >10 and 3:1	0.0	<0.00299	0.00 - 0.00299	0

Lab/Cor, Inc.

A Professional Service Corporation in the Northwest

Report # 041172R3

Client: Ecology and Environment, Inc.

Project Name: Site# 0440.01CP, 0440.01CP-0001- FINAL RESULTS

TEM ASBESTOS STRUCTURE COUNT - RAW DATA

Sample No.: RHB-H2-1FD-100304 *Lab/Cor Sample No.:* B4760 S31 A1

Descripiton:

Gr	No.	Loc.	ID	Prim	Tot	Class	Len	Wid	Asp	Neg#	EDS#	Comment	Count Categories
A	1	A43		NSD									
A	2	A23		NSD									
A	3	A3		NSD									
A	4	D23		NSD									
A	5	D43		NSD									
A	6	D41		NSD									
A	7	D21		NSD									
A	8	D1		NSD									
A	9	A11		NSD									
A	10	A31		NSD									
A	11	B40		NSD									
A	12	B20		NSD									
B	13	B42		NSD									
B	14	B22		NSD									
B	15	C2		NSD									
B	16	C22		NSD									
B	17	C42	AZQ	1	1	F	7	1.7	4.1	978	71.1	Mg, Al, Si, Ca, Fe Actinolite Zone Axis [1 0 0] - KM	AS>5, AFB>5, PCMEF-US, PCMES-US, TAS_AHRA, AS>5_AHRA, AS5-10_AHRA
B	18	C40		NSD									
B	19	C20		NSD									
B	20	B10		NSD									
B	21	A41		NSD									
B	22	A11		NSD									
B	23	D1		NSD									

Lab/Cor, Inc.

A Professional Service Corporation in the Northwest

Report # 041172R3

Client: Ecology and Environment, Inc.

Project Name: Site# 0440.01CP, 0440.01CP-0001- FINAL RESULTS

TEM ASBESTOS STRUCTURE COUNT - RAW DATA

Sample No.: RHB-H2-2FD-100304 *Lab/Cor Sample No.:* B4760 S32 A1

Descripiton:

Gr	No.	Loc.	ID	Prim	Tot	Class	Len	Wid	Asp	Neg#	EDS#	Comment	Count Categories
A	1	A43		NSD									
A	2	A23		NSD									
A	3	A3		NSD									
A	4	D13		NSD									
A	5	D33	AZQ	1	1	F	4.9	0.7	7.0	979	15504	Mg, Al, Si, Ca, Fe Actinolite Zone Axis [1 0 0] - KM	TAS_AHRA
A	6	D41		NSD									
A	7	D21	AQ	2		MD1-0	4.3	2.7	1.6			Actinolite	TAS_AHRA
A	7	D21	AQ		2	MF	4	0.45	8.9			Mg, Al, Si, Ca, Fe Actinolite	
A	8	D1		NSD									
A	9	A11		NSD									
A	10	B40		NSD									
A	11	B20		NSD									
A	12	C1		NSD									
B	13	B43	AQ	3	3	F	4.8	1.2	4.0			Mg, Al, Si, Ca, Fe Actinolite	TAS_AHRA
B	14	B23		NSD									
B	15	B3		NSD									
B	16	C13		NSD									
B	17	C43		NSD									
B	18	C41	AQ	4	4	F	11	1	11			Mg, Al, Si, Ca, Fe Actinolite	AS>5, AFB>5, PCMEF-US, PCMES-US, TAS_AHRA, AS>5_AHRA, AS>10_AHRA
B	19	C21		NSD									
B	20	C1		NSD									
B	21	B11		NSD									
B	22	B31	AQ	5	5	F	7.7	0.5	15			Mg, Al, Si, Ca, Fe Actinolite	AS>5, AFB>5, PCMEF-US, PCMES-US, PSAS 5-10, PSAS TOT, PSAM 5-10, PSAM TOT, TAS_AHRA, AS>5_AHRA, AS5-10_AHRA
B	22	B31	AQ	6	6	F	6	1.5	4.0			Mg, Al, Si, Ca, Fe Actinolite	AS>5, AFB>5, PCMEF-US, PCMES-US, TAS_AHRA, AS>5_AHRA, AS5-10_AHRA

Lab/Cor, Inc.

A Professional Service Corporation in the Northwest

Report # 041176R1

Client: Ecology and Environment, Inc.

Project Name: Site# 0440.01CP, 0440.01CP-0001- FINAL RESULTS

TEM ASBESTOS STRUCTURE COUNT - RAW DATA

Sample No.: RHB-H2-2FD-100304 *Lab/Cor Sample No.:* B4763 S1 A1

Descripiton: Replicate Analysis of 041172-32 - Same Grid Openings

Gr	No.	Loc.	ID	Prim	Tot	Class	Len	Wid	Asp	Neg#	EDS#	Comment	Count Categories
A	1	A43		NSD									
A	2	A23		NSD									
A	3	A3		NSD									
A	4	D13		NSD									
A	5	D33	AQ	1	1	F	4.7	0.6	7.8			Mg, Al, Si, Ca, Fe Actinolite	
A	6	D41		NSD									
A	7	D21	AQ	2	2	F	4	0.5	8.0			Mg, Al, Si, Ca, Fe Actinolite	
A	8	D1		NSD									
A	9	A11		NSD									
A	10	B40		NSD									
A	11	B20		NSD									
A	12	C1		NSD									
B	13	B43	AQ	3	3	F	4	1.3	3.1			Mg, Al, Si, Ca, Fe Actinolite	
B	14	B23		NSD									
B	15	B3		NSD									
B	16	C3		NSD									
B	17	C43		NSD									
B	18	C41	AQ	4	4	F	11	0.9	12			Mg, Al, Si, Ca, Fe Actinolite	
B	19	C21		NSD									
B	20	C1		NSD									
B	21	B11		NSD									
B	22	B31	AQ	5	5	F	8	0.5	16			Mg, Al, Si, Ca, Fe Actinolite	
B	22	B31	AQ	6	6	F	6	1.2	5.0			Mg, Al, Si, Ca, Fe Actinolite	

Lab/Cor, Inc.

A Professional Service Corporation in the Northwest

Report # 041176R1

Client: Ecology and Environment, Inc.

Project Name: Site# 0440.01CP, 0440.01CP-0001- FINAL RESULTS

TEM ASBESTOS STRUCTURE COUNT - RAW DATA

Sample No.: RHB-H2-2FD-100304 *Lab/Cor Sample No.:* B4763 S3 A1

Descripiton: Duplicate Analysis of 041172-32 -Different Grid Openings

Gr	No.	Loc.	ID	Prim	Tot	Class	Len	Wid	Asp	Neg#	EDS#	Comment	Count Categories
A	1	A42		NSD									
A	2	A22		NSD									
A	3	A2		NSD									
A	4	D12		NSD									
A	5	D32		NSD									
A	6	D21		NSD									
A	7	D1	CDQ	1		MD1-0	7.5	4	1.9			Chrysotile	
A	7	D1	CDQ		1	MF	1.2	0.1	12			Mg, Si Chrysotile	
A	8	A11		NSD									
A	9	A31		NSD									
A	10	B40		NSD									
A	11	B20		NSD									
B	12	B41		NSD									
B	13	B21		NSD									
B	14	B1		NSD									
B	15	C11		NSD									
B	16	C31		NSD									
B	17	B43	AQ	2		MD1-0	12	10	1.2			Actinolite	
B	17	B43	AQ		2	MF	1.5	0.4	3.8			Mg, Al, Si, Ca, Fe Actinolite	
B	18	B23		NSD									
B	19	B3	AQ	3		MD1-1	10	10	1.0			Actinolite	
B	19	B3	AQ		3	MF	5.5	1.5	3.7			Mg, Al, Si, Ca, Fe Actinolite	
B	20	C13		NSD									
B	21	B14	AQ	4		MD1-1	10	10	1.0			Actinolite	
B	21	B14	AQ		4	MF	9	1.5	6.0			Mg, Al, Si, Ca, Fe Actinolite	
B	22	B34		NSD									

Lab/Cor, Inc.

A Professional Service Corporation in the Northwest

Report # 041172R3

Client: Ecology and Environment, Inc.

Project Name: Site# 0440.01CP, 0440.01CP-0001- FINAL RESULTS

TEM ASBESTOS STRUCTURE COUNT - RAW DATA

Sample No.: RHB-H2-3FD-100304 *Lab/Cor Sample No.:* B4760 S33 A1

Descripiton:

Gr	No.	Loc.	ID	Prim	Tot	Class	Len	Wid	Asp	Neg#	EDS#	Comment	Count Categories
A	1	B42		NSD									
A	2	B12		NSD									
A	3	C12		NSD									
A	4	B14		NSD									
A	5	C14		NSD									
A	6	C44		NSD									
A	7	A20		NSD									
A	8	D10		NSD									
B	9	A32		NSD									
B	10	A2		NSD									
B	11	D22		NSD									
B	12	B31		NSD									
B	13	B1		NSD									
B	14	C21		NSD									
B	15	B13		NSD									
B	16	C3		NSD									
C	17	B23	CDQ	1	1	F	1	0.05	20	980	713	Mg, Si Chrysotile Verified - KM	TAS_AHRA
C	18	B43		NSD									
C	19	B3		NSD									
C	20	C13	AZQ	2		MD1-1	6	6	1.0			Mg, Al, Si, Ca, Fe Actinolite	AS>5, TAS_AHRA, AS>5_AHRA, AS5-10_AHRA
C	20	C13	AZQ		2	MF	8	0.75	11	5438	15505	Mg, Al, Si, Ca, Fe Actinolite Zone Axis [5 1 4] - KM	AFB>5, PCMEF-US
C	21	C33		NSD									
C	22	C42		NSD									
C	23	C22		NSD									

Lab/Cor, Inc.

A Professional Service Corporation in the Northwest

Report # 041176R1

Client: Ecology and Environment, Inc.

Project Name: Site# 0440.01CP, 0440.01CP-0001- FINAL RESULTS

TEM ASBESTOS STRUCTURE COUNT - RAW DATA

Sample No.: RHB-H2-3FD-100304 *Lab/Cor Sample No.:* B4763 S4 A1

Descripiton: Replicate Analysis of 041172-33 - Same Grid Openings

Gr	No.	Loc.	ID	Prim	Tot	Class	Len	Wid	Asp	Neg#	EDS#	Comment	Count Categories
A	1	A20	AQ	1	1	F	6	1.5	4.0			Mg, Al, Si, Ca, Fe Actinolite	
A	2	B12		NSD									
A	3	B14		NSD									
A	4	C12		NSD									
A	5	C14		NSD									
A	6	C44	ADQ	2	2	F	11	0.9	12			Mg, Al, Si, Ca, Fe Actinolite	
A	7	B42		NSD									
A	8	D10		NSD									
B	9	A2		NSD									
B	10	A32		NSD									
B	11	B1		NSD									
B	12	B13		NSD									
B	13	B31		NSD									
B	14	C21		NSD									
B	15	C3		NSD									
B	16	D22		NSD									
C	17	B23		NSD									
C	18	B3		NSD									
C	19	B43		NSD									
C	20	C13	AQ	3	3	F	4.5	0.38	12			Mg, Al, Si, Ca, Fe Actinolite	
C	21	C33		NSD									
C	22	C22		NSD									
C	23	C42		NSD									

Lab/Cor, Inc.

A Professional Service Corporation in the Northwest

Report # 041176R1

Client: Ecology and Environment, Inc.

Project Name: Site# 0440.01CP, 0440.01CP-0001- FINAL RESULTS

TEM ASBESTOS STRUCTURE COUNT - RAW DATA

Sample No.: RHB-H2-3FD-100304 *Lab/Cor Sample No.:* B4763 S5 A1

Descripiton: Duplicate Analysis of 041172-33 - Reprep

Gr	No.	Loc.	ID	Prim	Tot	Class	Len	Wid	Asp	Neg#	EDS#	Comment	Count Categories
A	1	A32		NSD									
A	2	A12		NSD									
A	3	D2		NSD									
A	4	D22		NSD									
A	5	D42		NSD									
A	6	D40		NSD									
A	7	D10		NSD									
A	8	A20		NSD									
A	9	A40		NSD									
A	10	B32		NSD									
A	11	B12		NSD									
A	12	C2		NSD									
A	13	C22	AQ	1	1	F	2.6	0.8	3.2			Mg, Al, Si, Ca, Fe Actinolite	
B	14	B32		NSD									
B	15	B12		NSD									
B	16	C2		NSD									
B	17	C22		NSD									
B	18	C42		NSD									
B	19	D40		NSD									
B	20	D10		NSD									
B	21	A10		NSD									
B	22	A30		NSD									
B	23	A22		NSD									

Lab/Cor, Inc.

A Professional Service Corporation in the Northwest

Report # 041172R6

Client: Ecology and Environment, Inc.

Project Name: Site# 0440.01CP, 0440.01CP-0001-FINAL RESULTS

TEM ASBESTOS STRUCTURE COUNT - RAW DATA

Sample No.: RHB-H2-4FD-100304 *Lab/Cor Sample No.:* B4760 S59 A1

Descripiton:

Gr	No.	Loc.	ID	Prim	Tot	Class	Len	Wid	Asp	Neg#	EDS#	Comment	Count Categories
A	1	B44		NSD									
A	2	B24	CDQ	1		MD2-0	3	2.5	1.2			Chrysotile	TAS_AHRA
A	2	B24	CDQ		1	MF	2	0.1	20	5684	15536	Mg, Si Chrysotile Verified - KM	
A	2	B24	CDQ		2	MF	1	0.1	10			Mg, Si Chrysotile	
A	3	B4		NSD									
A	4	C14		NSD									
A	5	C34		NSD									
A	6	C43		NSD									
A	7	C42		NSD									
A	8	C22		NSD									
A	9	C2		NSD									
A	10	B12		NSD									
A	11	B42		NSD									
A	12	B41	AQ	2		MD1-0	7.5	5	1.5			Actinolite	AS>5, TAS_AHRA, AS>5_AHRA, AS5-10_AHRA
A	12	B41	AQ		3	MF	3.75	0.85	4.4			Mg, Al, Si, Ca, Fe Actinolite	
A	13	B21	CDQ	3		MD1-0	15	15	1.0			Chrysotile	AS>5, TAS_AHRA, AS>5_AHRA, AS>10_AHRA
A	13	B21	CDQ		4	MF	2	0.1	20			Mg, Si Chrysotile	
A	14	B1		NSD									
B	15	B42	CDQ	4	5	CC10-0	4	4	1.0			Mg, Si Chrysotile	
B	16	B21		NSD									
B	17	B1		NSD									
B	18	D41		NSD									
B	19	D21		NSD									
B	20	D1		NSD									
B	21	A11	AZQ	5	6	F	2.5	0.6	4.2	5685	15537	Mg, Al, Si, Ca, Fe Actinolite Zone Axis - [3 -1 2] - KBM	TAS_AHRA
B	22	A42	CMQ	6		MD1-0	2.5	2.5	1.0			Chrysotile	TAS_AHRA
B	22	A42	CMQ		7	MF	2	0.1	20			Mg, Si Chrysotile	
B	23	A22		NSD									

Lab/Cor, Inc.

A Professional Service Corporation in the Northwest

Report # 041172R6

Client: Ecology and Environment, Inc.

Project Name: Site# 0440.01CP, 0440.01CP-0001-FINAL RESULTS

TEM ASBESTOS STRUCTURE COUNT - RAW DATA

Sample No.: RHB-H2-5FD-100304 *Lab/Cor Sample No.:* B4760 S60 A1

Descripiton:

Gr	No.	Loc.	ID	Prim	Tot	Class	Len	Wid	Asp	Neg#	EDS#	Comment	Count Categories
A	1	B44		NSD									
A	2	B24		NSD									
A	3	B4		NSD									
A	4	C14		NSD									
A	5	C34		NSD									
A	6	C43		NSD									
A	7	C42		NSD									
A	8	C22		NSD									
A	9	C2		NSD									
A	10	B12		NSD									
A	11	B32		NSD									
A	12	B41		NSD									
A	13	B21		NSD									
A	14	B1		NSD									
B	15	B43		NSD									
B	16	B23		NSD									
B	17	B3		NSD									
B	18	C13		NSD									
B	19	C33		NSD									
B	20	C41		NSD									
B	21	C21		NSD									
B	22	C1		NSD									
B	23	B11	AZQ	1	1	F	2.5	0.8	3.1	5686	15538	Mg, Al, Si, Ca, Fe Actinolite Zone Axis [2 0 3] - KBM	TAS_AHRA
B	24	B31		NSD									
B	25	B40		NSD									

Lab/Cor, Inc.

A Professional Service Corporation in the Northwest

Report # 041172R3

Client: Ecology and Environment, Inc.

Project Name: Site# 0440.01CP, 0440.01CP-0001- FINAL RESULTS

TEM ASBESTOS STRUCTURE COUNT - RAW DATA

Sample No.: RHB-L2-1CH-100304 *Lab/Cor Sample No.:* B4760 S34 A1

Descripiton:

Gr	No.	Loc.	ID	Prim	Tot	Class	Len	Wid	Asp	Neg#	EDS#	Comment	Count Categories
A	1	B44		NSD									
A	2	B24		NSD									
A	3	B4		NSD									
A	4	C14		NSD									
A	5	C34		NSD									
A	6	C43		NSD									
A	7	C23		NSD									
A	8	C3		NSD									
A	9	B13		NSD									
A	10	B33		NSD									
A	11	B42		NSD									
A	12	B22		NSD									
A	13	B2		NSD									
A	14	C12		NSD									
A	15	C32		NSD									
A	16	C41		NSD									
A	17	C21		NSD									
A	18	C1		NSD									
A	19	B11	CDQ	1		MD1-0	6	3.5	1.7			Chrysotile	AS>5, TAS_AHRA, AS>5_AHRA, AS5-10_AHRA
A	19	B11	CDQ		1	MF	0.95	0.1	9.5	5402	15298	Mg, Si, Fe Chrysotile Verified - KM	
A	20	B41		NSD									
A	21	B40		NSD									
A	22	B20		NSD									
A	23	C10	AZQ	2		MD1-0	4	2.5	1.6			Actinolite	TAS_AHRA
A	23	C10	AZQ		2	MF	2	0.25	8.0	5403	15299	Mg, Si, Ca, Fe Actinolite Zone Axis [3 1 -2] - KM	
A	24	C30		NSD									
A	25	D40		NSD									
A	26	D20	AQ	3		MD1-0	25.5	4.25	6.0			Actinolite	AS>5, TAS_AHRA, AS>5_AHRA, AS>10_AHRA
A	26	D20	AQ		3	MF	4.25	0.45	9.4			Mg, Al, Si, Ca, Fe Actinolite Alumino-actinolite	
A	27	A10		NSD									
A	28	A30		NSD									
A	29	A41		NSD									

Lab/Cor, Inc.

A Professional Service Corporation in the Northwest

Report # 041172R3

Client: Ecology and Environment, Inc.

Project Name: Site# 0440.01CP, 0440.01CP-0001- FINAL RESULTS

TEM ASBESTOS STRUCTURE COUNT - RAW DATA

Sample No.: RHB-L2-1CH-100304 *Lab/Cor Sample No.:* B4760 S34 A1

Descripiton:

Gr	No.	Loc.	ID	Prim	Tot	Class	Len	Wid	Asp	Neg#	EDS#	Comment	Count Categories
B	30	B44		NSD									
B	31	B44		NSD									
B	32	B34		NSD									
B	33	B24		NSD									
B	34	B14	AQ	4	4	F	3.3	0.6	5.5			Mg, Al, Si, Ca, Fe Actinolite	TAS_AHRA
B	35	C4		NSD									
B	36	C14		NSD									
B	37	C24		NSD									
B	38	C34		NSD									
B	39	C44		NSD									
B	40	C3		NSD									
B	41	C13		NSD									
B	42	C23		NSD									
B	43	C33		NSD									
B	44	C43		NSD									
B	45	C2		NSD									
B	46	C12		NSD									
B	47	C22		NSD									
B	48	C32		NSD									
B	49	C42		NSD									
B	50	C1		NSD									
B	51	C31	AZQ	5	5	F	5.8	1.5	3.9	5404	15300	Mg, Si, Ca Tremolite Zone Axis [3 1 0] - KM	AS>5, AFB>5, PCMEF-US, PCMES-US, TAS_AHRA, AS>5_AHRA, AS5-10_AHRA
B	52	C11		NSD									
B	53	C21		NSD									
B	54	C41		NSD									
B	55	C20		NSD									
B	56	C30	AQ	6		MD1-0	6	2.5	2.4			Tremolite	AS>5, TAS_AHRA, AS>5_AHRA, AS5-10_AHRA
B	56	C30	AQ		6	MF	3.8	0.5	7.6			Mg, Si, Ca Tremolite	
C	57	B44		NSD									
C	58	B24		NSD									
C	59	B4		NSD									
C	60	C14		NSD									

Lab/Cor, Inc.

A Professional Service Corporation in the Northwest

Report # 041172R3

Client: Ecology and Environment, Inc.

Project Name: Site# 0440.01CP, 0440.01CP-0001- FINAL RESULTS

TEM ASBESTOS STRUCTURE COUNT - RAW DATA

Sample No.: RHB-L2-1CH-100304 *Lab/Cor Sample No.:* B4760 S34 A1

Descripiton:

Gr	No.	Loc.	ID	Prim	Tot	Class	Len	Wid	Asp	Neg#	EDS#	Comment	Count Categories
C	61	C34		NSD									
C	62	B33		NSD									
C	63	B13	CDQ	7	7	B	8	0.35	23	5405	15301	Mg, Si Chrysotile Verified - KM	AS>5, AFB>5, PCMEF-US, PCMES-US, PSAS 5-10, PSAS TOT, PCAS 5-10, PCAS TOT, TAS_AHRA, AS>5_AHRA, AS5-10_AHRA
C	64	C3		NSD									
C	65	C23	AQ	8	8	F	3.7	0.6	6.2			Mg, Al, Si, Ca, Fe Actinolite	TAS_AHRA
C	66	C43		NSD									
C	67	B42		NSD									
C	68	B22		NSD									
C	69	B2		NSD									
C	70	C12		NSD									
C	71	C32		NSD									
C	72	B31		NSD									
C	73	B11		NSD									
C	74	C1		NSD									
C	75	C21		NSD									
C	76	C41		NSD									
C	77	B40		NSD									
C	78	B20	AQ	9	9	F	7.8	1.2	6.5			Mg, Al, Si, Ca, Fe Actinolite	AS>5, AFB>5, PCMEF-US, PCMES-US, TAS_AHRA, AS>5_AHRA, AS5-10_AHRA
C	79	B10		NSD									
C	80	C10		NSD									
C	81	C30		NSD									
C	82	A41		NSD									
C	83	A21		NSD									
C	84	A11		NSD									
C	85	A1		NSD									
C	86	D11		NSD									

Lab/Cor, Inc.

A Professional Service Corporation in the Northwest

Report # 041172R6

Client: Ecology and Environment, Inc.

Project Name: Site# 0440.01CP, 0440.01CP-0001-FINAL RESULTS

TEM ASBESTOS STRUCTURE COUNT - RAW DATA

Sample No.: RHB-L2-14CH-100304 *Lab/Cor Sample No.:* B4760 S61 A1

Descripiton:

Gr	No.	Loc.	ID	Prim	Tot	Class	Len	Wid	Asp	Neg#	EDS#	Comment	Count Categories
A	1	B44		NSD									
A	2	B34		NSD									
A	3	B24		NSD									
A	4	B14		NSD									
A	5	B4		NSD									
A	6	C4		NSD									
A	7	C14		NSD									
A	8	C24		NSD									
A	9	C34		NSD									
A	10	C44		NSD									
A	11	B42		NSD									
A	12	B32	AQ	1		MD1-1	10	1.5	6.7			Actinolite	AS>5, PCMES-US, TAS_AHRA, AS>5_AHRA, AS5-10_AHRA
A	12	B32	AQ		1	MF	10	1.2	8.3		15539	Mg, Al, Si, Ca, Fe Actinolite	AFB>5, PCMEF-US
A	13	B22		NSD									
A	14	B12		NSD									
A	15	B2		NSD									
A	16	C2		NSD									
A	17	C12		NSD									
A	18	C42		NSD									
A	19	B41		NSD									
A	20	B31		NSD									
A	21	B11		NSD									
A	22	B1		NSD									
A	23	C1		NSD									
A	24	C11	AZQ	2		MD1-1	7.5	5	1.5			Actinolite	AS>5, TAS_AHRA, AS>5_AHRA, AS5-10_AHRA
A	24	C11	AZQ		2	MF	5.5	0.75	7.3	5687	15540	Mg, Al, Si, Ca, Fe Actinolite Zone Axis [5 3 4] - KBM	AFB>5, PCMEF-US
A	25	C31		NSD									
A	26	C41		NSD									
A	27	C40		NSD									
A	28	C30		NSD									
A	29	C20		NSD									
A	30	C10		NSD									

Lab/Cor, Inc.

A Professional Service Corporation in the Northwest

Report # 041172R6

Client: Ecology and Environment, Inc.

Project Name: Site# 0440.01CP, 0440.01CP-0001-FINAL RESULTS

TEM ASBESTOS STRUCTURE COUNT - RAW DATA

Sample No.: RHB-L2-14CH-100304 *Lab/Cor Sample No.:* B4760 S61 A1

Descripiton:

Gr	No.	Loc.	ID	Prim	Tot	Class	Len	Wid	Asp	Neg#	EDS#	Comment	Count Categories
B	31	B44		NSD									
B	32	B34	AQ	3		MD1-0	4	2	2.0			Actinolite	TAS_AHRA
B	32	B34	AQ		3	MF	2.5	0.65	3.8			Mg, Al, Si, Ca, Fe Actinolite	
B	33	B24		NSD									
B	34	B14		NSD									
B	35	B4		NSD									
B	36	C4		NSD									
B	37	C14		NSD									
B	38	C24		NSD									
B	39	C34		NSD									
B	40	C44		NSD									
B	41	C42		NSD									
B	42	C32		NSD									
B	43	C22	AQ	4	4	F	4	0.75	5.3			Mg, Al, Si, Ca, Fe Actinolite	TAS_AHRA
B	44	C12		NSD									
B	45	C2		NSD									
B	46	B2	AQ	5	5	F	5	1.3	3.8			Mg, Al, Si, Ca, Fe Actinolite	TAS_AHRA
B	47	B12		NSD									
B	48	B22		NSD									
B	49	B32		NSD									
B	50	B42		NSD									
B	51	B40		NSD									
B	52	B30		NSD									
B	53	B20		NSD									
B	54	B10		NSD									
B	55	C10		NSD									
B	56	C20		NSD									
B	57	C30		NSD									
B	58	C40		NSD									
B	59	D41		NSD									
B	60	D31		NSD									
B	61	D21		NSD									
B	62	D11		NSD									
B	63	D1		NSD									

Lab/Cor, Inc.

A Professional Service Corporation in the Northwest

Report # 041172R6

Client: Ecology and Environment, Inc.

Project Name: Site# 0440.01CP, 0440.01CP-0001-FINAL RESULTS

TEM ASBESTOS STRUCTURE COUNT - RAW DATA

Sample No.: RHB-L2-14CH-100304 *Lab/Cor Sample No.:* B4760 S61 A1

Descripiton:

Gr	No.	Loc.	ID	Prim	Tot	Class	Len	Wid	Asp	Neg#	EDS#	Comment	Count Categories
B	64	A1		NSD									
C	65	B44		NSD									
C	66	B34		NSD									
C	67	B24		NSD									
C	68	B14		NSD									
C	69	B4		NSD									
C	70	C4		NSD									
C	71	C14		NSD									
C	72	C42		NSD									
C	73	C32		NSD									
C	74	C22		NSD									
C	75	C12		NSD									
C	76	C2		NSD									
C	77	B2		NSD									
C	78	B12		NSD									
C	79	B22		NSD									
C	80	B32		NSD									
C	81	B42		NSD									
C	82	A41		NSD									
C	83	A1		NSD									
C	84	D1		NSD									
C	85	D11		NSD									
C	86	D21		NSD									
C	87	D31		NSD									
C	88	D41		NSD									
C	89	D40		NSD									

Lab/Cor, Inc.

A Professional Service Corporation in the Northwest

Report # 041172R3

Client: Ecology and Environment, Inc.

Project Name: Site# 0440.01CP, 0440.01CP-0001- FINAL RESULTS

TEM ASBESTOS STRUCTURE COUNT - RAW DATA

Sample No.: RHB-L2-2CH-100304 *Lab/Cor Sample No.:* B4760 S35 A1

Descripiton:

Gr	No.	Loc.	ID	Prim	Tot	Class	Len	Wid	Asp	Neg#	EDS#	Comment	Count Categories
A	1	B44		NSD									
A	2	B34		NSD									
A	3	B24		NSD									
A	4	B14		NSD									
A	5	B4		NSD									
A	6	C4		NSD									
A	7	C14		NSD									
A	8	C24		NSD									
A	9	C34		NSD									
A	10	C43		NSD									
A	11	C33		NSD									
A	12	C23		NSD									
A	13	C13		NSD									
A	14	C3		NSD									
A	15	B3		NSD									
A	16	B13		NSD									
A	17	B23		NSD									
A	18	B33		NSD									
A	19	B43		NSD									
A	20	B42		NSD									
A	21	B32		NSD									
A	22	B22		NSD									
A	23	B12		NSD									
A	24	B2		NSD									
A	25	C2		NSD									
A	26	C12		NSD									
A	27	C22		NSD									
A	28	C32		NSD									
A	29	C42		NSD									
A	30	C41		NSD									
A	31	C31		NSD									
B	32	B44		NSD									
B	33	B34		NSD									

Lab/Cor, Inc.

A Professional Service Corporation in the Northwest

Report # 041172R3

Client: Ecology and Environment, Inc.

Project Name: Site# 0440.01CP, 0440.01CP-0001- FINAL RESULTS

TEM ASBESTOS STRUCTURE COUNT - RAW DATA

Sample No.: RHB-L2-2CH-100304 *Lab/Cor Sample No.:* B4760 S35 A1

Descripiton:

Gr	No.	Loc.	ID	Prim	Tot	Class	Len	Wid	Asp	Neg#	EDS#	Comment	Count Categories
B	34	B24	AZQ	1		MD1-1	16	12	1.3			Actinolite	AS>5, TAS_AHRA, AS>5_AHRA, AS>10_AHRA
B	34	B24	AZQ		1	MF	6	1	6.0	981	715	Mg, Al, Si, Ca, Fe Actinolite Zone Axis [5 1 4] - KM	AFB>5, PCMEF-US
B	35	B14		NSD									
B	36	B4		NSD									
B	37	C4		NSD									
B	38	C14		NSD									
B	39	C24		NSD									
B	40	C34		NSD									
B	41	C44	AZQ	2	2	F	6	1.5	4.0	982	716	Mg, Al, Si, Ca, Fe Tremolite Zone Axis [1 0 0] - KM	AS>5, AFB>5, PCMEF-US, PCMES-US, TAS_AHRA, AS>5_AHRA, AS5-10_AHRA
B	42	C43		NSD									
B	43	C33		NSD									
B	44	C23		NSD									
B	45	C13		NSD									
B	46	C3		NSD									
B	47	B3		NSD									
B	48	B13		NSD									
B	49	B23		NSD									
B	50	B33		NSD									
B	51	B43		NSD									
B	52	B41		NSD									
B	53	B21		NSD									
B	54	B1		NSD									
B	55	C11		NSD									
B	56	C31		NSD									
B	57	D40		NSD									
B	58	D20		NSD									
B	59	A10		NSD									
B	60	A30		NSD									
B	61	A42		NSD									
C	62	A43		NSD									
C	63	A23		NSD									
C	64	A3		NSD									

Lab/Cor, Inc.

A Professional Service Corporation in the Northwest

Report # 041172R3

Client: Ecology and Environment, Inc.

Project Name: Site# 0440.01CP, 0440.01CP-0001- FINAL RESULTS

TEM ASBESTOS STRUCTURE COUNT - RAW DATA

Sample No.: RHB-L2-2CH-100304 *Lab/Cor Sample No.:* B4760 S35 A1

Descripiton:

Gr	No.	Loc.	ID	Prim	Tot	Class	Len	Wid	Asp	Neg#	EDS#	Comment	Count Categories
C	65	D13		NSD									
C	66	D33		NSD									
C	67	D41		NSD									
C	68	D21		NSD									
C	69	D1		NSD									
C	70	A11		NSD									
C	71	A31	AQ	3	3	F	1.7	0.5	3.4			Mg, Si, Ca, Fe Actinolite	TAS_AHRA
C	72	B40		NSD									
C	73	B10		NSD									
C	74	C10		NSD									
C	75	C30		NSD									
C	76	C42		NSD									
C	77	C22		NSD									
C	78	C2		NSD									
C	79	B12		NSD									
C	80	B42		NSD									
C	81	B43		NSD									
C	82	B3		NSD									
C	83	C3		NSD									
C	84	C23		NSD									
C	85	C43		NSD									
C	86	C44		NSD									
C	87	C24		NSD									
C	88	C4		NSD									
C	89	D14		NSD									
C	90	A34		NSD									
C	91	A14		NSD									

Lab/Cor, Inc.

A Professional Service Corporation in the Northwest

Report # 041172R3

Client: Ecology and Environment, Inc.

Project Name: Site# 0440.01CP, 0440.01CP-0001- FINAL RESULTS

TEM ASBESTOS STRUCTURE COUNT - RAW DATA

Sample No.: RHB-L2-3CH-100304 *Lab/Cor Sample No.:* B4760 S36 A1

Descripiton:

Gr	No.	Loc.	ID	Prim	Tot	Class	Len	Wid	Asp	Neg#	EDS#	Comment	Count Categories
A	1	A44		NSD									
A	2	D24		NSD									
A	3	D34		NSD									
A	4	D32		NSD									
A	5	D12		NSD									
A	6	A2		NSD									
A	7	A12		NSD									
A	8	A32		NSD									
A	9	A42		NSD									
A	10	A40		NSD									
A	11	A20		NSD									
A	12	A10		NSD									
A	13	D10		NSD									
A	14	D30		NSD									
A	15	C41		NSD									
A	16	C21		NSD									
A	17	C1		NSD									
A	18	B11		NSD									
A	19	B31		NSD									
A	20	B41		NSD									
A	21	B43		NSD									
A	22	B23		NSD									
A	23	B3		NSD									
A	24	C13		NSD									
A	25	C33		NSD									
A	26	C43		NSD									
A	27	C44		NSD									
A	28	C24		NSD									
A	29	C4		NSD									
A	30	B14		NSD									
B	31	B43		NSD									
B	32	B33		NSD									
B	33	C23		NSD									
B	34	C43		NSD									

Lab/Cor, Inc.

A Professional Service Corporation in the Northwest

Report # 041172R3

Client: Ecology and Environment, Inc.

Project Name: Site# 0440.01CP, 0440.01CP-0001- FINAL RESULTS

TEM ASBESTOS STRUCTURE COUNT - RAW DATA

Sample No.: RHB-L2-3CH-100304 *Lab/Cor Sample No.:* B4760 S36 A1

Descripiton:

Gr	No.	Loc.	ID	Prim	Tot	Class	Len	Wid	Asp	Neg#	EDS#	Comment	Count Categories
B	35	C41		NSD									
B	36	C21		NSD									
B	37	C1		NSD									
B	38	B11		NSD									
B	39	B31		NSD									
B	40	B41		NSD									
B	41	A40		NSD									
B	42	A20		NSD									
B	43	A10		NSD									
B	44	D10		NSD									
B	45	D30		NSD									
B	46	D40		NSD									
B	47	D42		NSD									
B	48	D22		NSD									
B	49	D2		NSD									
B	50	A12		NSD									
B	51	A32		NSD									
B	52	A42		NSD									
B	53	A24		NSD									
B	54	A4		NSD									
B	55	D14		NSD									
B	56	D34		NSD									
B	57	D44		NSD									
B	58	D41		NSD									
C	59	A44		NSD									
C	60	A24		NSD									
C	61	A4		NSD									
C	62	D14		NSD									
C	63	D34		NSD									
C	64	D44		NSD									
C	65	D42		NSD									
C	66	D22		NSD									
C	67	D2		NSD									
C	68	A12		NSD									

Lab/Cor, Inc.

A Professional Service Corporation in the Northwest

Report # 041172R3

Client: Ecology and Environment, Inc.

Project Name: Site# 0440.01CP, 0440.01CP-0001- FINAL RESULTS

TEM ASBESTOS STRUCTURE COUNT - RAW DATA

Sample No.: RHB-L2-3CH-100304 *Lab/Cor Sample No.:* B4760 S36 A1

Descripiton:

Gr	No.	Loc.	ID	Prim	Tot	Class	Len	Wid	Asp	Neg#	EDS#	Comment	Count Categories
C	69	A32		NSD									
C	70	A42		NSD									
C	71	A40		NSD									
C	72	A20		NSD									
C	73	A10		NSD									
C	74	D10		NSD									
C	75	C41		NSD									
C	76	C21		NSD									
C	77	C1		NSD									
C	78	B11		NSD									
C	79	B31		NSD									
C	80	B41		NSD									
C	81	B43		NSD									
C	82	B23	AZQ	1	1	F	8	1.5	5.3	983	717	Mg, Al, Si, Ca, Fe Actinolite Zone Axis [1 0 5] - KM	AS>5, AFB>5, PCMEF-US, PCMES-US, TAS_AHRA, AS>5_AHRA, AS5-10_AHRA
C	83	B3		NSD									
C	84	B23		NSD									
C	85	B43		NSD									
C	86	B44		NSD									
C	87	B24		NSD									

Lab/Cor, Inc.

A Professional Service Corporation in the Northwest

Report # 041172R3

Client: Ecology and Environment, Inc.

Project Name: Site# 0440.01CP, 0440.01CP-0001- FINAL RESULTS

TEM ASBESTOS STRUCTURE COUNT - RAW DATA

Sample No.: RHB-L2-4CH-100304 *Lab/Cor Sample No.:* B4760 S37 A1

Descripiton:

Gr	No.	Loc.	ID	Prim	Tot	Class	Len	Wid	Asp	Neg#	EDS#	Comment	Count Categories
A	1	B44		NSD									
A	2	B24		NSD									
A	3	B4		NSD									
A	4	C14		NSD									
A	5	C34		NSD									
A	6	B33		NSD									
A	7	B13		NSD									
A	8	C3		NSD									
A	9	C23		NSD									
A	10	C43		NSD									
A	11	B32		NSD									
A	12	B12		NSD									
A	13	C2		NSD									
A	14	C22		NSD									
A	15	C42		NSD									
A	16	B31		NSD									
A	17	B21	ADQ	1		MD1-0	6.5	4	1.6			Actinolite	AS>5, TAS_AHRA, AS>5_AHRA, AS5-10_AHRA
A	17	B21	ADQ		1	MF	2	0.4	5.0		15302	Mg, Al, Si, Ca, Fe Actinolite	
A	18	B1		NSD									
A	19	C11		NSD									
A	20	C31		NSD									
A	21	A31		NSD									
A	22	A21		NSD									
A	23	A1		NSD									
A	24	D11		NSD									
A	25	D31		NSD									
A	26	A32		NSD									
A	27	A12		NSD									
A	28	D2		NSD									
A	29	D22		NSD									
B	30	B44		NSD									
B	31	B24		NSD									
B	32	B4		NSD									

Lab/Cor, Inc.

A Professional Service Corporation in the Northwest

Report # 041172R3

Client: Ecology and Environment, Inc.

Project Name: Site# 0440.01CP, 0440.01CP-0001- FINAL RESULTS

TEM ASBESTOS STRUCTURE COUNT - RAW DATA

Sample No.: RHB-L2-4CH-100304 *Lab/Cor Sample No.:* B4760 S37 A1

Descripiton:

Gr	No.	Loc.	ID	Prim	Tot	Class	Len	Wid	Asp	Neg#	EDS#	Comment	Count Categories
B	33	C4		NSD									
B	34	C24		NSD									
B	35	C44		NSD									
B	36	C43	AZQ	2		MD1-0	6	6	1.0			Actinolite	AS>5, TAS_AHRA, AS>5_AHRA, AS5-10_AHRA
B	36	C43	AZQ		2	MF	2.5	0.75	3.3	5408	15303	Mg, Al, Si, Ca, Fe Actinolite Zone Axis [2 0 1] - KM	
B	37	C23		NSD									
B	38	C3		NSD									
B	39	B3		NSD									
B	40	B23		NSD									
B	41	B43		NSD									
B	42	B42		NSD									
B	43	B22		NSD									
B	44	B2		NSD									
B	45	C2		NSD									
B	46	C22		NSD									
B	47	C42		NSD									
B	48	C41		NSD									
B	49	C21		NSD									
B	50	C1		NSD									
B	51	B1		NSD									
B	52	B21		NSD									
B	53	B41		NSD									
B	54	B40		NSD									
B	55	B20		NSD									
B	56	C20	AQ	3	3	F	8	0.9	8.9			Mg, Si, Ca, Fe Actinolite	AS>5, AFB>5, PCMEF-US, PCMES-US, TAS_AHRA, AS>5_AHRA, AS5-10_AHRA
B	57	C40		NSD									
B	58	D40		NSD									
C	59	B44		NSD									
C	60	B24		NSD									
C	61	B4	AQ	4	4	F	1.2	0.2	6.0			Mg, Al, Si, Ca, Fe Actinolite	TAS_AHRA
C	62	C14		NSD									
C	63	C24		NSD									

Lab/Cor, Inc.

A Professional Service Corporation in the Northwest

Report # 041172R3

Client: Ecology and Environment, Inc.

Project Name: Site# 0440.01CP, 0440.01CP-0001- FINAL RESULTS

TEM ASBESTOS STRUCTURE COUNT - RAW DATA

Sample No.: RHB-L2-4CH-100304 *Lab/Cor Sample No.:* B4760 S37 A1

Descripiton:

Gr	No.	Loc.	ID	Prim	Tot	Class	Len	Wid	Asp	Neg#	EDS#	Comment	Count Categories
C	64	C42		NSD									
C	65	C22		NSD									
C	66	C2		NSD									
C	67	B12		NSD									
C	68	B32		NSD									
C	69	B42		NSD									
C	70	B40		NSD									
C	71	B20		NSD									
C	72	B10		NSD									
C	73	C10		NSD									
C	74	C30		NSD									
C	75	D41		NSD									
C	76	D21		NSD									
C	77	D1		NSD									
C	78	A11		NSD									
C	79	A31		NSD									
C	80	A41		NSD									
C	81	A13		NSD									
C	82	D3		NSD									
C	83	D23		NSD									
C	84	D33		NSD									
C	85	D43		NSD									
C	86	D42		NSD									

Lab/Cor, Inc.

A Professional Service Corporation in the Northwest

Report # 041172R3

Client: Ecology and Environment, Inc.

Project Name: Site# 0440.01CP, 0440.01CP-0001- FINAL RESULTS

TEM ASBESTOS STRUCTURE COUNT - RAW DATA

Sample No.: RHB-L2-5CH-100304 *Lab/Cor Sample No.:* B4760 S38 A1

Descripiton:

Gr	No.	Loc.	ID	Prim	Tot	Class	Len	Wid	Asp	Neg#	EDS#	Comment	Count Categories
A	1	B34		NSD									
A	2	B14		NSD									
A	3	C4		NSD									
A	4	C24		NSD									
A	5	C44		NSD									
A	6	B43		NSD									
A	7	B23		NSD									
A	8	B3		NSD									
A	9	C13		NSD									
A	10	C33		NSD									
A	11	B32		NSD									
A	12	B12		NSD									
A	13	C2		NSD									
A	14	C22		NSD									
A	15	C42		NSD									
A	16	B41		NSD									
A	17	B21		NSD									
A	18	B1		NSD									
A	19	C11		NSD									
A	20	C31		NSD									
A	21	B30		NSD									
A	22	B10		NSD									
A	23	C10		NSD									
A	24	C30		NSD									
A	25	C40		NSD									
A	26	A41		NSD									
A	27	A21		NSD									
A	28	A1		NSD									
A	29	D11		NSD									
A	30	D31	ADQ	1		MD1-0	10	5	2.0			Tremolite	AS>5, TAS_AHRA, AS>5_AHRA, AS5-10_AHRA
A	30	D31	ADQ		1	MF	1.6	0.2	8.0			Mg, Al, Si, Ca, Fe Tremolite	
B	31	B34		NSD									
B	32	B14	AZQ	2	2	F	2	0.22	9.1	5439	718	Mg, Al, Si, Ca, Fe Tremolite Zone Axis [1 0 1] - KM	TAS_AHRA

Lab/Cor, Inc.

A Professional Service Corporation in the Northwest

Report # 041172R3

Client: Ecology and Environment, Inc.

Project Name: Site# 0440.01CP, 0440.01CP-0001- FINAL RESULTS

TEM ASBESTOS STRUCTURE COUNT - RAW DATA

Sample No.: RHB-L2-5CH-100304 *Lab/Cor Sample No.:* B4760 S38 A1

Descripiton:

Gr	No.	Loc.	ID	Prim	Tot	Class	Len	Wid	Asp	Neg#	EDS#	Comment	Count Categories
B	33	C4		NSD									
B	34	C24		NSD									
B	35	C44		NSD									
B	36	B43		NSD									
B	37	B23		NSD									
B	38	B3		NSD									
B	39	C13		NSD									
B	40	C33		NSD									
B	41	B32		NSD									
B	42	B12	ADQ	3	3	F	6	1.5	4.0			Mg, Al, Si, Ca, Fe Actinolite	AS>5, AFB>5, PCMEF-US, PCMES-US, TAS_AHRA, AS>5_AHRA, AS5-10_AHRA
B	43	C2		NSD									
B	44	C22		NSD									
B	45	C42		NSD									
B	46	B31		NSD									
B	47	B21		NSD									
B	48	B11		NSD									
B	49	B1		NSD									
B	50	C1		NSD									
B	51	C11		NSD									
B	52	C21		NSD									
B	53	C31		NSD									
B	54	C41		NSD									
B	55	A41		NSD									
B	56	A31		NSD									
B	57	A21		NSD									
B	58	A11		NSD									
B	59	A1		NSD									
B	60	D1		NSD									
B	61	D11		NSD									
B	62	D21		NSD									
B	63	D31		NSD									
B	64	D41		NSD									
C	65	B43		NSD									

Lab/Cor, Inc.

A Professional Service Corporation in the Northwest

Report # 041172R3

Client: Ecology and Environment, Inc.

Project Name: Site# 0440.01CP, 0440.01CP-0001- FINAL RESULTS

TEM ASBESTOS STRUCTURE COUNT - RAW DATA

Sample No.: RHB-L2-5CH-100304 *Lab/Cor Sample No.:* B4760 S38 A1

Descripiton:

Gr	No.	Loc.	ID	Prim	Tot	Class	Len	Wid	Asp	Neg#	EDS#	Comment	Count Categories
C	66	B33		NSD									
C	67	B23		NSD									
C	68	B13		NSD									
C	69	B3		NSD									
C	70	C3		NSD									
C	71	C13		NSD									
C	72	C23		NSD									
C	73	C33		NSD									
C	74	C43		NSD									
C	75	C42		NSD									
C	76	C32		NSD									
C	77	C22		NSD									
C	78	C12		NSD									
C	79	C2		NSD									
C	80	B2		NSD									
C	81	B12	AZQ	4	4	F	4	0.75	5.3	5440	719	Mg, Al, Si, Ca, Fe Actinolite Zone Axis [1 0 0] - KM	TAS_AHRA
C	82	B22		NSD									
C	83	B32		NSD									
C	84	B42		NSD									
C	85	B31		NSD									
C	86	B21		NSD									
C	87	B11		NSD									
C	88	B1		NSD									
C	89	C1		NSD									
C	90	C11		NSD									

Lab/Cor, Inc.

A Professional Service Corporation in the Northwest

Report # 041172R6

Client: Ecology and Environment, Inc.

Project Name: Site# 0440.01CP, 0440.01CP-0001-FINAL RESULTS

TEM ASBESTOS STRUCTURE COUNT - RAW DATA

Sample No.: RHB-L2-1NA-100304 *Lab/Cor Sample No.:* B4760 S62 A1

Descripiton:

Gr	No.	Loc.	ID	Prim	Tot	Class	Len	Wid	Asp	Neg#	EDS#	Comment	Count Categories
A	1	B44		NSD									
A	2	B34		NSD									
A	3	B24		NSD									
A	4	B14		NSD									
A	5	B4		NSD									
A	6	C4		NSD									
A	7	C14		NSD									
A	8	C24		NSD									
A	9	C34		NSD									
A	10	C44		NSD									
A	11	B43		NSD									
A	12	B33		NSD									
A	13	B23		NSD									
A	14	B13		NSD									
A	15	B3		NSD									
A	16	C3		NSD									
A	17	C13		NSD									
A	18	B42		NSD									
A	19	B32		NSD									
A	20	B22		NSD									
A	21	B12		NSD									
A	22	B2		NSD									
A	23	B41		NSD									
A	24	B31		NSD									
A	25	B21		NSD									
A	26	A42	CDQ	1	1	B	4.5	0.4	11	5688	15541	Mg, Si Chrysotile Verified - KM	TAS_AHRA
A	27	A32		NSD									
A	28	A22		NSD									
B	29	B44		NSD									
B	30	B24		NSD									
B	31	B4		NSD									
B	32	C14		NSD									
B	33	C44		NSD									

Lab/Cor, Inc.

A Professional Service Corporation in the Northwest

Report # 041172R6

Client: Ecology and Environment, Inc.

Project Name: Site# 0440.01CP, 0440.01CP-0001-FINAL RESULTS

TEM ASBESTOS STRUCTURE COUNT - RAW DATA

Sample No.: RHB-L2-1NA-100304 *Lab/Cor Sample No.:* B4760 S62 A1

Descripiton:

Gr	No.	Loc.	ID	Prim	Tot	Class	Len	Wid	Asp	Neg#	EDS#	Comment	Count Categories
B	34	B33		NSD									
B	35	B13	CDQ	2	2	F	0.5	0.08	6.2			Mg, Si Chrysotile	TAS_AHRA
B	36	B3		NSD									
B	37	C3		NSD									
B	38	C33		NSD									
B	39	B42		NSD									
B	40	B22		NSD									
B	41	B2		NSD									
B	42	C22		NSD									
B	43	C42		NSD									
B	44	B31		NSD									
B	45	B11		NSD									
B	46	C1		NSD									
B	47	C21		NSD									
B	48	C41		NSD									
B	49	A31		NSD									
B	50	A11		NSD									
B	51	D1		NSD									
B	52	D21		NSD									
B	53	D10		NSD									
B	54	D30		NSD									
B	55	B30		NSD									
B	56	B10		NSD									
C	57	C14		NSD									
C	58	C24		NSD									
C	59	B33		NSD									
C	60	B23		NSD									
C	61	C22		NSD									
C	62	B42		NSD									
C	63	B32	CDQ	3		MD1-0	3.5	1.5	2.3			Chrysotile	TAS_AHRA
C	63	B32	CDQ		3	MF	2	0.1	20			Mg, Si Chrysotile	
C	64	B22		NSD									
C	65	B12		NSD									
C	66	C41		NSD									

Lab/Cor, Inc.

A Professional Service Corporation in the Northwest

Report # 041172R6

Client: Ecology and Environment, Inc.

Project Name: Site# 0440.01CP, 0440.01CP-0001-FINAL RESULTS

TEM ASBESTOS STRUCTURE COUNT - RAW DATA

Sample No.: RHB-L2-1NA-100304 *Lab/Cor Sample No.:* B4760 S62 A1

Descripiton:

Gr	No.	Loc.	ID	Prim	Tot	Class	Len	Wid	Asp	Neg#	EDS#	Comment	Count Categories
C	67	B41	ADQ	4	4	F	13	1.7	7.6			Mg, Al, Si, Ca, Fe Actinolite	AS>5, AFB>5, PCMEF-US, PCMES-US, TAS_AHRA, AS>5_AHRA, AS>10_AHRA
C	68	B21		NSD									
C	69	B11		NSD									
C	70	C10		NSD									
C	71	C40		NSD									
C	72	B40		NSD									
C	73	B30		NSD									
C	74	B20	AZQ	5		MD1-0	2.5	0.4	6.2			Actinolite	TAS_AHRA
C	74	B20	AZQ		5	MF	2.1	0.22	9.5	5698	15547	Mg, Al, Si, Ca, Fe Actinolite Zone Axis [1 0 0] - JH	
C	75	A30		NSD									
C	76	A20		NSD									
C	77	A10		NSD									
C	78	A41		NSD									
C	79	A31		NSD									
C	80	A21		NSD									
C	81	A11		NSD									
C	82	A1		NSD									
C	83	D1		NSD									

Lab/Cor, Inc.

A Professional Service Corporation in the Northwest

Report # 041172R6

Client: Ecology and Environment, Inc.

Project Name: Site# 0440.01CP, 0440.01CP-0001-FINAL RESULTS

TEM ASBESTOS STRUCTURE COUNT - RAW DATA

Sample No.: RHB-L2-1ZB-100304 *Lab/Cor Sample No.:* B4760 S63 A1

Descripiton:

Gr	No.	Loc.	ID	Prim	Tot	Class	Len	Wid	Asp	Neg#	EDS#	Comment	Count Categories
A	1	B44		NSD									
A	2	B34		NSD									
A	3	B24		NSD									
A	4	B14		NSD									
A	5	B4		NSD									
A	6	C4		NSD									
A	7	C14		NSD									
A	8	C24		NSD									
A	9	C34		NSD									
A	10	C44		NSD									
A	11	C42		NSD									
A	12	C32		NSD									
A	13	C22		NSD									
A	14	C12		NSD									
A	15	C2		NSD									
A	16	A41		NSD									
A	17	A31		NSD									
A	18	A21		NSD									
A	19	A11		NSD									
A	20	A1		NSD									
A	21	D1		NSD									
A	22	D11		NSD									
A	23	D21		NSD									
A	24	D32		NSD									
A	25	D22		NSD									
A	26	D12		NSD									
A	27	D2		NSD									
A	28	A2		NSD									
A	29	A12		NSD									
A	30	A22		NSD									
A	31	A32		NSD									
A	32	A42		NSD									
B	33	A44		NSD									
B	34	A43		NSD									

Lab/Cor, Inc.

A Professional Service Corporation in the Northwest

Report # 041172R6

Client: Ecology and Environment, Inc.

Project Name: Site# 0440.01CP, 0440.01CP-0001-FINAL RESULTS

TEM ASBESTOS STRUCTURE COUNT - RAW DATA

Sample No.: RHB-L2-1ZB-100304 *Lab/Cor Sample No.:* B4760 S63 A1

Descripiton:

Gr	No.	Loc.	ID	Prim	Tot	Class	Len	Wid	Asp	Neg#	EDS#	Comment	Count Categories
B	35	A42		NSD									
B	36	A41		NSD									
B	37	A40		NSD									
B	38	B40		NSD									
B	39	B41		NSD									
B	40	B42		NSD									
B	41	B43		NSD									
B	42	B44		NSD									
B	43	B34		NSD									
B	44	B33		NSD									
B	45	B32		NSD									
B	46	B31		NSD									
B	47	B30		NSD									
B	48	A30		NSD									
B	49	A31		NSD									
B	50	A32		NSD									
B	51	A33		NSD									
B	52	A34		NSD									
B	53	A24		NSD									
B	54	A23		NSD									
B	55	A22		NSD									
B	56	A21		NSD									
B	57	A20		NSD									
B	58	B20		NSD									
B	59	B21		NSD									
B	60	B22		NSD									
B	61	B23		NSD									
B	62	B24		NSD									
C	63	B44		NSD									
C	64	B34		NSD									
C	65	B24		NSD									
C	66	B14		NSD									
C	67	B4		NSD									
C	68	C4		NSD									

Lab/Cor, Inc.

A Professional Service Corporation in the Northwest

Report # 041172R6

Client: Ecology and Environment, Inc.

Project Name: Site# 0440.01CP, 0440.01CP-0001-FINAL RESULTS

TEM ASBESTOS STRUCTURE COUNT - RAW DATA

Sample No.: RHB-L2-1ZB-100304 *Lab/Cor Sample No.:* B4760 S63 A1

Descripiton:

Gr	No.	Loc.	ID	Prim	Tot	Class	Len	Wid	Asp	Neg#	EDS#	Comment	Count Categories
C	69	C14		NSD									
C	70	C24		NSD									
C	71	C34		NSD									
C	72	C43		NSD									
C	73	C42		NSD									
C	74	C41		NSD									
C	75	C40		NSD									
C	76	D40		NSD									
C	77	A13		NSD									
C	78	A3		NSD									
C	79	D3		NSD									
C	80	D13		NSD									
C	81	D12		NSD									
C	82	D2		NSD									
C	83	A2		NSD									
C	84	A12		NSD									
C	85	D11		NSD									
C	86	D21		NSD									
C	87	D20		NSD									
C	88	D10		NSD									

Sample No.: RHB-L2-FB-100304 *Lab/Cor Sample No.:* B4760 S64 A1

Descripiton: FILTER BLANK

Gr	No.	Loc.	ID	Prim	Tot	Class	Len	Wid	Asp	Neg#	EDS#	Comment	Count Categories
A	1	A31		NSD									
A	2	A11		NSD									
A	3	D11		NSD									
A	4	B1		NSD									
A	5	C11		NSD									
B	6	B11		NSD									
B	7	C1		NSD									
B	8	C21		NSD									
B	9	D21		NSD									
B	10	D1		NSD									

Lab/Cor, Inc.

A Professional Service Corporation in the Northwest

Report # 041172R3

Client: Ecology and Environment, Inc.

Project Name: Site# 0440.01CP, 0440.01CP-0001- FINAL RESULTS

TEM ASBESTOS STRUCTURE COUNT - RAW DATA

Sample No.: CC2A-L6-1CA-100304 *Lab/Cor Sample No.:* B4760 S12 A1

Descripiton:

Gr	No.	Loc.	ID	Prim	Tot	Class	Len	Wid	Asp	Neg#	EDS#	Comment	Count Categories
A	1	A1		NSD									
A	2	A2		NSD									
A	3	B24	CDQ	1	1	B	8.5	2	4.2	5238	15157	Mg, Si, Fe Chrysotile Confirmed - KM	AS>5, PCMEF-US, PCMES-US, TAS_AHRA, AS>5_AHRA, AS5-10_AHRA
A	4	B22		NSD									
A	5	B21		NSD									
A	6	B20		NSD									
A	7	A11		NSD									
A	8	A10		NSD									
A	9	B10		NSD									
A	10	B12		NSD									
A	11	C20		NSD									
A	12	C21		NSD									
A	13	C23		NSD									
A	14	C33		NSD									
A	15	C44		NSD									
A	16	C43	CDQ	2		MD2-0	2.5	2	1.2	5239	15158	Mg, Si, Fe Chrysotile Confirmed - KM	TAS_AHRA
A	16	C43	CDQ		2	MF	1.25	0.05	25			Chrysotile	
A	16	C43	CDQ		3	MF	1	0.05	20			Chrysotile	
A	17	C42		NSD									
A	18	C32		NSD									
A	19	D41	ADQ	3	4	F	2.5	0.5	5.0		15159	Mg, Si, Ca, Fe Actinolite	TAS_AHRA
A	20	D42		NSD									
A	21	D32		NSD									
A	22	D31		NSD									
A	23	D30		NSD									
A	24	D20	CDQ	4		MD99-0	6	4	1.5	5242	15160	Mg, Si, Fe Chrysotile Confirmed - KM	AS>5, TAS_AHRA, AS>5_AHRA, AS5-10_AHRA
A	24	D20	CDQ		5	MR50-0	2.5	1.5	1.7			Chrysotile	
A	24	D20	CDQ		6	MR30-0	2.5	1	2.5			Chrysotile	
A	24	D20	CDQ		7	MR15-0	2	1.5	1.3			Chrysotile	
A	24	D20	CDQ		8	MR7-0	2	0.8	2.5			Chrysotile	
A	24	D20	CDQ		9	MR30-0	2	0.5	4.0			Chrysotile	
A	24	D20	CDQ		10	MF	1.2	0.06	20			Chrysotile	

Lab/Cor, Inc.

A Professional Service Corporation in the Northwest

Report # 041172R3

Client: Ecology and Environment, Inc.

Project Name: Site# 0440.01CP, 0440.01CP-0001- FINAL RESULTS

TEM ASBESTOS STRUCTURE COUNT - RAW DATA

Sample No.: CC2A-L6-1CA-100304 *Lab/Cor Sample No.:* B4760 S12 A1

Descripiton:

Gr	No.	Loc.	ID	Prim	Tot	Class	Len	Wid	Asp	Neg#	EDS#	Comment	Count Categories
A	24	D20	CDQ		11	MF	0.7	0.05	14			Chrysotile	
A	24	D20	CDQ		12	MF	0.6	0.05	12			Chrysotile	
A	25	D21		NSD									
A	26	D22		NSD									
A	27	D12		NSD									
A	28	D11		NSD									
A	29	D10		NSD									
A	30	D2		NSD									
A	31	A12	CDQ	5	13	F	0.65	0.05	13	5243	15161	Mg, Si, Fe Chrysotile Confirmed - KM	TAS_AHRA
A	32	A22		NSD									
A	33	A30		NSD									
B	34	A1		NSD									
B	35	A11		NSD									
B	36	A10		NSD									
B	37	B10		NSD									
B	38	B11		NSD									
B	39	B1		NSD									
B	40	C1		NSD									
B	41	C11	CDQ	6	14	F	1.1	0.1	11			Mg, Si, Fe Chrysotile	TAS_AHRA
B	42	C10		NSD									
B	43	D10		NSD									
B	44	D11		NSD									
B	45	D1		NSD									
B	46	A2		NSD									
B	47	A12		NSD									
B	48	A22	AZQ	7	15	F	1.25	0.3	4.2	5284	15199	Mg, Si, Ca, Fe Actinolite Zone Axis [5 1 2] - KM	TAS_AHRA
B	49	A21		NSD									
B	50	A20	ADQ	8	16	F	4.5	0.55	8.2			Mg, Si, Ca, Fe Actinolite	TAS_AHRA
B	51	B20		NSD									
B	52	B21		NSD									
B	53	B22		NSD									
B	54	B12		NSD									
B	55	B2		NSD									

Lab/Cor, Inc.

A Professional Service Corporation in the Northwest

Report # 041172R3

Client: Ecology and Environment, Inc.

Project Name: Site# 0440.01CP, 0440.01CP-0001- FINAL RESULTS

TEM ASBESTOS STRUCTURE COUNT - RAW DATA

Sample No.: CC2A-L6-1CA-100304 *Lab/Cor Sample No.:* B4760 S12 A1

Descripiton:

Gr	No.	Loc.	ID	Prim	Tot	Class	Len	Wid	Asp	Neg#	EDS#	Comment	Count Categories
B	56	C2		NSD									
B	57	C12		NSD									
B	58	C22		NSD									
B	59	C21		NSD									
B	60	C20		NSD									
B	61	D20		NSD									
B	62	D21		NSD									
B	63	D22		NSD									
B	64	D12		NSD									
B	65	D2		NSD									
B	66	A30		NSD									
C	67	A1		NSD									
C	68	A10		NSD									
C	69	B10		NSD									
C	70	B11		NSD									
C	71	B1		NSD									
C	72	C1		NSD									
C	73	C11		NSD									
C	74	C10		NSD									
C	75	D10		NSD									
C	76	B44		NSD									
C	77	B24		NSD									
C	78	B4		NSD									
C	79	C14		NSD									
C	80	C34		NSD									
C	81	B33		NSD									
C	82	B12		NSD									
C	83	C2		NSD									
C	84	C22		NSD									
C	85	C42		NSD									
C	86	B41		NSD									
C	87	B21		NSD									
C	88	C21		NSD									
C	89	C41		NSD									

Lab/Cor, Inc.

A Professional Service Corporation in the Northwest

Report # 041172R3

Client: Ecology and Environment, Inc.

Project Name: Site# 0440.01CP, 0440.01CP-0001- FINAL RESULTS

TEM ASBESTOS STRUCTURE COUNT - RAW DATA

Sample No.: CC2A-L6-1CA-100304 *Lab/Cor Sample No.:* B4760 S12 A1

Descripiton:

Gr	No.	Loc.	ID	Prim	Tot	Class	Len	Wid	Asp	Neg#	EDS#	Comment	Count Categories
C	90	C20		NSD									
C	91	C40	CD	9		MD1-0	8	8	1.0			Chrysotile	AS>5, TAS_AHRA, AS>5_AHRA, AS5-10_AHRA
C	91	C40	CD		17	MB	3.5	0.5	7.0			Chrysotile	
C	92	B30	CM	10	18	F	0.6	0.1	6.0			Chrysotile	TAS_AHRA
C	93	A20		NSD									
C	94	D20		NSD									
C	95	D40		NSD									
C	96	D33	CM	11		MD3-0	4.5	3.5	1.3			Chrysotile	TAS_AHRA
C	96	D33	CM		19	MF	1.8	0.1	18			Chrysotile	
C	96	D33	CM		20	MB	1.6	0.2	8.0			Chrysotile	
C	96	D33	CM		21	MF	1.2	0.1	12			Chrysotile	
C	97	D13		NSD									
C	98	A2		NSD									
C	99	D12		NSD									

Lab/Cor, Inc.

A Professional Service Corporation in the Northwest

Report # 041172R3

Client: Ecology and Environment, Inc.

Project Name: Site# 0440.01CP, 0440.01CP-0001- FINAL RESULTS

TEM ASBESTOS STRUCTURE COUNT - RAW DATA

Sample No.: CC2-L6-1CC-100304 *Lab/Cor Sample No.:* B4760 S14 A1

Descripiton:

Gr	No.	Loc.	ID	Prim	Tot	Class	Len	Wid	Asp	Neg#	EDS#	Comment	Count Categories
A	1	A2	CDQ	1	1	B	24	4	6.0	818	565	Mg, Si Chrysotile Confirmed - KM	AS>5, AFB>5, TAS_AHRA, AS>5_AHRA, AS>10_AHRA
A	2	A4		NSD									
A	3	A24		NSD									
A	4	A22		NSD									
A	5	A20		NSD									
A	6	B21		NSD									
A	7	B23		NSD									
A	8	B43		NSD									
A	9	B41		NSD									
A	10	A40		NSD									
A	11	A42		NSD									
A	12	A44		NSD									
A	13	A24		NSD									
A	14	A22		NSD									
A	15	A20		NSD									
A	16	B21		NSD									
A	17	B23		NSD									
A	18	B4		NSD									
A	19	B2		NSD									
A	20	A1		NSD									
A	21	A3		NSD									
A	22	D14		NSD									
A	23	D12		NSD									
A	24	D10		NSD									
A	25	C11		NSD									
B	26	D1		NSD									
B	27	D3		NSD									
B	28	D24		NSD									
B	29	D22		NSD									
B	30	D20		NSD									
B	31	C20		NSD									
B	32	D40		NSD									
B	33	D42		NSD									

Lab/Cor, Inc.

A Professional Service Corporation in the Northwest

Report # 041172R3

Client: Ecology and Environment, Inc.

Project Name: Site# 0440.01CP, 0440.01CP-0001- FINAL RESULTS

TEM ASBESTOS STRUCTURE COUNT - RAW DATA

Sample No.: CC2-L6-1CC-100304 *Lab/Cor Sample No.:* B4760 S14 A1

Descripiton:

Gr	No.	Loc.	ID	Prim	Tot	Class	Len	Wid	Asp	Neg#	EDS#	Comment	Count Categories
B	34	A1		NSD									
B	35	A3		NSD									
B	36	A24		NSD									
B	37	A22		NSD									
B	38	A21		NSD									
B	39	B20		NSD									
B	40	B11		NSD									
B	41	B21		NSD									
B	42	B31		NSD									
B	43	B40		NSD									
B	44	A41		NSD									
B	45	A43		NSD									
B	46	A33		NSD									
B	47	A13		NSD									
B	48	D33	AZQ	2	2	F	4	0.6	6.7	819	566	Mg, Si, Ca, Fe Actinolite Zone Axis [9 1 10] - KM	TAS_AHRA
B	49	D31		NSD									
B	50	B10		NSD									
B	51	C10		NSD									

Lab/Cor, Inc.

A Professional Service Corporation in the Northwest

Report # 041172R3

Client: Ecology and Environment, Inc.

Project Name: Site# 0440.01CP, 0440.01CP-0001- FINAL RESULTS

TEM ASBESTOS STRUCTURE COUNT - RAW DATA

Sample No.: CC2-L6-11CC-100304 *Lab/Cor Sample No.:* B4760 S13 A1

Descripiton:

Gr	No.	Loc.	ID	Prim	Tot	Class	Len	Wid	Asp	Neg#	EDS#	Comment	Count Categories
A	1	B44		NSD									
A	2	B24		NSD									
A	3	B4		NSD									
A	4	C14		NSD									
A	5	B34		NSD									
A	6	C23		NSD									
A	7	C3		NSD									
A	8	B23		NSD									
A	9	B33		NSD									
A	10	B42		NSD									
A	11	B22		NSD									
A	12	B2		NSD									
A	13	C12		NSD									
A	14	C32		NSD									
A	15	C31		NSD									
A	16	C11		NSD									
A	17	B1		NSD									
A	18	B10		NSD									
A	19	B20		NSD									
A	20	B30	AZQ	1	1	F	4	0.5	8.0	816	563	Mg, Si, Ca, Fe Actinolite Zone Axis [4 1 1] - KM	TAS_AHRA
A	21	B40		NSD									
A	22	A41		NSD									
A	23	A21		NSD									
A	24	A1		NSD									
A	25	A3		NSD									
B	26	D1		NSD									
B	27	D3		NSD									
B	28	D24		NSD									
B	29	D22		NSD									
B	30	D20		NSD									
B	31	C21		NSD									
B	32	C23		NSD									
B	33	C44		NSD									

Lab/Cor, Inc.

A Professional Service Corporation in the Northwest

Report # 041172R3

Client: Ecology and Environment, Inc.

Project Name: Site# 0440.01CP, 0440.01CP-0001- FINAL RESULTS

TEM ASBESTOS STRUCTURE COUNT - RAW DATA

Sample No.: CC2-L6-11CC-100304 *Lab/Cor Sample No.:* B4760 S13 A1

Descripiton:

Gr	No.	Loc.	ID	Prim	Tot	Class	Len	Wid	Asp	Neg#	EDS#	Comment	Count Categories
B	34	C42		NSD									
B	35	C40		NSD									
B	36	D41		NSD									
B	37	D43		NSD									
B	38	B1		NSD									
B	39	B3		NSD									
B	40	B14		NSD									
B	41	B12		NSD									
B	42	B10		NSD									
B	43	A11	ADQ	2	2	F	16	4.5	3.6			Mg, Si, Ca, Fe Actinolite	AS>5, AFB>5, TAS_AHRA, AS>5_AHRA, AS>10_AHRA
B	44	A12	AZQ	3	3	F	6	1.3	4.6	817	564	Na, Mg, Si, Ca, Fe Edenite Zone Axis [9 -1 6] - KM	PCMEF-US, PCMES-US, TAS_AHRA, AS>5_AHRA, AS5-10_AHRA
B	45	A42		NSD									
B	46	A40		NSD									
B	47	B41		NSD									
B	48	B43		NSD									
B	49	B24		NSD									
B	50	B22		NSD									
B	51	B20		NSD									

Lab/Cor, Inc.

A Professional Service Corporation in the Northwest

Report # 041172R3

Client: Ecology and Environment, Inc.

Project Name: Site# 0440.01CP, 0440.01CP-0001- FINAL RESULTS

TEM ASBESTOS STRUCTURE COUNT - RAW DATA

Sample No.: CC2-L6-2CC-100304 *Lab/Cor Sample No.:* B4760 S15 A1

Descripiton:

Gr	No.	Loc.	ID	Prim	Tot	Class	Len	Wid	Asp	Neg#	EDS#	Comment	Count Categories
A	1	B44		NSD									
A	2	B4		NSD									
A	3	C14		NSD									
A	4	C34		NSD									
A	5	C3		NSD									
A	6	C23		NSD									
A	7	C43		NSD									
A	8	B22		NSD									
A	9	B2		NSD									
A	10	C12		NSD									
A	11	C32		NSD									
A	12	B31		NSD									
A	13	C1		NSD									
A	14	C21		NSD									
A	15	C41		NSD									
A	16	D40		NSD									
A	17	D20		NSD									
B	18	B34		NSD									
B	19	B14		NSD									
B	19	C4		NSD									
B	20	C14		NSD									
B	21	C24		NSD									
B	22	C44		NSD									
B	23	B43		NSD									
B	24	B23		NSD									
B	25	B3		NSD									
B	26	C13		NSD									
B	27	C33		NSD									
B	28	B42		NSD									
B	29	B22		NSD									
B	30	B2		NSD									
B	31	C12		NSD									
B	32	C32		NSD									
B	33	B31		NSD									

Lab/Cor, Inc.

A Professional Service Corporation in the Northwest

Report # 041172R3

Client: Ecology and Environment, Inc.

Project Name: Site# 0440.01CP, 0440.01CP-0001- FINAL RESULTS

TEM ASBESTOS STRUCTURE COUNT - RAW DATA

Sample No.: CC2-L6-2CC-100304 *Lab/Cor Sample No.:* B4760 S15 A1

Descripiton:

Gr	No.	Loc.	ID	Prim	Tot	Class	Len	Wid	Asp	Neg#	EDS#	Comment	Count Categories
B	34	B11		NSD									
C	35	B44		NSD									
C	36	B24		NSD									
C	37	B4		NSD									
C	38	C14		NSD									
C	39	C34		NSD									
C	40	B33		NSD									
C	41	B13		NSD									
C	42	C3		NSD									
C	43	C23		NSD									
C	44	C43		NSD									
C	45	B42		NSD									
C	46	B22		NSD									
C	47	B2		NSD									
C	48	C12		NSD									
C	49	C32		NSD									
C	50	B31		NSD									
C	51	B11		NSD									

Lab/Cor, Inc.

A Professional Service Corporation in the Northwest

Report # 041172R3

Client: Ecology and Environment, Inc.

Project Name: Site# 0440.01CP, 0440.01CP-0001- FINAL RESULTS

TEM ASBESTOS STRUCTURE COUNT - RAW DATA

Sample No.: CC2-L6-3CC-100304 *Lab/Cor Sample No.:* B4760 S16 A1

Descripiton:

Gr	No.	Loc.	ID	Prim	Tot	Class	Len	Wid	Asp	Neg#	EDS#	Comment	Count Categories
A	1	B44	ADQ	1	1	F	8.5	1.5	5.7			Mg, Si, Ca, Fe Actinolite	AS>5, AFB>5, PCMEF-US, PCMES-US, TAS_AHRA, AS>5_AHRA, AS5-10_AHRA
A	2	B24		NSD									
A	3	B4		NSD									
A	4	C14		NSD									
A	5	C34		NSD									
A	6	B33		NSD									
A	7	B13		NSD									
A	8	B23		NSD									
A	9	C23		NSD									
A	10	C43		NSD									
A	11	B42		NSD									
A	12	B22		NSD									
A	13	B2		NSD									
A	14	C12		NSD									
A	15	C32		NSD									
A	16	B41	ADQ	2	2	F1-0	4.5	1	4.5			Mg, Si, Ca, Fe Actinolite	TAS_AHRA
A	17	B21		NSD									
A	18	B1		NSD									
B	19	B44		NSD									
B	20	B24		NSD									
B	21	B4		NSD									
B	22	C14		NSD									
B	22	C34		NSD									
B	23	B33	AZQ	3	3	F	3.8	0.4	9.5	5246	15163	Mg, Si, Ca, Fe Actinolite Zone Axis [5 3.0] - RF	TAS_AHRA
B	24	B13	ADQ	4		MD1-0	3.5	1.2	2.9			Actinolite	TAS_AHRA
B	24	B13	ADQ		4	MF	1.8	0.38	4.7			Actinolite	
B	25	C3	ADQ	5	5	F	6	1	6.0			Mg, Si, Ca, Fe Actinolite	AS>5, AFB>5, PCMEF-US, PCMES-US, TAS_AHRA, AS>5_AHRA, AS5-10_AHRA
B	26	C23		NSD									
B	27	C43		NSD									
B	28	B32		NSD									
B	29	C10	AQ	6		MD1-0	17	.8	2.1			Actinolite	AS>5, TAS_AHRA, AS>5_AHRA, AS>10_AHRA

Lab/Cor, Inc.

A Professional Service Corporation in the Northwest

Report # 041172R3

Client: Ecology and Environment, Inc.

Project Name: Site# 0440.01CP, 0440.01CP-0001- FINAL RESULTS

TEM ASBESTOS STRUCTURE COUNT - RAW DATA

Sample No.: CC2-L6-3CC-100304 *Lab/Cor Sample No.:* B4760 S16 A1

Descripiton:

Gr	No.	Loc.	ID	Prim	Tot	Class	Len	Wid	Asp	Neg#	EDS#	Comment	Count Categories
B	29	C10	AQ		6	MB	3.8	1.2	3.2			Actinolite	
B	30	C30		NSD									
B	31	A1		NSD									
B	32	D11		NSD									
B	33	D31		NSD									
B	34	D20		NSD									
B	35	D10		NSD									
C	36	A42	ADQ	7	7	F	3.6	0.4	9.0			Mg, Si, Ca, Fe Actinolite	TAS_AHRA
C	36	A42	ADQ	8	8	F	9	3	3.0			Mg, Si, Ca, Fe Actinolite	AS>5, AFB>5, PCMEF-US, PCMES-US, TAS_AHRA, AS>5_AHRA, AS5-10_AHRA
C	37	A22	AZQ	9	9	F	4	1	4.0	5278	15164	Mg, Si, Ca, Fe Amosite Zone Axis [1 2 0] - KM	TAS_AHRA
C	37	A22	ADQ	10		MD1-1	13	7	1.9			Actinolite	AS>5, TAS_AHRA, AS>5_AHRA, AS>10_AHRA
C	37	A22	ADQ		10	MF	9.5	2	4.8			Mg, Si, Ca, Fe Actinolite	AFB>5, PCMEF-US
C	38	A2		NSD									
C	39	D12		NSD									
C	40	D42		NSD									
C	41	A41		NSD									
C	42	A21		NSD									
C	43	A1		NSD									
C	44	D11		NSD									
C	45	D31		NSD									
C	46	B41		NSD									
C	47	B21		NSD									
C	48	B1	ADQ	11	11	F	10.5	1.2	8.8			Mg, Si, Ca, Fe Actinolite	AS>5, AFB>5, PCMEF-US, PCMES-US, TAS_AHRA, AS>5_AHRA, AS>10_AHRA
C	49	C11		NSD									
C	50	C31		NSD									
C	51	C10		NSD									
C	52	C30		NSD									

Lab/Cor, Inc.

A Professional Service Corporation in the Northwest

Report # 041172R3

Client: Ecology and Environment, Inc.

Project Name: Site# 0440.01CP, 0440.01CP-0001- FINAL RESULTS

TEM ASBESTOS STRUCTURE COUNT - RAW DATA

Sample No.: CC2-L6-4CC-100304 *Lab/Cor Sample No.:* B4760 S17 A1

Descripiton:

Gr	No.	Loc.	ID	Prim	Tot	Class	Len	Wid	Asp	Neg#	EDS#	Comment	Count Categories
B	29	B22	ADQ	NSD		F.	4.2	0.6	7.0			Actinolite	TAS_AHRA
A	1	B34	CM	1	1	F	0.9	0.08	11			Chrysotile	TAS_AHRA
A	2	B14		NSD									
A	3	C4	ADQ	2	2	F	1.8	0.6	3.0		15165	Mg, Si, Ca, Fe Actinolite	TAS_AHRA
A	4	C24		NSD									
A	5	C44		NSD									
A	6	B43		NSD									
A	7	B23	ADQ	3	3	F	2.5	0.5	5.0			Actinolite	TAS_AHRA
A	8	B3		NSD									
A	9	C13		NSD									
A	10	C33		NSD									
A	11	B41		NSD									
A	12	B11		NSD									
A	13	C1		NSD									
A	14	C31		NSD									
A	15	A40		NSD									
A	16	A10		NSD									
A	17	D10		NSD									
B	18	B44	AZQ	4	4	F	7	2	3.5	5279	15197	Mg, Al, Si, Ca, Fe Actinolite Zone Axis [2 1 3] - KM	AS>5, AFB>5, PCMEF-US, PCMES-US, TAS_AHRA, AS>5_AHRA, AS5-10_AHRA
B	19	B24	ADQ	5		MD1-0	3.2	1.2	2.7			Actinolite	TAS_AHRA
B	19	B24	ADQ		5	MF	1.5	0.5	3.0			Actinolite	
B	19	B24		NSD									
B	20	B4		NSD									
B	21	C14		NSD									
B	22	C34		NSD									
B	23	B33	CDQ	6	6	B	6.5	1.5	4.3	5250	15166	Mg, Si Chrysotile Confirmed - KM	AS>5, PCMEF-US, PCMES-US, TAS_AHRA, AS>5_AHRA, AS5-10_AHRA
B	23	B33	ADQ	7		MD1-1	25	8	3.1			Amosite	AS>5, TAS_AHRA, AS>5_AHRA, AS>10_AHRA
B	23	B33	ADQ		7	MF	9	0.5	18			Mg, Si, Ca, Fe Amosite	AFB>5, PCMEF-US, PSAS 5-10, PSAS TOT, PSAM 5-10, PSAM TOT
B	24	B13	ADQ	8	8	F	5	1.5	3.3			Actinolite	TAS_AHRA
B	24	B13	CMQ	9	9	F	1.5	0.1	15			Chrysotile	TAS_AHRA

Lab/Cor, Inc.

A Professional Service Corporation in the Northwest

Report # 041172R3

Client: Ecology and Environment, Inc.

Project Name: Site# 0440.01CP, 0440.01CP-0001- FINAL RESULTS

TEM ASBESTOS STRUCTURE COUNT - RAW DATA

Sample No.: CC2-L6-4CC-100304 *Lab/Cor Sample No.:* B4760 S17 A1

Descripiton:

Gr	No.	Loc.	ID	Prim	Tot	Class	Len	Wid	Asp	Neg#	EDS#	Comment	Count Categories
B	25	C3		NSD									
B	26	C23		NSD									
B	27	C43		NSD									
B	28	B42		NSD									
B	29	B2		NSD									
B	30	C12		NSD									
B	31	C32		NSD									
B	32	B41		NSD									
B	33	B21		NSD									
C	34	B44		NSD									
C	35	B24		NSD									
C	36	B4	ADQ	10	10	F	1.8	0.6	3.0			Mg, Si, Ca, Fe Actinolite	TAS_AHRA
C	37	C4		NSD									
C	38	B43	ADQ	11	11	F	5.1	0.7	7.3			Mg, Si, Ca, Fe Actinolite	AS>5, AFB>5, PCMEF-US, PCMES-US, TAS_AHRA, AS>5_AHRA, AS5-10_AHRA
C	39	B23		NSD									
C	40	B3	CMQ	12	12	F	0.7	0.1	7.0			Chrysotile	TAS_AHRA
C	40	B3	CDQ	13	13	F	1.2	0.1	12			Chrysotile	TAS_AHRA
C	41	C23		NSD									
C	42	B42		NSD									
C	43	B32		NSD									
C	44	B12		NSD									
C	45	C2		NSD									
C	46	B31		NSD									
C	47	B11	ADQ	14	14	F	3.5	0.4	8.8			Actinolite	TAS_AHRA
C	48	C1		NSD									
C	49	C11		NSD									