Geomatrix

APPENDIX A

Site Photographs - Characterization

6/5/06 Characterization sampling in Maintenance Area, looking east.

6/7/06 Characterization sampling in Pilot Area, looking north.

6/5/06 Closeup of Maintenance Area sample MAINT-1-16. Note green discoloration of soil.

6/7/06 Pre-labeled characterization sample jars.

6/7/06 Closeup of Pilot Area boring PILOT-X-29.

6/8/06 Closeup of Compressor Area sample COMP-2-21.

6/8/06 Closeup of Compressor Area sample COMP-1-21. Note green soil horizon.

6/9/06 Characterization sampling in Laboratory Area.

6/9/06 Characterization sampling in Laboratory Area, looking east.

6/9/06 Characterization sampling in Compressor Area, looking east. Note concrete compressor pad.

6/9/06 Characterization sampling in Sulfuric Acid Area, looking northeast. Note concrete compressor pad in right foreground.

6/13/06 Characterization sampling in Background Area.

6/13/06 Compressor Area (left foreground);
Maintenance Area (left background), looking south.