Table 2
Concentrations of Asbestos in Soil and Rock Samples
Burlington Hill Site
Burlington, Washington

Sample Number	Description	Asbestos Concentration (%)	Asbestos Type
12090102	Location 1 - West	0.5	Actinolite
12090104	Location 1 - Middle	0.75	Actinolite
12090105	Location 1 - East	0.5	Actinolite
12090107	Location 2 - Along Driveway	ND	--
12090109	Location 2 - West of Garage	ND	--
12090111	Location 3 - North End of Quarry	ND	--
12090112	Location 3 - South End of Quarry	ND	--
12090114	Location 4 - North	ND	--
12090115	Location 4 - South	ND	--