CERCLIS SITE FILE REVIEW

REGION X SUPERFUND REMOVAL AND EMERGENCY SECTION

Facility Name: Aluminum Recycling Corp

City/State: Trentwood, WA EPA Number: ~~##~~ WAD980722979

Nature of Problem: The facility is a secondary aluminum smelter. The Smelting Process produces about 1800 Tons/yr of black dross waste consisting of sodium + Potassium chlorides and aluminum oxides. The dross is stored in large piles on site. It produces ammonia, acetylene & methane gases when wet

Comments: There is no evidence of hazardous waste deposited at this site. Possible substances of concern are chlorides migrated into groundwater and ammonia vapors from the dross piles.

Potential for Site Assessment/Removal:

____ Yes Priority: ____ High ____ Medium ____ Low

✓ No ma

____ Insufficient Information

TAT Reviewer: Gene Florentino Date: 4/1/87

EPA SRES Reviewer: Carl Kitz Date: 4/27/87

Concur with TAT? ____ Yes

✓ No

Comments: THIS SITE HAS SPILLED PROCESS WASTE WHICH HAS CAUSED LARGE FISH KILL. TYPE AND QUANTITY OF WASTE WARRANT FURTHER TAT ASSESSMENT

USEPA SF
1589412