A2

412-03-0026
Box 58 of 58
Vol XXXIII

EPA

POTENTIAL HAZARDOUS WASTE SITE PRELIMINARY ASSESSMENT
PART 1 - SITE INFORMATION AND ASSESSMENT

I. IDENTIFICATION
01 STATE: MO
02 SITE NUMBER: P2

II. SITE NAME AND LOCATION

01 SITE NAME (Legal, common, or descriptive name of site): Walsh & Associates
02 STREET, ROUTE NO., OR SPECIFIC LOCATION IDENTIFIER: 1901 Hanley
03 CITY: Brentwood
04 STATE: MO
05 ZIP CODE: 63144
06 COUNTY: St. Louis
07 COUNTY CODE:
08 CONG DIST:
09 COORDINATES LATITUDE: ___ ___ ___.___ LONGITUDE: ___ ___ ___.___
10 DIRECTIONS TO SITE (Starting from nearest public road): US 40 east from I-270. Exit at Hanley Rd. Go south on Hanley Rd. The building is on the right side of the road and is labelled "Brentwood"

III. RESPONSIBLE PARTIES

01 OWNER (If known): Robert Walsh
02 STREET (Business, mailing, residential): unknown
03 CITY: St. Louis
04 STATE: MO
05 ZIP CODE:
06 TELEPHONE NUMBER: (314) 781-2570
07 OPERATOR (If known and different from owner):
08 STREET (Business, mailing, residential):
09 CITY:
10 STATE:
11 ZIP CODE:
12 TELEPHONE NUMBER: ( )

SUPERFUND
MAY 31 1984
SITE LOG

13 TYPE OF OWNERSHIP (Check one)
☒ A. PRIVATE ☐ B. FEDERAL: _____ (Agency name) ☐ C. STATE ☐ D. COUNTY ☐ E. MUNICIPAL
☐ F. OTHER: _____ (Specify) ☐ G. UNKNOWN

14 OWNER/OPERATOR NOTIFICATION ON FILE (Check all that apply)
☐ A. RCRA 3001 DATE RECEIVED: __/__/__ (MONTH DAY YEAR) ☐ B. UNCONTROLLED WASTE SITE (CERCLA 103 c) DATE RECEIVED: __/__/__ (MONTH DAY YEAR) ☒ C. NONE

IV. CHARACTERIZATION OF POTENTIAL HAZARD

01 ON SITE INSPECTION
☒ YES DATE 3/24/84 (MONTH DAY YEAR)
☐ NO
BY (Check all that apply)
☒ A. EPA ☒ B. EPA CONTRACTOR ☐ C. STATE ☐ D. OTHER CONTRACTOR
☐ E. LOCAL HEALTH OFFICIAL ☐ F. OTHER: _____ (Specify)
CONTRACTOR NAME(S): Weston/TAT

02 SITE STATUS (Check one)
☒ A. ACTIVE ☐ B. INACTIVE ☐ C. UNKNOWN
03 YEARS OF OPERATION
c. 1968 (BEGINNING YEAR) | present (ENDING YEAR) ☐ UNKNOWN

04 DESCRIPTION OF SUBSTANCES POSSIBLY PRESENT, KNOWN, OR ALLEGED
2,3,7,8-TCDD was allegedly sprayed on site driveway in early 1970's.

05 DESCRIPTION OF POTENTIAL HAZARD TO ENVIRONMENT AND/OR POPULATION
TCDD is ~~and~~ extremely toxic - causes liver dysfunction, Chloracne. Complete effects to humans unknown.

V. PRIORITY ASSESSMENT

01 PRIORITY FOR INSPECTION (Check one. If high or medium is checked, complete Part 2 - Waste Information and Part 3 - Description of Hazardous Conditions and Incidents)
☐ A. HIGH (Inspection required promptly) ☐ B. MEDIUM (Inspection required) ☐ C. LOW (Inspect on time available basis) ☐ D. NONE (No further action needed, complete current disposition form)

VI. INFORMATION AVAILABLE FROM

01 CONTACT: Ron McCutcheon
02 OF (Agency/Organization): EPA/EP&R
03 TELEPHONE NUMBER: (913) 236-3888
04 PERSON RESPONSIBLE FOR ASSESSMENT: Wood Ramsey
05 AGENCY: Weston
06 ORGANIZATION: TAT
07 TELEPHONE NUMBER: (913) 236-3888
08 DATE: 5/15/84 (MONTH DAY YEAR)

EPA FORM 2070-12 (7-81)

224191

S00180609
SUPERFUND RECORDS

A1

EPA

POTENTIAL HAZARDOUS WASTE SITE
SITE INSPECTION REPORT
PART 1 - SITE LOCATION AND INSPECTION INFORMATION

I. IDENTIFICATION

01 STATE	02 SITE NUMBER
MO	P-2

II. SITE NAME AND LOCATION

01 SITE NAME (Legal, common, or descriptive name of site)	02 STREET, ROUTE NO., OR SPECIFIC LOCATION IDENTIFIER
Walsh & Associates	1801 Hanley

03 CITY	04 STATE	05 ZIP CODE	06 COUNTY	07 COUNTY CODE	08 CONG DIST
Brentwood	MO	63144	St. Louis		

09 COORDINATES LATITUDE	LONGITUDE	10 TYPE OF OWNERSHIP (Check one)
___ ___ ___.___	___ ___ ___.___	☒ A. PRIVATE ☐ B. FEDERAL ☐ C. STATE ☐ D. COUNTY ☐ E. MUNICIPAL ☐ F. OTHER ☐ G. UNKNOWN

III. INSPECTION INFORMATION

01 DATE OF INSPECTION	02 SITE STATUS	03 YEARS OF OPERATION
3 24 84 (MONTH DAY YEAR)	☒ ACTIVE ☐ INACTIVE	c. 1968 (BEGINNING YEAR) — (ENDING YEAR) ___ UNKNOWN

04 AGENCY PERFORMING INSPECTION (Check all that apply)

☒ A. EPA ☒ B. EPA CONTRACTOR ___ (Name of firm) ☐ C. MUNICIPAL ☐ D. MUNICIPAL CONTRACTOR ___ (Name of firm)
☐ E. STATE ☐ F. STATE CONTRACTOR ___ (Name of firm) ☐ G. OTHER ___ (Specify)

05 CHIEF INSPECTOR	06 TITLE	07 ORGANIZATION	08 TELEPHONE NO
Dan Harris	EPA - OSC	EPA/EP&R	(913) 236-3888

09 OTHER INSPECTORS	10 TITLE	11 ORGANIZATION	12 TELEPHONE NO
Wood Ramsey	Reg. VII TAT	Weston	(913) 621-6240
Susie Love	"	"	( ) "
Mike Clemons	"	"	( ) "
Dave Svingen	Reg. XVII TAT	"	816 (~~413~~) 221-1722
Mark Reising	MDNR	State of Missouri	( )

13 SITE REPRESENTATIVES INTERVIEWED	14 TITLE	15 ADDRESS	16 TELEPHONE NO
Mark Walsh	employee	unknown	(314) 991-1125
			( )
			( )
			( )
			( )
			( )
			( )

S00180610
SUPERFUND RECORDS

SUPERFUND
MAY 31 1984
SITE LOG

17 ACCESS GAINED BY (Check one)	18 TIME OF INSPECTION	19 WEATHER CONDITIONS
☒ PERMISSION ☐ WARRANT	0700 - 0930	Partly cloudy, cool.

IV. INFORMATION AVAILABLE FROM

01 CONTACT	02 OF (Agency/Organization)	03 TELEPHONE NO.
Ron McCutcheon	USEPA - Reg. VII EP&R	(913) 236-3888

04 PERSON RESPONSIBLE FOR SITE INSPECTION FORM	05 AGENCY	06 ORGANIZATION	07 TELEPHONE NO.	08 DATE
Wood H. Ramsey	Weston	TAT	913/621-6240	5 15 84 (MONTH DAY YEAR)

EPA FORM 2070-13 (7-81)

224192