LaPlace Chloroprene Air Sampling

Date: 3/20-21/17			Set Up			Collection			
Location	Canister ID	Flow Controller ID	Date	Time (HRS)	Pres. ("Hg)	Date	Time (HRS)	Pres. ("Hg)	Comments
E. St. John HS	A21035	PR-18	3/20/17	1330	-30	3/21/17	1331	-8.5	
Ochsners	A21108	PR-4	3/20/17	1334	-30	3/21/17	1335	-8.5	
Acorn and Hwy 44	22324	PR-22	3/20/17	1344	-30	3/21/17	1345	-8.5	co-located w/in-line filter
Levee	5063	PR-23	3/20/17	1348	-30	3/21/17	1352	-9	w/in-line filter
5th Ward Elementary	5100	PR-12	3/20/17	1352	-30	3/21/17	1356	-9.5	w/in-line filter
238 Chad Baker	SAT072	PR-10	3/20/17	1356	-30	3/21/17	1400	-7	
Acorn & Hwy 44	5062	PR-1	3/20/17	1344	-30	3/21/17	1345	(4) -18.75	w/in-line filter co-located
		LAST	LINE		3/21/17				

Notes: 1) SAMPLER = Erik Hadwin =

2) All canisters / flow controllers passed leak check prior to deployment.

3) Weather = current (3/20) - winds SW @ 9mph; predicted - winds WSW 10-15mph during day of 3/20, then winds SW @ 5-10mph during evening of 3/20, and then winds WSW @ 10-15mph during day of 3/21. Based on current / predicted winds, sampler selected Acorn & Hwy 44 as co-located sample location.

(4) Sample submitted as ~~total~~ invalid due to low sample volume believed to be associated w/ faulty flow controller.