40 CFR Part 60 - Standards of Performance for Crude Oil and Natural Gas Facilities for which Construction, Modification or Reconstruction Commenced After September 18, 2015 - 60.5420a(b) Annual Report

For the collection of fugitive emissions components at each well site and the collection of fugitive emissions components at each compressor station within the company-defined area, an owner or operator must include the records of each monitoring survey including the information specified in paragraphs (b)(7)(i) through (xii) of this section in all annual reports:

The asterisk (*) next to each field indicates that the corresponding field is required.

Facility Record No. * (Select from dropdown list - may need to scroll up)	Identification of Each Affected Facility * (§60.5420a(b)(1))	Date of Survey * (§60.5420a(b)(7)(i))	Survey Begin Time * (§60.5420a(b)(7)(ii))	Survey End Time * (§60.5420a(b)(7)(iii))	Name of Surveyor * (§60.5420a(b)(7)(iii))	Ambient Temperature During Survey * (§60.5420a(b)(7)(iv))	Sky Conditions During Survey * (§60.5420a(b)(7)(iv))	Maximum Wind Speed During Survey * (§60.5420a(b)(7)(iv))	Monitoring Instrument Used * (§60.5420a(b)(7)(v))	Deviations From Monitoring Plan (If none, state none.) * (§60.5420a(b)(7)(vi))	Type of Component for which Fugitive Emissions Detected * (§60.5420a(b)(7)(vii))	Number of Each Component Type for which Fugitive Emissions Detected * (§60.5420a(b)(7)(vii))	Type of Component Not Repaired as Required in §60.5397a(h) * (§60.5420a(b)(7)(viii))	Number of Each Component Type Not Repaired as Required in § 60.5397a(h) * (§60.5420a(b)(7)(viii))	Type of Difficult-to-Monitor Components Monitored * (§60.5420a(b)(7)(ix))	Number of Each Difficult-to-Monitor Component Type Monitored * (§60.5420a(b)(7)(ix))	Type of Unsafe-to-Monitor Component Monitored * (§60.5420a(b)(7)(ix))	Number of Each Unsafe-to-Monitor Component Type Monitored * (§60.5420a(b)(7)(ix))	Date of Successful Repair of Fugitive Emissions Component * (§60.5420a(b)(7)(x))	Type of Component Placed on Delay of Repair * (§60.5420a(b)(7)(xi))	Number of Each Component Type Placed on Delay of Repair * (§60.5420a(b)(7)(xi))	Explanation for Delay of Repair * (§60.5420a(b)(7)(xii))	Type of Instrument Used to Resurvey Repaired Components Not Repaired During Original Survey * (§60.5420a(b)(7)(xii))
	e.g.: Well Site ABC	e.g.: 8/13/17	e.g.: 10:00 am	e.g.: 1:00 pm	e.g.: John Smith	e.g.: 90°F	e.g.: Sunny, no clouds	e.g.: 2 mph	e.g.: Company ABC optical gas imaging camera	e.g.: None	e.g.: Valve	e.g.: 3	e.g.: Valve	e.g.: 1	e.g.: Valve	e.g.: 1	e.g.:Valve	e.g.: 1	e.g.: 11/10/14	e.g.: Valve	e.g.: 1	e.g.: Unsafe to repair until next shutdown	e.g.: Company ABC optical gas imaging camera
	Utchak 2	8/27/2019	11:45am	1:15pm	Tom Mullen	65	partly cloudy		SENSIT HXG-3	none	produce fluid tank hatch	1	0	0	0	0	0	0		0	0	NA	n/a
	Grea Location	9/9/2019	10:40am	11:35am	Tom Mullen	62	partly cloudy		SENSIT HXG-3	none	pump	1	0	0	0	0	0	0					