Fugitive Emissions Components

Identification of Each Affected Facility * (§60.5420a(b)(1))	Date of Survey * (§60.5420a(b)(7)(i))	Type of Unsafe-to-Monitor Component Monitored * (§60.5420a(b)(7)(ix))	Number of Each Unsafe-to-Monitor Component Type Monitored * (§60.5420a(b)(7)(ix))	Date of Successful Repair of Fugitive Emissions Component * (§60.5420a(b)(7)(x))	Type of Component Placed on Delay of Repair * (§60.5420a(b)(7)(xi))	Number of Each Component Type Placed on Delay of Repair * (§60.5420a(b)(7)(xi))	Explanation for Delay of Repair * (§60.5420a(b)(7)(xi))
e.g.: Well Site ABC	e.g.: 8/13/17	e.g.:Valve	e.g.: 1	e.g.: 11/10/16	e.g.: Valve	e.g.: 1	e.g.: Unsafe to repair until next shutdown
N-7 Compressor Station	11/10/2017	None	None	None	None	None	Not applicable
N-7 Compressor Station	1/31/2018	None	None	1/31/2018	None	None	Not applicable
N-7 Compressor Station	4/19/2018	None	None	None	None	None	Not applicable