Fugitive Emissions Components

			OGI	Compressor Station Affected Facility Only	
Identification of Each Affected Facility * (§60.5420a(b)(1))	Date of Survey * (§60.5420a(b)(7)(i))	Type of Instrument Used to Resurvey Repaired Components Not Repaired During Original Survey * (§60.5420a(b)(7)(xii))	Training and Experience of Surveyor * (§60.5420a(b)(7)(iii))	Was a monitoring survey waived under § 60.5397a(g)(5)? * (§60.5420a(b)(7))	If a monitoring survey was waived, the calendar months that make up the quarterly monitoring period for which the monitoring survey was waived. * (§60.5420a(b)(7))
e.g.: Well Site ABC	e.g.: 8/13/17	e.g.: Company ABC optical gas imaging camera	e.g.: Trained thermographer; completed 40-hour course at XYZ Training Center. Has 10 years of experience with OGI surveys.	e.g.: Yes	e.g.: January; February; and March
N-7 Compressor Station	11/10/2017	Not applicable	Trained thermographer, completed ~ 32 hour course with the Infrared Training Center. Has 2 years experience with OGI surveys.	Not applicable	Not applicable
N-7 Compressor Station	1/31/2018	Not applicable	Trained thermographer, completed ~ 32 hour course with the Infrared Training Center. Has 8 years experience with OGI surveys.	Not applicable	Not applicable
N-7 Compressor Station	4/19/2018	Not applicable	Trained thermographer, completed ~ 32 hour course with the Infrared Training Center. Has 8 years experience with OGI surveys.	Not applicable	Not applicable