40 CFR Part 60 - Standards of Performance for Crude Oil and Natural Gas Facilities for which Construction, Modification or Reconstruction Commenced After September 18, 2015 - 60.5420a(b) Annual Report

For the collection of fugitive emissions components at each well site and the collection of fugitive emissions components at each compressor station within the company defined area, an owner or operator must include the records of each monitoring survey including the information specified in paragraphs (b)(7)(i) through (xii) of this section in all annual reports:

The asterisk (*) next to each field indicates that the corresponding field is required.

Identification of Each Affected Facility * (§60.5420a(b)(1))	Date of Survey * (§60.5420a(b)(7)(i))	Survey Begin Time * (§60.5420a(b)(7)(ii))	Survey End Time * (§60.5420a(b)(7)(ii))	Name of Surveyor * (§60.5420a(b)(7)(iii))	Ambient Temperature During Survey * (§60.5420a(b)(7)(iv))	Sky Conditions During Survey * (§60.5420a(b)(7)(v))	Maximum Wind Speed During Survey * (§60.5420a(b)(7)(vi))	Monitoring Instrument Used * (§60.5420a(b)(7)(vii))	Deviations From Monitoring Plan (If none, state none.) * (§60.5420a(b)(7)(viii))	Type of Component for which Fugitive Emissions Detected * (§60.5420a(b)(7)(viii))	Number of Each Component Type for which Fugitive Emissions Detected * (§60.5420a(b)(7)(viii))	Type of Component Not Repaired as Required in §60.5397a(h) * (§60.5420a(b)(7)(viii))	Number of Each Component Type Not Repaired as Required in § 60.5397a(h) * (§60.5420a(b)(7)(viii))	Type of Difficult to Monitor Components Monitored * (§60.5420a(b)(7)(ix))	Number of Each Difficult to Monitor Component Type Monitored * (§60.5420a(b)(7)(ix))	Type of Unsafe to Monitor Component Monitored * (§60.5420a(b)(7)(x))	Number of Each Unsafe to Monitor Component Type Monitored * (§60.5420a(b)(7)(x))	Date of Successful Repair of Fugitive Emissions Component * (§60.5420a(b)(7)(xi))	Type of Component Placed on Delay of Repair * (§60.5420a(b)(7)(xi))	Number of Each Component Type Placed on Delay of Repair * (§60.5420a(b)(7)(xi))	Explanation for Delay of Repair * (§60.5420a(b)(7)(xi))	Type of Instrument Used to Resurvey Repaired Components Not Repaired During Original Survey * (§60.5420a(b)(7)(xii))	Training and Experience of Sur (§60.5420a(b)(7)(xii)
RU 22 TNT 1 LIMITED PARTNERSHIP EAST PAD	7/16/2018	11:10:00 AM	12:24:00 PM	Wyatt Tompkins	85	Sunny	5	FLIR GFX 320	None	Connectors/Union	1	N/A	N/A	N/A	N/A	N/A	N/A	7/16/2018	N/A	0	N/A	FLIR GFX 320	FLIR OGI Certified <1yr and 7yrs LDA
RU 22 TNT 1 LIMITED PARTNERSHIP EAST PAD	7/16/2018	11:10:00 AM	12:24:00 PM	Wyatt Tompkins	85	Sunny	5	FLIR GFX 320	None	None	0	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	0	N/A	N/A