ch Unsafe-to-onent Type red * (b)(7)(ix))	Date of Successful Repair of Fugitive Emissions Component * (§60.5420a(b)(7)(x))	Type of Component Placed on Delay of Repair * (§60.5420a(b)(7)(xi))	Number of Each Component Type Placed on Delay of Repair * (§60.5420a(b)(7)(xi))	Explanation for Delay of Repair * (§60.5420a(b)(7)(xi))	Type of Instrument Used to Resurvey Repaired Components Not Repaired During Original Survey * (§60.5420a(b)(7)(xii))	OGI Training and Experience of Surveyor * (§60.5420a(b)(7)(iii))
e.g.: 11/10/16		e.g.: Valve	e.g.: 1	e.g.: Unsafe to repair until next shutdown	e.g.: Company ABC optical gas imaging camera	e.g.: Trained thermographer; completed 40-hour course at XYZ Training Center. Has 10 years of experience with OGI surveys.
	4/25/2018	NA	NA	NA	NA	Infrared Training Center Certified. Over 100 site inspections
	9/20/2018	NA	NA	NA	NA	Infrared Training Center Certified. Over 500 site inspections
	2/6/2018	NA	NA	NA	NA	Infrared Training Center Certified. Over 500 site inspections
	3/2/2018	NA	NA	NA	NA	Infrared Training Center Certified. Over 500 site inspections
NA		NA	NA	NA	NA	Infrared Training Center Certified. Over 100 site inspections
NA		NA	NA	NA	NA	Infrared Training Center Certified. Over 100 site inspections
	2/6/2018	NA	NA	NA	NA	Infrared Training Center Certified. Over 500 site inspections
NA		NA	NA	NA	NA	Infrared Training Center Certified. Over 500 site inspections
NA		NA	NA	NA	NA	Infrared Training Center Certified. Over 100 site inspections
	2/6/2018	NA	NA	NA	NA	Infrared Training Center Certified. Over 500 site inspections
NA		NA	NA	NA	NA	Infrared Training Center Certified. Over 500 site inspections
	12/13/2017	NA	NA	NA	NA	Infrared Training Center Certified. Over 100 site inspections
NA		NA	NA	NA	NA	Infrared Training Center Certified. Over 500 site inspections
NA		NA	NA	NA	NA	Infrared Training Center Certified. Over 500 site inspections